


## Problem Statement


The Montana Department of Transportation (MDT) installed high-friction surface treatments (HFSTs) on four bridge decks in 2014 and 2015 in order to improve their skid resistance. Initial skid numbers were approximately 80 after HFST installation but after only 3 or 4 years, two of the HFSTs had average skid numbers between 50 and 55 while the other two HFSTs had average skid numbers of 36 and 17. A skid number of 30 to 35 is typically considered to be the minimum acceptable skid number for highway structures. The objective of this research was to assess the factors that influence the long-term performance of polymer-based HFST systems in Montana, specifically with respect to friction resistance and durability, and to provide guidance and recommendations to MDT regarding the use of HFSTs across Montana's varying geographic regions.

## Methodology

1. Literature Review and Survey
  - a. Compiled research literature, construction challenges, potential performance issues, and best practices
  - b. Survey of practices across 12 states and provinces
2. Field Investigation
  - a. Visual inspection and sounding surveys of 16 HFSTs
  - b. Detailed investigation of four HFSTs with cores sampled in 2020 and 2022
  - c. Skid testing data collected (ASTM E274) from 2014 to 2023
3. Laboratory Testing
  - a. Petrographic examination (ASTM C856)
  - b. Rapid chloride penetration (ASTM C1202) and rapid chloride migration (AASHTO T 357)
  - c. Bond strength (ASTM C1583)
  - d. Chemical composition (Fourier Transform Infrared spectroscopy)
  - e. Polymer degradation (Differential Scanning Calorimetry and Thermogravimetric Analysis)
  - f. Pavement macrotexture depth (modified ASTM E965)



Bridge ID	Route Carried	Year of HFST Installation	Type of Aggregate	ADT (vehicles per day)	ADTT (% of ADT)
1670	I-90 WB	2015	Armorstone	9522	19
1682	I-90 WB	2015	Armorstone	9522	19
1459	I-90 EB	2018	Nat. Calc. Bauxite	8044	22
1367	I-90 EB	2016	Nat. Calc. Bauxite	6415	29
14	Russell St NB	2020	Nat. Calc. Bauxite	15747	0
25	Russell St SB	2020	Nat. Calc. Bauxite		
1333	I-90 EB Ramp	2017	Nat. Calc. Bauxite	768	3
1336	I-90 WB	2017	Nat. Calc. Bauxite	6553	27
1338	I-90 WB	2021	Nat. Calc. Bauxite	6553	27
1374	I-90 EB	2017	Nat. Calc. Bauxite	6415	29
1392	I-90 EB	2018	Nat. Calc. Bauxite	9138	20
1428	I-90 EB	2018	Nat. Calc. Bauxite	16309	11
3734	Rock Creek Rd	2018	Nat. Calc. Bauxite	100	3
49.39 (mile marker)	I-90 EB	not recorded	Nat. Calc. Bauxite	6415	29



## Findings

- Overlays were well-bonded, generally intact, and performing well with the following conditions observed in the field:
  - Areas of surface polishing
  - Aggregate pop-out and small gouges (on the order of one or two inches in diameter)
  - Reflective cracking and spalling around pre-existing partial-depth repairs
  - Deck delaminations due to ongoing reinforcement corrosion
- Progression of deterioration observed in field:
  - Initial surface wear is rapid but slows with age and appeared to stabilize after ~ 2 years of age
  - Transverse cracks sometimes reflect in HFSTs and increased between inspections for some HFSTs. Some transverse deck cracks did not reflect through the HFSTs.
- Results of laboratory testing:
  - High bond strength (failure in deck substrate) at ages of 2 to 5 years
  - Good chloride penetrability resistance (0 Coulombs passed) at ages of 2 to 5 years
  - Installations of good quality, although some voiding and incomplete consolidation observed
- Skid resistance and HFST wear:
  - Driving lane of one HFST had skid number < 35 after 5 years of service, but skid numbers > 35 observed for all other lanes tested after 5 to 8 years of service
  - Loss of skid resistance appeared to govern service life of HFSTs in driving lanes
  - Wear characterized by fracture of aggregates at level of resin, loss of aggregates, and loss of aggregate agglomerations exposing voids in HFSTs
  - Difference in wear between driving lanes, passing lanes, and shoulders measurable by skid testing and pavement macrotexture depth
  - No definitive correlation between ADT or ADTT and skid resistance
  - No geographical restrictions for the use of HFSTs

## Recommendations

Based on the findings, the researchers concluded that the HFST systems studied are appropriate for use on Montana bridge decks, particularly for decks with no active corrosion or minimal repair needs due to ongoing corrosion, and that current practices are adequate for the system studied. Continued monitoring of performance to better characterize the actual service life of the HFSTs and how the performance of different HFST systems and aggregates compares was recommended. Each polymer system should be evaluated separately and new resin formulations that better address loss of skid resistance were identified as an area for future research.