# **EXISTING AND PROJECTED CONDITIONS**

Maclay Bridge Planning Study

FINAL





Prepared for: Montana Department of Transportation Helena, Montana





Prepared by: **Robert Peccia & Associates** Helena, Montana November 1, 2012



# **TABLE OF CONTENTS**

TABLE OF CONTENTS	I
ABBREVIATIONS / ACRONYMS	IV
1.0 INTRODUCTION	1
1.1. Previous Planning and Maintenance Efforts	1
1.2. Maclay Bridge Project Nomination	
1.3. Analysis Area	
1.4. History of Westside Bypass	
1.5. Committed and Planned Improvements	
2.0 DEMOGRAPHICS	5
2.1. Population Characteristics	
2.2. Employment and Income Characteristics	
3.0 LOCAL PLANNING	
3.1. Transportation Planning	
3.1.1. 2008 Missoula Long Range Transportation Plan	
3.1.2. 2012 Missoula Long Range Transportation Plan	
3.2. Non-Motorized Transportation Planning	
3.2.1. Missoula 2011 Active Transportation Plan (MATP)	
3.3. Transit Planning	
3.3.1. Missoula Transit Development Plan	
3.4. Parks and Recreation Planning 3.4.1. 2012 Missoula County Parks and Trails Master Plan	
3.4.1. 2012 Missoula County Parks and Trails Master Plan	
3.4.3. 2004 Master Parks and Recreation Plan for the Greater Missoula Area	
3.5. Land Use Planning	
3.5.1. Missoula County Growth Policy	
3.5.2. Missoula Urban Comprehensive Plan: 1998 Update	
3.5.3. Missoula Urban Fringe Development Area (UFDA) Project	
3.5.4. Target Range Neighborhood Plan	
3.6. Lolo National Forest Plan	13
4.0 ROADWAY, BRIDGE AND PHYSICAL CHARACTERISTICS	13
4.1. Existing Roadway Users	
4.2. Existing Traffic Data	
4.2. Existing Traffic Projections	
4.3.1. Historic Traffic Growth Rates	
4.3.2. Future Traffic Modeling	
4.4. Crash Analysis	
4.4.1. Identifiable Crash Trends and Areas of Concern	
4.5. Existing Travel Times	
4.6. Design Standards	
4.7. Roadway Geometrics	
4.7.1. Horizontal Alignment	
4.7.2. Vertical Alignment	
4.7.3. Roadside Clear Zone	25
4.8. Bridge Considerations	26

4.8.1. Sufficiency Rating	
4.8.2. Bridge Health Index	
4.8.3. Fracture Critical Status	
4.9. Parking Considerations	
4.10. Roadway Surfacing	
4.11. Access Points	
4.12. Right-of-Way	
4.13. Hydraulics	
4.13.1. Floodplain Considerations	
4.13.2. Preliminary Hydrology	
4.13.3. Channel Characteristics	
4.14. Transit Service	
4.15. Utilities	
4. 10. Otinites	
5.0 ENVIRONMENTAL SETTING	
5.1. Geographic Setting	
5.1.1. Land Ownership and Land Management	
5.1.2. Land Use	
5.2. Physical Resources	
5.2.1. Geologic Resources	
5.2.2. Soils and Prime Farmland	
5.2.2. Solis and Finne Farmand	
5.2.4. Wetlands	
5.2.5. Floodplains (EO 11988) and Floodways	
5.2.6. Hazardous Material	
5.2.7. Air Quality	
5.2.8. Noise	
5.3. Visual Resources	
5.4. Biological Resources	
5.4.1. Wildlife and Fish	
5.4.2. Threatened and Endangered Wildlife Species	
5.4.3. Montana Animal Species of Concern	
5.4.4. Vegetation	
5.5. Cultural and Archaeological Resources	
5.5.1. 4(f) Resources	
5.5.2. 6(f) Resources	
6.0 CONCLUSION	
6.1. Transportation System	46
6.2. Environmental Considerations Within Environmental Scan Boundary	
6.3. Other Considerations	
APPENDIX A: FIELD REVIEW PHOTO LOG	
APPENDIX B: MACLAY BRIDGE INSPECTION REPORT	
APPENDIX C: MISSOULA COUNTY PARKING RESOLUTIONS	

### APPENDIX D: HOURLY TRAFFIC VOLUMES - RIVER PINES ROAD

# **FIGURES**

Figure 1: Vicinity Map	4
Figure 2: Population by Age – Missoula County and State of Montana (2010)	6
Figure 3: Percent Change in AADT	17
Figure 4: Crash Locations (01/01/2002 – 12/31/2011)	21
Figure 5: Typical Rating Vehicles for Bridge Design	26
Figure 6: Crime Locations in General Vicinity	32

# TABLES

Table 1: Population Growth Trends and Density	5
Table 2: Employment Statistics (March 2012)	6
Table 3: Income Statistics (2006 – 2010)	7
Table 4: Commuting Statistics (2010)	7
Table 5: Average Annual Daily Traffic	13
Table 6: River Pines Road Hourly Traffic Volumes – Twelve Hour Period (10/03/2012)	14
Table 7: Historic Traffic Growth Rates and Projected AADT (Straight-line)	15
Table 8: 2040 AADT Traffic Modeling Projections	16
Table 9: Travel Time Evaluation	22
Table 10: Missoula County Roadway Design Considerations	24
Table 11: Horizontal Alignment Areas of Concern	
Table 12: Bridge Location and Type	26
Table 13: Bridge Design Loads and Ratings	27
Table 14: Bridge Sufficiency Rating for Maclay Bridge	29
Table 15: Missoula County Parking Resolutions	30
Table 16: Existing Road and Bridge Surfacing	33
Table 17: Access Points	
Table 18: Preliminary Hydrology for Bitterroot River	34
Table 19: USFWS Endangered, Threatened, Proposed, and Candidate Wildlife Species	41
Table 20: Montana Animal Species of Concern	42
Table 21: USFWS Endangered, Threatened, Proposed, and Candidate Plant Species	42
Table 22: Summary of Cultural Resources	44
Table 23: Summary of Potential Section 4(f) Resources	45

# **ABBREVIATIONS / ACRONYMS**

AASHTO	American Association of State Highway Transportation Officials
ADT	Average Daily Traffic
AADT	Average Annual Daily Traffic
AAGR	Average Annual Growth Rate
APE	Area of Potential Effect
CFR	Code of Federal Regulations
cfs	Cubic Feet per Second
CLOMR	Conditional Letter of Map Revision
CRABS	Cultural Resources Annotated Bibliography Search
CRIS	Cultural Resources Information System
DHV	Design Hourly Vehicle
DNRC	Department of Natural Resources and Conservation
DOI	Department of Interior
EA	Environmental Assessment
ESA	Endangered Species Act
FAS	Fishing Access Site
FEMA	Federal Emergency Management Agency
FHWA	Federal Highway Administration
FIRM	Flood Insurance Rate Maps
FIS	Flood Insurance Study
FONSI	Finding of No Significant Impact
FPPA	Farmland Protection Policy Act
GIS	Geographic Information System
LOMR	Letter of Map Revision
LRTP	Long Range Transportation Plan
LUST	Leaking Underground Storage Tank
LWCF	Land and Water Conservation Funds
MAAQS	Montana Ambient Air Quality Standards
MATP	Missoula Active Transportation Plan
MDEQ	Montana Department of Environmental Quality
MDT	Montana Department of Transportation
MEPA	Montana Environmental Policy Act
MFWP	Montana Department of Fish, Wildlife, and Parks

MNHP	Montana Natural Heritage Program
mph	Miles per Hour
MPO	Metropolitan Planning Organization
MSAT	Mobile Source Air Toxics
mton	Metric Ton
MUTD	Missoula Urban Transportation District
NAAQS	National Ambient Air Quality Standards
NEPA	National Environmental Policy Act
NPL	National Priority List
NPS	National Park Service
NRCS	Natural Resource Conservation Service
NRHP	National Register of Historic Places
NRIS	Natural Resource Information System
OPG	Office of Planning and Grants
PM	Particulate Matter
RDM	Road Design Manual
TDM	Travel Demand Model
TDP	Transit Development Plan
TIP	Transportation Improvement Program
TMDL	Total Maximum Daily Load
TPCC	Transportation Policy Coordinating Committee
USACOE	U.S. Army Corps of Engineers
UFDA	Urban Fringe Development Area
UPN	Uniform Project Number
UPWP	Unified Planning Work Program
URSA	Urban Service Area
USACOE	U.S. Army Corps of Engineers
USEPA	U.S. Environmental Protection Agency
USFS	U.S. Forest Service
USFWS	U.S. Fish and Wildlife Service
USGS	U.S. Geological Service
UST	Underground Storage Tank
vpd	Vehicles per Day
Section 4(f)	Section 4(f) of the 1966 Department of Transportation Act
Section 6(f)	Section 6(f) of the National Land and Water Conservation Funds Act

# **EXISTING AND PROJECTED CONDITIONS**

# **1.0 INTRODUCTION**

The North Avenue Bridge, known locally and referred to hereafter as the Maclay Bridge, is a single-lane structure located west of the City of Missoula. The Maclay Bridge crosses the Bitterroot River approximately 2.75 miles west of Reserve Street. North Avenue connects to the existing bridge as the eastern approach, and River Pines Road serves as its western approach.

The intent of the *Existing and Projected Conditions* report is to identify existing and projected conditions associated with the Maclay Bridge and surrounding area and to highlight relevant environmental factors with the potential to influence the development of improvement options. This report is a high-level planning analysis aimed at identifying constraints and opportunities related to the potential rehabilitation, reconstruction or replacement of the Maclay Bridge.

# **1.1. PREVIOUS PLANNING AND MAINTENANCE EFFORTS**

In 1994, an Environmental Assessment (EA) for the *Maclay Bridge Site Selection Study*<sup>1</sup> was completed defining the purpose and need for a project at the Maclay Bridge, identifying potential alternatives, and assessing impacts of the various alternatives identified to address the project's purpose and need. Sixteen (16) alternatives were initially considered in the EA including:

- Bridge rehabilitation or bridge replacement (one-lane structure) at the current location;
- Numerous alternatives that would provide a new two-lane bridge elsewhere; and
- A "No Build" alternative.

Through a screening process, four alternatives were advanced for further consideration and a "Preferred Alternative" was identified. The Preferred Alternative was described in the EA as follows:

"A new two-lane (one lane for each direction of traffic) bridge constructed over the Bitterroot River which connects River Pines Road on the west side to South Avenue West on the east side. The Preferred Alternative includes increasing the number of lanes on the bridge from one lane (existing) to two lanes (proposed). The bridge cross section includes adequate shoulders for bicycle travel and a separated pedestrian walkway."

A Finding of No Significant Impact (FONSI) on the 1994 EA was never issued by the Federal Highway Administration (FHWA) and the Preferred Alternative from the EA was not advanced due to lack of funding. Even though the 1994 EA was completed and approved for circulation, a decision document (i.e. FONSI) was not issued, rendering the NEPA process incomplete. FHWA views a signed FONSI as the NEPA decision document for a project evaluated and advanced with an EA. Missoula County had intended to use special project demonstration funds from Congress to implement the project but was unsuccessful in obtaining the funding. The Maclay Bridge replacement project was inactive until the County nominated it to receive funding from MDT's off-system bridge program in 2002.

Minor maintenance activities have been performed on the bridge at various times since the completion of the 1994 EA. These have included the following:

<sup>&</sup>lt;sup>1</sup> Maclay Bridge Site Selection Study Environmental Assessment, Carter & Burgess Inc., April 1994

- The west bridge abutment was armored with material in anticipation of high water conditions during Spring run-off (April, 1997);
- The existing timber deck was replaced with corrugated steel decking and an asphalt overlay. In addition, bearings were replaced and/or added, and steel curbing was placed to prevent vehicular damage to pedestrian rail and truss elements (2003);
- The expansion joints at the west abutment were modified, as the expansion joint installed with the 2003 deck replacement were found to be inadequate and in need of mitigation (2004); and
- The expansion joint between the main truss and the pony truss was modified, as the expansion joint installed with the 2003 deck replacement were found to be inadequate and in need of mitigation (2005).

Many of the underlying issues previously identified as deficiencies (and reasons for proposing transportation improvements) in the 1994 EA and subsequent safety inspections remain. This, coupled with the community's ongoing interest in the Maclay Bridge and possible changes in traffic patterns resulting from potential improvements, served as the reason for initiating the *Maclay Bridge Planning Study*.

# **1.2. MACLAY BRIDGE PROJECT NOMINATION**

Missoula County has nominated the Maclay Bridge for replacement under the Montana Department of Transportation Off-System Bridge Program (formerly known as the *Highway Bridge Replacement and Rehabilitation Program*). Funds for the program are derived from the Federal gas tax, which is outside Federal general revenue sources and doesn't impact or add to the Federal deficit. Funds are Federally apportioned to Montana under the provisions of the current highway bill, MAP-21. MAP-21 requires a minimum percentage of the funding be used for off-system bridges. In general, projects are funded with 86.58% Federal and the State is responsible for the remaining 13.42%. The State share is funded through the Highway State Special Revenue Account. Because the Maclay Bridge is an "off-system" facility, it falls under the category of the "Off-System Bridge Program".

MDT conducts a condition inspection of off-system bridges on a two-year cycle. The condition inspection provides information used to calculate the Sufficiency Rating (SR). The SR formula is the industry standard method of evaluating bridge data to obtain a numeric value indicating the sufficiency of the bridge to remain in service. The sufficiency rating is expressed by a value ranging from 0 to 100 with 100 being an entirely sufficient bridge and 0 being an entirely deficient bridge.

The condition inspection information is also used to classify the bridges as either "Not Deficient", Structurally Deficient" or "Functionally Obsolete" (further explained in Section 4.8.1).

Procedures for selecting bridges for inclusion into this program are based on a ranking system that weighs various elements of a structure condition, usage alternate routes, and considers local priorities. Safety and economic impacts are considerations in the selection process.

MDT periodically asks each county for Off-System bridge nominations. In 2006, the Maclay Bridge was Missoula County's number one priority.

# **1.3.** ANALYSIS AREA

Existing and projected conditions were analyzed in the greater area west of Reserve Street which is most likely to be affected by a potential upgrade, reconstruction or replacement of the Maclay Bridge. For the purposes of the *Environmental Scan*, an "Environmental Scan Boundary" was established to encompass

an expanded area around the Maclay Bridge to include the areas potentially affected by the alternative options considered in the 1994 EA.

A vicinity map showing the location of the Maclay Bridge, the Environmental Scan Boundary, and the surrounding area is shown as **Figure 1**.

# **1.4. HISTORY OF WESTSIDE BYPASS**

Several studies and resultant documents have been prepared over the last five decades relative to a potential bypass route west of Missoula. This route, commonly referred to as the Westside Bypass, has been the subject of much interest and debate. The studies and discussions concluded that the Westside Bypass is not feasible due to a variety of factors. In terms of this specific planning study, the Westside Bypass concept is not a consideration nor is it a factor in this study's development. Planning exercises and their brief highlights are listed below:

### **1965 MISSOULA AREA TRANSPORTATION PLAN**

This planning document included the first presentation of a Westside Bypass. The general route identified included a route proceeding south from the Wye area across the Harper's Bridge site, and then follow Big Flat and Blue Mountain Roads to US Highway 93 southwest of Missoula.

### 1980 RESERVE STREET PLAN

The Reserve Street Plan concluded that a Westside Bypass would not serve local traffic very well, and would add additional miles of travel and generate impacts on the rural character of Grass Valley and Big Flat. Accordingly, the Westside Bypass was dismissed as a feasible route, and efforts were placed on expansion of Reserve Street.

### 2007 FEASIBILITY WORKSHOP

A feasibility workshop was held in 2007 at the request of the community and came out of the MPO. A consultant was hired to examine a Westside Bypass and it was concluded not to be feasible due to the presence of 4(f) and 6(f) properties.

# **1.5. COMMITTED AND PLANNED IMPROVEMENTS**

There are currently three committed and planned improvements designated within the general vicinity of the Maclay Bridge. They are in varying stages of development, and are summarized as follows:

**River Pines Road HSIP 32(80)** - MDT has a planned safety improvement project at the intersection of River Pines Road and Riverside Drive on the western side of the Maclay Bridge. The project is intended to address an existing crash trend identified by MDT Safety Engineering and includes the installation of an overhead light at the intersection, a single arrow board, and the replacement of the "Dead End" and street name sign.

**Blue Mountain Road STPHS 32(47)** - MDT is developing this safety improvement project that involves the reconstruction and re-alignment, with a larger radius, of a curve on Blue Mountain Road located 0.3 miles south of the intersection of Blue Mountain Road, O'Brien Creek Road, and River Pines Road. The project will involve environmental documentation, right-of-way acquisition, utility relocation, and potential geotechnical considerations to mitigate the crash trends relative to the horizontal alignment.




Figure 1: Vicinity Map

**Clements Road and 3<sup>rd</sup> Street UPP 8199(99)** – MDT is developing this pavement preservation project to extend the service life of Clements Road. Clements Road will be milled and given an asphalt overlay, between South Avenue and Seventh Street. The remainder of Clements Road will be chip sealed. Replacement of the pavement markings and signing will also be included.

# **2.0 DEMOGRAPHICS**

This section provides an overview of social, economic, and land use characteristics for the area. Historic and recent trends in area demographics help define existing conditions and aid forecasting techniques as there is a direct correlation between motor vehicle travel and socio-economic indicators.

Demographic and socio-economic information was reviewed to help understand recent trends in population, age distribution, employment, economic status, and commuting for area residents. Note that socio-economic data sources often lag considerably behind the actual years of interest. This analysis presents the most recent data and statistics available and describes recent and potential changes in the area.

# **2.1. POPULATION CHARACTERISTICS**


Over the last decade, the population in Missoula County has increased by more than 14 percent and the City of Missoula's population has grown by 17 percent. This is in contrast to the 9.7 percent growth experienced over the same period in the State of Montana and the entire United States. According to the 2010 Census, Missoula County has a density of 42.1 persons per square mile. This is well above the population density for the State of Montana as a whole. **Table 1** presents population and growth statistics for Missoula County and the City of Missoula compared to the State of Montana and the United States.

Area	Population (2010)	Population (2000)	Percent Growth	Average Annual Growth	Persons per Square Mile (2010)
Missoula County	109,299	95,799	14.1%	1.3%	42.1
City of Missoula	66,788	57,053	17.1%	1.6%	2,427.6
State of Montana	989,415	902,195	9.7%	0.9%	6.8
United States	308,745,538	281,421,906	9.7%	0.9%	87.4

### **Table 1: Population Growth Trends and Density**

Source: US Bureau of the Census, <u>http://quickfacts.census.gov</u>

**Figure 2** shows the age distribution for residents of Missoula County and the State of Montana. The figure illustrates the population of Missoula County is notably younger than that of the State of Montana. Specifically, Missoula County has a higher percentage of population between 20 and 29 than the State of Montana. In Missoula County, 20.0 percent of the population is between 20 and 29 years old; for the State of Montana 13.3 percent of the population is in the 20 to 29 age group. This trend is likely influenced by to the presence of the University of Montana in Missoula.



### Figure 2: Population by Age – Missoula County and State of Montana (2010)

Source: US Census Bureau, 2010 Demographic Profile, <u>http://factfinder2.census.gov</u>

# **2.2. EMPLOYMENT AND INCOME CHARACTERISTICS**

Employment statistics from the Montana Department of Labor and Industry for Missoula County, the State of Montana, and the United States as of March 2012 are shown in **Table 2**. Missoula County has a slightly lower unemployment rate (6.9 percent) than the State of Montana (7.0 percent). Both Missoula County and the State of Montana have unemployment rates lower than that of the United States (8.4 percent).

#### Table 2: Employment Statistics (March 2012)

Location	Civilian Labor Force	Employed	Unemployed	Unemployment Rate
Missoula County	58,198	54,182	4,016	6.9%
State of Montana	503,012	467,981	35,031	7.0%
United States	154,316,000	141,412,000	12,904,000	8.4%

Source: MT Department of Labor and Industry, Employment Information, March 2012, <u>http://www.ourfactsyourfuture.org</u> Note: Data non-seasonally adjusted According to the 2006 – 2010 American Community Survey five-year estimates, median household income levels for Missoula County and City of Missoula residents were below those for the State of Montana and the United States. Per capita income levels for Missoula County were higher than the State of Montana and lower than the United States. Missoula County and the City of Missoula have a higher percentage of persons living below poverty than the State of Montana and United States. The income statistics data is summarized in **Table 3**.

Area	Median Household Income	Per Capita Income	Persons Below Poverty Level (%)
Missoula County	\$42,887	\$24,343	17.30%
City of Missoula	\$36,547	\$22,543	22.10%
State of Montana	\$43,872	\$23,836	14.50%
United States	\$51,914	\$27,334	13.80%

### Table 3: Income Statistics (2006 – 2010)

Source: US Bureau of the Census, American Community Survey 2006-2010, http://factfinder2.census.gov

**Table 4** presents 2010 commuting statistics from the American Community Survey. According to the data, Missoula County residents are more likely to walk or commute to work by other means than are residents of the State of Montana or nation. Mean travel time to work is lower for Missoula County residents than for residents of the State of Montana and United States as a whole.

#### Table 4: Commuting Statistics (2010)

Subject	Missoula County		City of Missoula		State of Montana		United States	
Workers 16 years and over	56,103 35,430		459,904		136,941,	010		
Car, truck, or van drove alone	41,152	73.4%	24,157	68.2%	347,835	75.6%	104,857,517	76.6%
Car, truck, or van carpooled	4,795	8.5%	3,284	9.3%	44,652	9.7%	13,266,356	9.7%
Public transportation (excluding taxicab)	1,168	2.1%	1,090	3.1%	3,856	0.8%	6,768,661	4.9%
Walked	3,181	5.7%	2,579	7.3%	23,813	5.2%	3,797,048	2.8%
Other means	2,423	4.3%	2,094	5.9%	9,636	2.1%	2,327,228	1.7%
Worked at home	3,384	6.0%	2,226	6.3%	30,112	6.5%	5,924,200	4.3%
Mean travel time to work (minutes)	18	.0	16	.3	18.	6	25.3	

Source: US Census Bureau, 2010 American Community Survey, http://factfinder2.census.gov

# **3.0 LOCAL PLANNING**

Missoula County and the City of Missoula have a cooperative agreement in place to conduct planning based on the shared environmental, economic, aesthetic, and social values of city and county residents. The agreement created a City-County Office of Planning and Grants (OPG) which is responsible for land use permitting, long range planning, transportation planning, historic preservation, housing, and a variety of other programs.

# **3.1. TRANSPORTATION PLANNING**

When Missoula's urbanized area population exceeded 50,000, a Metropolitan Planning Organization (MPO) was created and designated to oversee the regional transportation planning and federal transportation funding within the area. The Missoula Transportation Policy Coordinating Committee (TPCC) is the policy making body for the MPO. The Transportation Division of the OPG performs transportation planning functions for the MPO.

The MPO is responsible for transportation planning and programming through the following federally required activities:

- Unified Planning Work Program (UPWP);
- Transportation Improvement Program (TIP); and
- Long Range Transportation Plan (LRTP).

The UPWP is a document prepared each year by the MPO describing transportation planning activities to be conducted during the Federal fiscal year. The Missoula TIP, also updated annually, contains a five-year program of transportation projects and programs to be carried out within the Missoula MPO planning area. The TIP lists projects according to amount and source of funds to be spent for each project within the planning boundary. The Missoula Federal Fiscal Year 2011-2015 TIP includes a project named "Bitterroot River W of MSL" on the list of Bridge Replacement and Bridge Rehab projects within the MPO planning area; however, the project does not have an assigned estimated cost or program schedule.

The LRTP is a planning document intended to establish a vision of transportation investments and how future spending should be allocated over the long term within the planning area. Missoula's MPO updates the LRTP every four years, based on a 20+-year projection of transportation conditions and needs in the MPO planning area. The current version of the LRTP is discussed below.

# 3.1.1. 2008 Missoula Long Range Transportation Plan

The 2008 Missoula Long Range Transportation Plan, adopted in November 2008, contains a list of projects and programs representing all modes of surface transportation through 2035. The LRTP is "fiscally constrained" meaning the total estimated cost of the planned improvements cannot exceed anticipated levels of Federal, state and local funding for the planning period. The LRTP also contains "illustrative projects" that are unfunded but have been included by state or local partners for future consideration if and when funding becomes available.

The 2008 Missoula Long Range Transportation Plan reflects the results of an extensive community visioning process (known as "Envision Missoula") designed to link transportation and land use planning within the urban area. The process identified several future growth scenarios for an area population of 200,000 with different associated patterns of regional development and supporting transportation infrastructure to the year 2035. The preferred growth scenario—designated as the "Focus Inward Scenario"—reflects a community vision to manage travel demand by bringing together activities into one highly concentrated downtown area linked by a multi-modal corridor from Lolo to downtown Missoula. The scenario was based on the assumption that the number of households in the urban area will increase by 37% between 2007 and 2035 and that the majority of new trips in the Missoula area would occur in pockets of growth either downtown, or in other existing areas of Missoula.<sup>2</sup>

The 2008 LRTP analyzes the performance of the existing transportation system and identifies a package of improvements intended to meet Missoula's existing and projected transportation needs. Projects included in the plan are categorized into Committed (those with obligated funds), Recommended (funded) and Illustrative (unfunded potential future projects). The LRTP identifies the North Avenue Bridge Replacement (Maclay Bridge) as a "Recommended Roadway Capacity Project" (LRTP, page 4-13) to be funded by State/Federal Off-System Bridge Funds.

<sup>&</sup>lt;sup>2</sup> Missoula 2008 Long Range Transportation Plan, December 18, 2008, page 3-4 & Envision Missoula Planning Summit Report, September 2008, page 37.

# 3.1.2. 2012 Missoula Long Range Transportation Plan

An updated LRTP should be finalized by the end of 2012. LSA Associates—in partnership with Cambridge Systematics and Crandall Arambula—was retained by the MPO to help update the 2008 LRTP.

# **3.2. NON-MOTORIZED TRANSPORTATION PLANNING**

### 3.2.1. Missoula 2011 Active Transportation Plan (MATP)

The 2011 Missoula Active Transportation Plan (MATP) replaces the 2001 Non-Motorized Transportation Plan and was adopted by the Missoula City Council and the Missoula County Commissioners in June 2011. The MATP presents a long-term vision for the bicycle and pedestrian components of the community's multi-modal transportation system. The document recommends new policies and designs and provides a list of proposed projects from which the MPO can draw from for bicycle and pedestrian infrastructure in the MPO planning area.

The MATP acknowledges use of the Maclay Bridge crossing by pedestrians and bicyclists and notes existing multi-use trails along North Avenue, South Avenue, Humble Road (between North and South Avenues) Clements and Spurgin Roads, and South 7th Street West. The document identifies a desirable future trail corridor for pedestrians and bicyclists across the Bitterroot River along South Avenue.

# **3.3. TRANSIT PLANNING**

### 3.3.1. Missoula Transit Development Plan

The Missoula Urban Transportation District (MUTD), established in 1976, operates the Mountain Line bus system. A Transit Development Plan (TDP)—a strategic guide for public transportation in the MUTD—is prepared and annually updated by Mountain Line. The TDP describes existing facilities and transit projects needed over a five-year planning horizon and relevant projects and activities are incorporated into the Missoula TIP. Mountain Line also operates para-transit service, a Senior Van, and provides transportation for special events.

The Mountain Line operates twelve fixed routes within the Missoula area. Mountain Line's Route 9 includes portions of South Avenue, Clements Road, and South 7th Avenue in the Study Area. Public transit service to and from downtown Missoula is available from 7:00 am to 7:30 pm Monday through Friday and from 10:00 am to 6:00 pm on Saturdays. A designated bus stop exists at the Target Range School near the intersection of South Avenue and Clements Road.

The TDP for Fiscal Years 2010-2014 does not identify any specific projects in the Study Area. The document does note the potential for service improvements in the Lower Miller Creek and Lolo areas.

# **3.4. PARKS AND RECREATION PLANNING**

### 3.4.1. 2012 Missoula County Parks and Trails Master Plan

The *Missoula County Parks and Trails Master Plan* guides the administration and management of park and recreational lands in Missoula County. The County recently completed an update to the 1997 County Parks and Conservation Land Plan. The updated plan was adopted by the Missoula County Park Board in early 2012. The Master Plan includes a trails component and reflects broad community support for development of natural surface hiking and bicycle trails, paved commuter trails, river access sites, and preservation of natural areas and wildlife habitats.

### 3.4.2. Missoula Urban Area Open Space Plan 2006 Update

This plan was first adopted by the City and County of Missoula in 1995 and was updated in 2006. The plan envisions a trail system "to provide recreational opportunities and help further facilitate non-motorized transportation as a viable option for more people in and around the City." The priorities listed include extending and filling in gaps for existing trails and extending commuter/recreational trails in various portions of the Missoula Valley.

The document identifies the presence of important conservation and recreational lands in the Target Range area including the Bitterroot and Clark Fork Rivers, the Kelly Island Fishing Access Site, and the Blue Mountain Recreation Area.

# 3.4.3. 2004 Master Parks and Recreation Plan for the Greater Missoula Area

The *Master Parks and Recreation Plan for the Greater Missoula Area*, adopted in May 2004, was intended to provide a long-term vision for land use as it relates to parks, trails, open spaces, conservation lands, urban forest, and recreation facilities in the Missoula Urban Area. The area covered by the plan included the City of Missoula and an area approximately 3 miles beyond the City limits. The plan establishes the desired Level of Service for parkland acreage, sets forth standards for developed parks, and adopts numerous goals, policies, and action items to increase the quantity and quality of parks.

The plan acknowledged the public parklands, recreation sites, and conservation lands in the general area but did not make specific recommendations that would be relevant to the planning study. The plan also supported recommendations made in other planning documents of the time regarding non-motorized transportation in the urban area.

# 3.5. LAND USE PLANNING

Land use planning within the area is guided by several plans including the *Target Range Neighborhood Plan*, the *Missoula Urban Area Comprehensive Plan: 1998 Update*, and the *Missoula County Growth Policy, 2005 Update* (amended in March 2010). Areas outside the designated Target Range Neighborhood Plan boundary are governed by the Comprehensive Plan and the Growth Policy. These documents are discussed in the following sections.

# 3.5.1. Missoula County Growth Policy

A growth policy is an official public document adopted and used by Montana local governments as a general guide for decisions about the community's physical development. The document is not regulatory; it serves as an official statement of public policy to guide growth and manage change for the betterment of the community. It establishes the legal and philosophical foundation upon which future plans and regulations will be based. State law requires growth policies contain several notable elements including:

- Community goals and objectives;
- Information about existing conditions and trends;
- A description of the policies, regulations, and other tools to be implemented in order to achieve the identified goals and objectives; and
- A strategy for development, maintenance, and replacement of public infrastructure.

Missoula County first adopted its Growth Policy in 2002 and an update to the document was subsequently made in 2005. Most recently, the *Missoula County Growth Policy* was amended by the Board of County Commissioners in March 2010. A prevalent theme of the most recent update was identifying actions and strategies to address the effects of rapid community growth and development. The Growth Policy notes that "a primary objective of managing growth is to ensure the availability and affordability of infrastructure such as sewer, water, transportation, public safety, health and social services, public lands, parks, and other open spaces, cultural resources, and education. Adequate infrastructure is essential to a healthy, natural, economic, and social environment in Missoula County."

Long-range transportation planning is recognized as one of many important implementation tools for helping to meet the goals and objectives outlined in the Growth Policy.

# 3.5.2. Missoula Urban Comprehensive Plan: 1998 Update

The *Missoula Urban Comprehensive Plan: 1998 Update*, is a policy document that provides the Missoula County and the City of Missoula and other agencies and districts with a coordinated guide for managing long-term growth and development. The urban area as defined by the Plan includes the Missoula Valley and the Lolo area. The plan recommends the development of planning policies, programs and regulatory tools in response to a "Growth Management Themes Document" for the urban area adopted in 1994 and revised in 1996. The growth management themes, developed by a Growth Management Task Force formed in 1994, are intended to help guide and manage growth in the Missoula urban area and address a range of identified urban growth issues.

Land uses identified in the *Missoula Urban Comprehensive Plan: 1998 Update* for the Maclay Bridge and Target Range area are residential (2 dwelling units per acre) and parks and open space along the Bitterroot and Clark Fork river corridors.

# 3.5.3. Missoula Urban Fringe Development Area (UFDA) Project

The Missoula OPG Urban Initiatives Division undertook its Urban Fringe Development Area (UFDA) Project during 2007 to provide City and County governments with a regional context for making decisions about residential growth on the edges of the City of Missoula. Growth trends suggest that the Missoula Urban Service Area (URSA) could see as many as 15,000 new residential units by 2030. The Missoula Urban Service Area is the same in geographic extent as the Missoula City Waste Water Service Boundary and includes lands in the City of Missoula and unincorporated Missoula County land. The Target Range Neighborhood lies within the URSA.

The goal of the project was to identify how an estimated 15,000 new residential units can be accommodated within the URSA and develop implementation strategies for addressing growth in accordance with adopted policies applicable to the areas. Four growth scenarios were prepared by OPG to describe the number and locations of anticipated new dwelling units, including already entitled lots. Each scenario presented varying growth plans in fourteen "neighborhoods" within the URSA.

OPG staff ultimately recommended the "Focus Inward Scenario" in response to the Growth Policy goals, public comments and agency input, existing zoning, constrained lands, changing market/demographics, entitled lots, and probable infrastructure investments. In November 2008, the UFDA was adopted as an amendment to the 2005 Missoula County Growth Policy. The amendment includes a map showing the preferred residential development allocation within the URSA. The UFDA study forecasted 400 new residential units in the Target Range neighborhood over the next 20-30 years. OPG provides an annual update of the supporting data in the Urban Fringe Development Area (UFDA) Growth Policy Amendment. The most recent update, distributed in May 2012, provides information about community growth during calendar year 2011 and indicates the following:

For the second consecutive year the number of new residential construction building permits increased within the Urban Services Area (URSA). Only 8 of the 538 new residential building permits were for new dwelling units in Target Range/Orchard Homes subarea within the URSA. Overall, the number of new residential construction building permits inside the URSA during 2011 increased by 1.4%. OPG indicates this is within the expected 1 to 2% Annual Adjusted Growth Rate, based on 50 years of census data.

Subdivision activity within the URSA remained slow. There were no major subdivisions approved in the Target Range/Orchard Homes subarea within the URSA during 2011.<sup>3</sup>

# 3.5.4. Target Range Neighborhood Plan

Growth Policies may include neighborhood plans as long as the plans are consistent with the Growth Policy. A neighborhood plan is a plan for a geographic area within the boundaries of the jurisdictional area that addresses one or more of the elements of the growth policy in more detail. The Missoula Growth Policy includes the following types of plans – regional, neighborhood, vicinity, and issue plans. These smaller scale plans are developed to be consistent with broader county-wide objectives, but are specific enough to address issues unique to individual neighborhoods.

Residents of the Target Range neighborhood initiated the process of creating a neighborhood plan in late 2008. This citizen-based planning effort, facilitated by the Missoula OPG, resulted in the development of the *Target Range Neighborhood Plan* which was adopted by Missoula County in June 2010. The *Target Range Neighborhood Plan* is intended to:

- Identify and document the neighborhood's values, interests and goals;
- Make recommendations to achieve identified goals and help guide future development;
- Determine the ability of the area to accommodate future growth;
- Identify, preserve and protect the resources most valued by the neighborhood; and
- Establish goals and priorities that will shape the future of the area.

The Residential Development Allocation Map developed through the UFDA project allocates an additional 1000 new dwellings in the combined Target Range and Orchard Homes neighborhoods by the year 2030, with approximately 400 dwellings in the Target Range neighborhood. Using the Institute of Transportation Engineers (ITE) trip generation rate of 9.57 trips per dwelling unit, the addition of 400 dwelling units alone could result in 3,828 additional vehicle trips per day in the Target Range area. The *Target Range Neighborhood Plan* recommends a residential development density of 1 dwelling unit per acre over most of the neighborhood but identifies a density of 2 dwelling units per acre for the area that lies between Clements Road and the Bitterroot River and between Mount and South Avenues.

The neighborhood plan includes a section devoted to transportation infrastructure and emphasizes that efforts should be taken to mitigate growth in motorized traffic while enhancing the traditional lifestyle and safety of citizens living within the Target Range area. The plan advocates the implementation of transportation alternatives that offset potential negative impacts associated with future development, including expansion of the walking and biking paths to reduce the number of miles traveled to improve air quality. Recommendations and strategies are offered on topics such as speed limits and speed zones, development of bike paths and trails, traffic calming, public transit, and intersection improvements.

The plan also includes the Maclay Bridge. The document emphasizes the importance of continued County maintenance of the structure to help preserve access for local and Missoula Valley residents

<sup>&</sup>lt;sup>3</sup> UFDA Yearbook 2011, released by Missoula OPG on May 16, 2012

seeking recreational opportunities on nearby lands. The *Target Range Neighborhood Plan* does not identify the need for a new bridge.

# 3.6. LOLO NATIONAL FOREST PLAN

Lolo National Forest lands exist south and west of the Bitterroot River. These lands are administered by the U.S. Forest Service (USFS) Missoula Ranger District according to the management direction established in the *1986 Lolo National Forest Plan*. The current Forest Plan indicates the lands are managed for concentrated public use and dispersed recreation opportunities.

The Forest Plan is being revised to reflect new scientific information and natural and social changes that have occurred since its publication. Preliminary USFS documents for the Forest Plan revision show the forest lands in the area may be designated as "Management Area 6.1— High Use Recreation Complexes or Use Areas." Mapping indicates these forest lands are part of the Blue Mountain Recreation Area located southwest of Missoula.

# 4.0 ROADWAY, BRIDGE AND PHYSICAL CHARACTERISTICS

# 4.1. EXISTING ROADWAY USERS

Primary users of the Maclay Bridge consist of local residents from the Target Range and Orchard Homes neighborhoods (east of the Bitterroot River), land owners west of the Bitterroot River, and city and county residents accessing recreational uses along the Bitterroot River and USFS lands. Additionally, the Maclay Bridge is used by pedestrians, bicyclists, emergency response providers, and school buses.

# 4.2. EXISTING TRAFFIC DATA

Historic traffic data for area roadways was obtained from MDT's Bureau of Data & Statistics. **Table 5** shows the most recent 20 years of traffic data for two count stations in the area: one located on River Pines Road just west of the Maclay Bridge and one located on North Avenue just west of Clements Road. The traffic data in **Table 5** is representative of the average annual daily traffic (AADT) volume, in vehicles per day (vpd). AADT volumes account for seasonal and daily travel variations and represent an average number of vehicles to be expected on an average day over the course of a year. The AADT volume is based on adjustments from the ADT (Average Daily Traffic) volume which is a traffic count taken at a specific location during a time period greater than one day but less than 365 days.

Street	Location	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001
<b>River Pines Rd</b>	300 ft W of Maclay Bridge	1610	1580	1840	2060	2190	2230	(a)	(a)	(a)	2230
North Ave	300 ft W of Clements Rd	1610	(a)	2200	(a)	1960	(a)	1980	(a)	1790	(a)
Street	Location	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011
Street River Pines Rd	Location 300 ft W of Maclay Bridge	<b>2002</b> 2300	<b>2003</b> 2060	<b>2004</b> 2300	<b>2005</b> 2130	<b>2006</b> 2410	<b>2007</b> 2460	2008 (a)	<b>2009</b> 2380	<b>2010</b> 2610	<b>2011</b> 2360

### Table 5: Average Annual Daily Traffic

Source: MDT Data and Statistics Bureau, Traffic Data Collection Section, 2012 <sup>(a)</sup> Data unavailable

**Table 5** shows the 2010 AADT volumes are 2,610 vpd (on River Pines Road) and 2,000 vpd (on North Avenue. The year 2010 is the most recent year for which traffic count data is available for both locations shown in **Table 5**. Based on field observations, the majority of traffic is automobiles accessing either adjacent properties or recreational destinations on the west side of the Bitterroot River. The area

roadways are also used by school buses and emergency response vehicles. Vehicles traveling along these two roadways currently do not experience vehicle delay or congestion. However, at the single-lane Maclay Bridge, there can be some delay associated with vehicles waiting to cross the structure. Field observations have shown this delay to take up to 30 seconds during peak hour periods. Delay times will increase with future traffic projections. Travel routes to reach the Maclay Bridge include a network of various local and collector roadways. These include South Avenue, Clements Road, Woodlawn Avenue, North Avenue, and River Pines Road.

Subsequent to the second informational meeting held on July 10, 2012, it was decided to collect additional traffic data on River Pines Road to get an idea of when the hourly peak traffic volumes occur. Missoula County placed automatic hose counters on River Pines Road, just west of the Maclay Bridge, to collect hourly traffic volumes by time of day and by direction. The counter was set up to collect data on Wednesday, October 3, 2012. The peak twelve hours of data, by direction, is shown below in **Table 6**. These are raw traffic volumes in that no adjustments to the data were made for time of week, month of year, etc. **Appendix D** contains the raw data output file.

Time Period	Southbound Traffic Volume (vph)	Northbound Traffic Volume (vph)	Total Hourly Traffic Volume (vph)
7-8 AM	19	151	170
8-9 AM	50	91	141
9-10 AM	31	66	97
10-11 AM	47	58	105
11 AM - NOON	48	64	112
NOON - 1 PM	66	55	121
1 - 2 PM	57	32	89
2 - 3 PM	58	64	122
3 - 4 PM	115	52	167
4 - 5 PM	127	64	191
5 - 6 PM	143	95	238
6 - 7 PM	127	54	181
7 - 8 PM	73	47	120

### Table 6: River Pines Road Hourly Traffic Volumes – Twelve Hour Period (10/03/2012)

Source: Missoula County Public Works Department.

# **4.3. FUTURE TRAFFIC PROJECTIONS**

Projected transportation conditions were analyzed to estimate how traffic volumes and transportation characteristics may change compared to existing conditions. The analysis was based on existing volumes projected out to the year 2040. Two methods were examined. The first method analyzed historic traffic counts from the most recent 20-year period to arrive at an average annual growth rate (AAGR) that could be used to project traffic volumes forward. The second relied on the adopted *TransCad* travel demand model used by the Missoula County OPG and MDT. The *TransCad* model incorporates land use planning found within the Missoula County Growth Policy, including zoning, and also reflects the preferred growth scenario found within the Urban Fringe Development Area (UFDA). Additionally, the *TransCad* model is the tool utilized for the Missoula Area Transportation Plan (2008 and 2012 Updates). Both methods are explained in further detail below.

### 4.3.1. Historic Traffic Growth Rates

Historic traffic data was analyzed to determine traffic growth patterns near the Maclay Bridge. AAGR's were calculated at known traffic count locations. As is evident from **Table 5**, traffic volumes have fluctuated along River Pines Road and North Avenue. For the purposes of projecting traffic growth, AAGR's were calculated for each count site based on the most recent 20 years of traffic data. In addition to the AAGR's, **Table 7** shows year 2030 and 2040 AADT projections at the two traffic count sites.

Road	Location	2010 AADT	AAGR (1992 - 2011)	Projected 2030 AADT <sup>(a)</sup>	Projected 2040 AADT <sup>(a)</sup>
<b>River Pines Rd</b>	300 ft W of Maclay Bridge	2610	1.88%	3,800	4,550
North Ave	300 ft W of Clements Rd	2000	0.51%	2,200	2,350

#### Table 7: Historic Traffic Growth Rates and Projected AADT (Straight-line)

Source: MDT Data and Statistics Bureau, Traffic Data Collection Section, 2012. <sup>(a)</sup> Projected AADT's rounded to nearest 50 vpd.

### 4.3.2. Future Traffic Modeling

A Travel Demand Model (TDM) was utilized as a tool to help predict future traffic growth. The TDM was developed using year 2010 information to determine baseline conditions. Estimated future land use was applied to the model to project year 2040 conditions.

For the purposes of this study, a percent difference in year 2010 and year 2040 traffic volumes from the TDM was calculated to determine a percent growth rate at various locations. Year 2010 and year 2040 TDM traffic volumes are a product of intensive land use and transportation planning exercises that are undertaken by the Missoula County OPG via regular planning exercises. The TDM model is the best tool for forecasting potential traffic given land use plans and the transportation network. However model traffic volumes cannot be construed as being 100 percent accurate. Standard practice is to calculate the percent difference in the model, and apply that percentage to actual, known traffic volumes on the transportation system. Accordingly, the percent growth rate at various locations from the TDM was applied to known AADT traffic count locations to project 2040 AADT values. **Table 8** provides a summary of traffic count locations within the study analysis area. These results are also shown graphically in **Figure 3**.

The results provided in **Table 8** and **Figure 3** differ from earlier results presented to the public at the second informational meeting held on July 10, 2012. At the second informational meeting, the results of the TransCad travel demand model were questioned as some members of the public believed the land use inputs did not represent the adopted land use strategies in place through Missoula County planning documents. Accordingly, the TransCad model input, and corresponding output, was further reviewed by Missoula County and MDT and updated. The model results shown in **Table 8** and **Figure 3** are from the most current TransCad model that is being used - not only for this planning study, but also the regional transportation plan update currently in process by Missoula OPG.

Street	Location	2010 AADT	2010 TDM	2040 TDM	TDM % Diff	Projected 2040 AADT <sup>(a)</sup>
Big Flat Rd	100 ft W of O'Brian Ck Rd	1,870	2,199	7,691	249.7%	6,550
Blue Mountain Rd	500 ft N of Hwy 93	2,360	2,628	6,091	131.8%	5,450
Blue Mountain Rd	S of South Side Rd	1,370	1,674	5,346	219.4%	4,400
Brooks St	Bitterroot River Bridge	26,530	26,157	45,368	73.4%	46,000
Clements Rd	300 ft N of North Av	3,140	2,615	4,914	87.9%	5,900
Clements Rd	300 ft S of North Av	2,750	1,811	2,549	40.8%	3,850
Clements Rd	500 ft S of S 3rd W	2,350	1,914	3,677	92.1%	4,500
Kona Ranch Rd	Kona Ranch Bridge	(b)	1,723	6,471	275.6%	(b)
Mullan Rd	E of Snowdrift Ln	3,950	4,284	9,870	130.4%	9,100
North Av	300 ft W of Clements Rd	2,000	1,318	3,118	136.6%	4,750
Reserve St	Between Dearborn & South Av	33,580	32,617	45,425	39.3%	46,750
Reserve St	Between Olofson Dr & S 3rd W	38,010	38,985	51,443	32.0%	50,150
Reserve St	Between South Av & Central Av	36,740	36,953	47,510	28.6%	47,250
Reserve St	S of Larkenwood Dr	37,930	39,255	52,411	33.5%	50,650
River Pines Rd	300 ft W of Maclay Bridge	2,610	2,779	6,039	117.3%	5,650
S 3rd W	W of Reserve	7,620	6,690	11,596	73.3%	13,200
S 7th W	150 ft W of Reserve	1,320	1,901	4,664	145.3%	3,250
S 7th W	300 ft E of Clements Rd	350	345	699	102.6%	700
South Av	Between 31st and 33rd	6,610	6,491	8,187	26.1%	8,350
South Av	Between Humble & Pleasant	1,770	2,210	3,638	64.6%	2,900
South Av	Between Reserve & 26th	15,010	14,914	16,255	9.0%	16,350
South Av	E of Clements Rd	4,350	4,952	6,141	24.0%	5,400
South Av	W of Clements Rd	4,710	5,379	7,453	38.6%	6,550
Spurgin Rd	250 ft W of Reserve	2,000	2,401	3,086	28.5%	2,550
Spurgin Rd	300 ft E of Clements Rd	980	1,033	1,285	24.4%	1,200

### Table 8: 2040 AADT Traffic Modeling Projections

Source: MDT Multi Modal Planning Bureau, Statewide & Urban Planning Section, 2012; Missoula Office of Planning and Grants, Transportation Division.

<sup>(a)</sup> Projected AADT's rounded to nearest 50 vpd.

<sup>(b)</sup> Data unavailable

Both projection methods yield different results. For example, for a straight-line growth based on historical data for 20 years (see **Table 7**), the count location just west of the Maclay Bridge (i.e. River Pines Road) yields a future year 2040 estimated AADT of 4,550 vpd, while the *TransCad* travel demand model (**Table 8**) yields a future year 2040 estimated AADT of 5,650 vpd. The North Avenue count location yields an estimated AADT of 2,350 vpd as compared to a *TransCad* estimated AADT value of 4,750 vpd.

For planning purposes, the *TransCad* travel demand model was used for future year projections and improvement option analysis. The *TransCad* model incorporates land use planning found within the Missoula County Growth Policy, including zoning, and also reflects the preferred growth scenario found within the Urban Fringe Development Area (UFDA). Additionally, the *TransCad* model is the tool utilized for the Missoula Area Transportation Plan (2008 and 2012 Updates). The *TransCad* model utilizes existing housing and employment data, with the existing transportation network, to represent the "built environment" found within the area.




Figure 3: Percent Change in AADT

# 4.4. CRASH ANALYSIS

The MDT Traffic and Safety Bureau provided crash data for the ten-year period from January 1, 2002 to December 31, 2011. The crash data was provided for the following locations:

- Township 13 North, Range 20 West, Section 26 (T13N R20W S26)
- Township 13 North, Range 20 West, Section 27 (T13N R20W S27)
- Township 13 North, Range 20 West, Section 34 (T13N R20W S34)
- Township 13 North, Range 20 West, Section 35 (T13N R20W S35)

According to the MDT crash database, there were 131 total crashes reported within these identified locations during the ten-year time period. Reportable crashes are defined as those with a fatality, an injury, or property damage only with a minimum of \$1,000 in damages.

As part of the crash analysis, crash investigation reports were reviewed to help identify specific locations and contributing factors. Based on the information provided in the crash reports, trends and contributing factors for the crashes, along with characteristics of the drivers and vehicles involved, were identified. The information and analysis provided herein is a summary of the data as contained in the reports.

A location map of the reported crashes is shown in **Figure 4**. Based on the crash data, a number of crash clusters and trends were identified and are discussed further below. The crash trends and locations presented below comprise a total of 95 of the 131 reported crashes. The remaining crashes are scattered throughout the four sections of land queried for crashes.

### BIG FLAT ROAD

Six crashes were reported along Big Flat Road at or near the horizontal curve located approximately 0.15 miles northwest of the intersection with River Pines Road. All 6 involved single vehicles with 5 occurring during "dark not lit" conditions and two resulting in injuries. The most common contributing circumstance for the crashes was driving too fast for conditions.

### BLUE MOUNTAIN ROAD

Blue Mountain Road had two separate crash clusters noted within the analysis area. A crash cluster was noted approximately 0.3 miles south of the intersection with River Pines Road along a sharp horizontal curve. A total of 16 crashes were reported at this location. Of the 16 crashes, 15 involved a single vehicle. Five crashes resulted in a total of 10 injuries. Eight crashes occurred during "dark not lit" conditions. The most common contributing circumstances reported were driving too fast for conditions and careless driving. In addition, alcohol was listed as a contributing factor in 4 crashes. As noted previously in **Section 1** of this report, MDT currently has a planned safety project for this location to address the identified crash trends.

A second crash cluster was noted along the horizontal curves located approximately 0.5 to 0.9 miles south of the intersection with River Pines Road. There were 13 reported crashes along the 0.4 mile segment of Blue Mountain Road. All 13 crashes were single-vehicle crashes with 4 occurring during "dark not lit" conditions. Two crashes resulted in a total of two injuries. Driving too fast for conditions and/or careless driving were listed as the most common contributing circumstances. Alcohol was a contributing factor in 4 of the crashes in this cluster.

### NORTH AVENUE

There were 12 crashes reported along the 0.25 mile segment of North Avenue between Humble Road and the Maclay Bridge. Seven of the 12 crashes involved more than one vehicle. The most common contributing circumstances were inattentive driving and failure to yield. Alcohol was listed as a factor in one crash.

#### **RIVER PINES DRIVE**

A total of 18 crashes were reported between Maclay Bridge and Riverside Drive. These crashes resulted in a total of 12 injuries. Of the 18 crashes, 12 occurred under "dark not lit" conditions and three involved multiple vehicles. Alcohol involvement was a factor in 8 of the 18 crashes. Inattentive driving, driving too fast for conditions, and careless driving were other common contributing circumstances for crashes occurring in this area of River Pines Drive. In addition, a "head-on" crash was located in this area. As noted previously in **Section 1** of this report, MDT currently has a planned safety project for this location to address the identified crash trends.

A second crash cluster was noted along the horizontal curves located approximately 0.15 to 0.30 miles southwest of the intersection with Riverside Drive. Eight crashes were reported along the 0.15 mile stretch of River Pines Drive, 3 of which occurred under "dark not lit" conditions. Seven of the 8 reported crashes involved a single vehicle and none of the crashes resulted in injuries. Careless driving and driving too fast for conditions were the most common contributing circumstances. Alcohol involvement was a contributing factor in 1 crash at this location.

Another crash cluster was noted between the intersection with Big Flat Road and the sharp horizontal curve located approximately 0.25 miles east of Big Flat Road. A total of 12 crashes were reported at this location, eight of which involved a single vehicle. Five crashes occurred under "dark not lit" conditions. Three crashes resulted in a total of 4 injuries. Alcohol involvement was a factor in 5 of the 12 crashes. Careless driving and driving too fast for conditions were the most common contributing circumstances.

#### SOUTH AVENUE

A crash cluster was noted along South Avenue between the intersections with Pauline Drive and Woodlawn Avenue. Ten crashes were reported here, with 7 occurring under "dark not lit" conditions. Eight of the 10 reported crashes involved a single vehicle, while 4 crashes resulted in a total of 5 injuries Alcohol was a contributing factor in 4 crashes.

### 4.4.1. Identifiable Crash Trends and Areas of Concern

A number of crash trends and areas of concern were identified within the crash analysis area. The following crash trends and areas of concern were identified based on MDT-supplied crash data and field investigators reports:

- Big Flat Road
  - Single vehicle crashes along the horizontal curve approximately 0.15 miles north of the intersection with River Pines Road.
- Blue Mountain Road
  - Single vehicle crashes along the sharp horizontal curve approximately 0.3 miles south of the intersection with River Pines Road.
  - Single vehicle crashes along the horizontal curves located approximately 0.5 to 0.9 miles south of the intersection with River Pines Road.
- North Avenue
  - Crashes with inattentive driving and failure to yield listed as contributing circumstances between Humble Road and the Maclay Bridge.

- River Pines Drive
  - Single vehicle crashes at or near the intersection with Riverside Drive under "dark not lit" conditions.
  - Single vehicle crashes along the horizontal curves located approximately 0.15 to 0.30 miles southwest of the intersection with Riverside Drive.
  - Crashes between the intersection with Big Flat Road and the sharp horizontal curve located approximately 0.25 miles east of Big Flat Road.
- South Avenue
  - Single vehicle crashes between the intersections with Pauline Drive and Woodlawn Avenue under "dark not lit" conditions.




Figure 4: Crash Locations (01/01/2002 - 12/31/2011)

# 4.5. EXISTING TRAVEL TIMES

A "travel time" evaluation was conducted to determine the approximate time it would take to travel within the Maclay Bridge area. The travel time evaluation was completed during the middle of a weekday, during off-peak travel hours. Although this evaluation was performed under "normal" driving conditions in a private automobile, it is acknowledged that in an emergency response situation that responders may likely travel faster and have the ability to "pre-empt" traffic signals on certain roadways. Although there are no traffic signals in the immediate vicinity of the Maclay Bridge area, for purposes of alternate routes traffic signals may influence travel times. Travel times along three distinct routes from east of the Bitterroot River to the intersection of Big Flat Road/Blue Mountain Road/O'Brien Creek Road/River Pines Road were calculated. Each route crossed the Bitterroot River using one of three crossings: the Maclay Bridge, the Kona Ranch Bridge, or the Buckhouse Bridge.

The three origins that were identified for this analysis included the following:

- Missoula Rural Fire Station #1 Located on South Avenue
- Community Medical Center Located on South Avenue
- Missoula Rural Fire Station #6 Located on Mullan Road

**Table 9** shows the travel times from these origins to the intersection of Big Flat Road/Blue Mountain Road/O'Brien Creek Road/River Pines Road using the three routes that cross the Bitterroot River on a typical weekday. Trips to and from each location were performed to help establish typical travel times.

	Maclay I	Maclay Bridge		dge	Buckhouse Bridge	
Route <sup>(a)</sup>	Baseline Travel Time	Distance Travelled	Additional Travel Time if Maclay Bridge Out of Service	Distance Travelled	Additional Travel Time if Maclay Bridge Out of Service	Distance Travelled
Fire Station #1 to/from Intersection	6.52 minutes	3.65 miles	17.64 minutes	13.74 miles	3.36 minutes	5.87 miles
Community Medical Hospital to/from Intersection	6.17 minutes	3.41 miles	18.58 minutes	13.98 miles	4.47 minutes	6.11 miles
Fire Station #6 to/from intersection	19.61 minutes	10.05 miles	(8.09 minutes) <sup>(b)</sup>	7.34 miles	2.62 minutes	12.14 miles

### **Table 9: Travel Time Evaluation**

Source: RPA field data collection during normal weekday, off-peak hours.

<sup>(a)</sup> Each route was driven once in each direction, and results were averaged to arrive at noted travel time.

<sup>(b)</sup> Travel time is reduced by 8.09 minutes from baseline travel time measurement.

The table shows if the Maclay Bridge is inaccessible, the time it would take to reach the intersection of Big Flat Road/Blue Mountain Road/O'Brien Creek Road from most of the locations of interest increases. For example, if the Maclay Bridge was out of service, it would be expected to take approximately 18.58 minutes longer using the Kona Bridge or 4.47 minutes longer using the Buckhouse Bridge when travelling between Community Medical Hospital and the subject intersection. In terms of emergency service, this means that travel times would likely be longer if the Maclay Bridge is out of service. During the field work, it was noted that many intersections located on Reserve Street are large, with traffic and congestion on Reserve Street increasing during the daytime business hours. This may cause an even greater delay for the emergency respondents needing to access the intersection using a route that includes Reserve Street. Comments provided by the Missoula Rural Fire Department state that 5 minutes or more are added to their response times when using the Buckhouse Bridge in lieu of the Maclay Bridge.

# 4.6. DESIGN STANDARDS

Design standards are an important consideration when assessing existing areas of concern, as well as for planning new infrastructure. Depending on funding source, different sets of design standards may be applicable to the Maclay Bridge. One set of standards are the design standards in place by Missoula County. These standards are found via the Missoula County *Public Works Manual 2010*, and set forth road design considerations for various roadway classifications. **Table 10** depicts the roadway design considerations adopted by Missoula County, along with select subdivision standards that establish minimum surface widths for various road classifications. According to the data in **Table 10**, a collector roadway built to Missoula County standards would have a surface width of 44 feet. The County's standards for collector roadways were used as a basis to evaluate existing design concerns on River Pines Road and North Avenue in section 4.7. Vertical grades and horizontal curvature were of primary importance in evaluating consistency with design standards.

Roadway functional classifications are typically defined as arterials, collector routes and local streets. These road types can apply to both an urban and a rural area, with slight modifications. Missoula County defines roads within their jurisdiction as presented in the Missoula County *Public Works Manual*. For the roadway classifications found within the immediate vicinity of the Maclay Bridge, the following definitions apply:

- Arterial A street or road having the primary function of moving traffic and the secondary function of providing access to adjacent land. Arterials generally carry relatively large volumes of traffic. Characteristics of an arterial are two to four lanes of traffic with limited access to abutting property.
- **Collector** A street or road having the equally important functions of moving traffic and providing access to adjacent land. General characteristics of collector streets are two traffic lanes and two parking lanes serving more than 200 lots. Residential collectors serve only residential neighborhoods; non-residential collectors serve other land uses.
- **Minor Collector** A street or road having the equally important functions of moving traffic and providing access to adjacent land. General characteristics of collector streets are two traffic lanes and one or two parking lanes serving between 40 and 199 lots.
- Local Streets A street or road having the primary function of serving abutting properties and the secondary function of moving traffic. Local streets generally consist of two traffic lanes, may include one or two parking lanes and provide access to abutting properties. Local streets shall be designed to discourage future use as collector streets. Residential local streets serve individual residential areas; non-residential local streets serve nonresidential land uses.

It is also important to note there is a difference between a facility's design speed and its operating speed. The <u>design speed</u> is a selected speed used to determine the various geometric design features of the roadway. The <u>operating speed</u> is the highest overall speed at which a driver can travel on a given section of roadway under favorable weather conditions and under prevailing traffic conditions without at any time exceeding the safe speed as determined by the design speed. The operating speed is different than the <u>posted speed</u>. Posted speed limits are typically accomplished by measuring the speeds at which 85 percent of the drivers are travelling at or below, and signing for that speed within 5 mph of the result. This is typically referred to as the 85<sup>th</sup> percentile speed. Posted speeds are commonly set at 25 mph on local urban roads.

	Road Classification					
Design Parameter	Local	Minor Collector	Collector	Arterial		
Design Speed (mph)	25-35	25-35	25-45	35-55		
Maximum Vertical Grade (%)	10	8	6	6		
Minimum Horizontal Curve Radius (ft)	150	200	525	900		
Return Radius Between Intersecting Streets <sup>(a)</sup> (ft)	25	35	50	50		
Horizontal Clearance (ft)	20	20	20	20		
Vertical Clearance (ft)	14	14	14	14		
Surface Width (ft)	24-32	32	44	44		
Right-of-Way Width (ft)	40-60	60-70	60-80	60-80		

### Table 10: Missoula County Roadway Design Considerations

Source: Table 6.1, "Road Design Considerations" and Table 6.2, "Minimum Surface Widths Required for Road Improvements", Missoula County Public Works Manual, 2010

<sup>(a)</sup> Based on road with higher classification

AASHTO design standards may be applicable since Missoula County does not have any specific "bridge related" standards to measure against. AASHTO bridge width standards allow a single-lane bridge only for very low volume roads in which traffic is less than 100 vpd. In those cases, the minimum single-lane bridge width must be no less than 15 feet in width (see AASHTO's *Guidelines for Geometric Design of Very Low-Volume Local Roads, 2001*). Since existing, and projected traffic volumes, are much higher than this threshold (2,610/5,650 respectively), applicable AASHTO design standards are found in AASHTO's *A Policy on Geometric Design of Highways and Streets, 2011*. For "local" and "collector" road classifications, the minimum clear width for a bridge carrying over 2,000 vpd is equal to 30 feet (two 12-foot driving lanes plus 3-foot shoulders on each side).

An additional set of design standards, and those that may be considered in design if Federal or State funds were used for any type of project identified through this planning effort, are the standards and guidelines found in MDT's *Road Design Manual (*RDM). The RDM specifies general design principles and controls which determine the overall operational characteristics of the roadway and enhance the aesthetic appearance of the roadway. If a new bridge results from the study, either at its present location or an alternate location, it would connect to roadways currently classified as rural roads or streets. The RDM geometric design criteria would be reviewed in the context of the adjacent land use, topography, and function, and compared to existing Missoula County design criteria.

Using the National Bridge Inspection (NBI) Coding Guide, the minimum bridge "curb-to-curb" width needed to eliminate the "Functionally Obsolete" designation is 28 feet and applies to an ADT range of 2,001 to 5,000 vpd. If the bridge length is greater than 200 feet, then the 28 feet width could be applied to an ADT greater than 5,000 vpd. The 28 feet would allow for two 12-foot lanes, and a 2-foot shoulder on each side. Accordingly, it is likely that the minimum bridge width, "curb-to-curb", would need to be at least 28 feet.

For most "off-system" locations such as the Maclay Bridge (i.e. not on a State-highway), local conditions and context to the surrounding land uses would be considered in developing geometric features such as road width, acceptable curves, and the need for non-motorized facilities.

# 4.7. ROADWAY GEOMETRICS

Existing roadway geometrics were evaluated and compared to current Missoula County standards. The analysis was conducted based on a review of public information, bridge drawings, Geographic Information Systems (GIS) data, and field observations. As-built drawings for area roadways were not available. As such, a field review was conducted in April 2012 to confirm and supplement information, as

well as to identify additional areas of concern within the Maclay Bridge area. **Appendix A** provides a log of some of the photos taken during the field review.

# 4.7.1. Horizontal Alignment

Elements comprising horizontal alignment include curvature, superelevation (i.e. the "bank" on the road), and sight distance. These horizontal alignment elements influence traffic operation and safety. As mentioned in section 4.6, Missoula County roadway standards for a collector roadway were used as a basis to evaluate existing design concerns along River Pines Road and North Avenue. Missoula County's standards for horizontal curves are defined in terms of curve radius, and for a collector roadway, the minimum required radius is 525 feet.

Horizontal curve radii were evaluated based on field review and aerial photography. Three horizontal curves were identified that do not meet current Missoula County standards. These three curves also do not meet current MDT design standards. **Table 11** provides a summary of the three substandard horizontal curves. The presence of sub-standard curvature may contribute to crash numbers and severity.

### **Table 11: Horizontal Alignment Areas of Concern**

Location	Feature	Value <sup>(a)</sup>	Standard	
North Ave W / Edward Ave Intersection	450' SE of Maclay Bridge	Horizontal Curve	175'	525'
River Pines Rd / Riverside Dr	50' NW of Maclay Bridge	Horizontal Curve	125'	525'
River Pines Rd	2300' SW of Maclay Bridge	Horizontal Curve	125'	525'

<sup>(a)</sup> Estimated based on aerial photography

# 4.7.2. Vertical Alignment

Vertical alignment is a measure of elevation change of a roadway. The length and steepness of grades directly affects the operational characteristics of the roadway. In addition, the available stopping sight distance (SSD) for the vertical alignment, and specifically the vertical curvature, also directly affects the operational characteristics of the roadway.

Missoula County roadway standards for a collector roadway define a maximum allowable vertical grade of 6.0 percent. As-built drawings were not available for River Pines Road or North Avenue, thus field observations were made and noted pertinent to vertical grades. Both roadways connecting to the Maclay Bridge were estimated to have grades that do not exceed the Missoula County standard of 6.0 percent for a collector roadway or the current MDT design standards.

# 4.7.3. Roadside Clear Zone

The roadside clear zone, starting at the edge of the traveled way, is the total roadside border area available for safe use by errant vehicles. This area may consist of a shoulder, a recoverable slope, a non-recoverable slope, and/or recovery area. The desired clear zone width varies depending on traffic volumes, speeds, and roadside geometry. Clear zones are evaluated individually based on the roadside cross section.

Clear zones should be attained by removing or shielding obstacles if costs are reasonable. In certain instances, it may be impractical to protect or remove certain obstacles within the clear zone. As improvement options develop, roadside clear zones should be designated, to a practical extent, to meet current design standards to improve safety deficiencies to reduce the likelihood of crashes. The presence of unshielded obstacles and/or non-recoverable slopes may contribute to crash numbers and severity.

Within the area, there were locations identified that do not meet the Missoula County horizontal clearance requirement as listed in **Table 10** for a collector roadway. The most notable area is located along River Pines Road, just southwest of the existing bridge. At this location, the top of roadway fill slope is between 2 and 4 feet from the edge of the travel lane. In addition, trees and utility poles are found within this area. The roadway fill slope in this area is steep and lined with riprap to the river.

# 4.8. BRIDGE CONSIDERATIONS


The dominant transportation feature located within the study area is the Maclay Bridge. It has been the subject of past technical and planning level analysis, and was analyzed in detail during the development of the 1994 Maclay Bridge Site Selection Study EA. **Table 12** shows the bridge number, date of most recent inspection, type, size, and year constructed (or reconstructed). A copy of the most recent Bridge Inspection Report completed by MDT is included in **Appendix B**. **Table 13** presents both the operating and inventory rating load for the structure, correlated to different truck sizes. Design loads are expressed in metric tons (mton), which represents the total mass of the entire vehicle, while ratings are expressed in tons, which is more common for posting.

### Table 12: Bridge Location and Type

Number	Structure Name	Date of Last Inspection	Type of Bridge (Dimensions)	Year Constructed (Reconstructed)	Waterbody Traversed
L32101000+01001	Maclay Bridge	10/31/2011	4-span structure	1935 (1964)	Bitterroot River
132101000101001	Maciay Bridge	10/31/2011	(16' wide x 346' long)	1555 (1504)	

Source: MDT Bridge Management System, 2012

The three rating vehicles include Type 3 (single truck), Type 3-S3 (semi-truck and trailer) and Type 3-3 (truck and "pup"). **Figure 5** shows truck schematics for the three rating vehicles. For a short-span bridge such as the Maclay Bridge, the Type 3 (single truck) vehicle would be the likely unit for design purposes.





Rating / Truck Type	Maclay Bridge
Operating Load (Design)	(20.9 mton)
Truck 1 Type 3 <sup>(a)</sup> Rating	19 ton
Truck 2 Type 3-S3 Rating	29 ton
Truck 3 Type 3-3 Rating	37 ton
Inventory Load (Design)	(12.7 mton)
Truck 1 Type 3 <sup>(a)</sup> Rating	11 ton
Truck 2 Type 3-S3 Rating	17 ton
Truck 3 Type 3-3 Rating	22 ton

### Table 13: Bridge Design Loads and Ratings

Source: MDT Bridge Management System, 2012

<sup>(a)</sup> Posted at 11 tons

- The <u>operating rating</u> defines the absolute maximum permissible load level to which the structure may be subjected for the vehicle type used in the rating. This rating determines the capacity of the bridge for occasional use. Allowing unlimited numbers of vehicles at the operating level will compromise the bridge life.
- The <u>inventory rating</u> defines the load level which can safely use an existing structure for an indefinite period of time.
- The <u>posting rating</u> results in a load level which may safely use an existing structure on a routine basis for a limited period of time. When a bridge is not able to safely carry the loads allowed, it is posted for its inventory rating.

Since the 2011 Bridge Inspection Report was prepared, there has been further analysis of the bridge that resulted in the posted load limit being reduced from 14 tons to 11 tons. This reduction was based on analysis by MDT engineers. The two primary vehicles impacted by this reduction are school buses and fire trucks. School buses are generally within the 11 ton limit, as they weigh approximately 19,000 pounds when empty and 22,000 pounds when loaded. Fully loaded school buses are near or at the 11 tons limit. School buses are thus allowed across the bridge, as long as they do not exceed the posted 15 mph speed limit.

An agreement exists that allows the local rural fire department to operate their Type I fire engines (i.e. overweight vehicles) across the bridge, as long as they straddle the centerline of the bridge and travel no more than 5 mph.

The 2011 Bridge Inspection Report also noted some areas of concern related to a variety of bridge features. Some of these are reiterated below (see **Appendix B** for further detail).

- Transverse cracking in deck asphalt surfacing;
- Paint loss and rusting on various features, such as floor beams, bottom chords, and steel stringers;
- Minor cracking and spalling on concrete pier wall and abutments; and
- Moveable roller bearings are not functional and are out of alignment.

Residents reaffirmed those findings during the public process and RPA staff reviewed these areas of concern in the filed for validity. These areas of concern are listed below (select photographs of some of these concerns are included in **Appendix A**).

- The current structure exhibits spalling and cracked concrete and exposed rebar;
- Rust and steel pitting is observed under the bridge on some load bearing members and the deck;
- The bridge is a composite of varying ages and types of load-bearing steel used throughout the structure; and
- The strength of the steel is unknown in much of the bridge, as it has never been tested.

# 4.8.1. Sufficiency Rating

An important consideration in the evaluation of roadway bridges is the sufficiency rating associated with the structure. The sufficiency rating formula is the industry standard of evaluating highway bridge data to obtain a numeric value indicating the sufficiency of the bridge to remain in service. The sufficiency rating is expressed by a value ranging from 0 to 100 with 100 being an entirely sufficient bridge and 0 being an entirely deficient bridge. To receive funding through the Off-System Bridge Program, structures must be classified as "Structurally Deficient" or "Functionally Obsolete" and have a sufficiency rating of 80 or below. Structures with a sufficiency rating of 0 to 49.9 are eligible for replacement, and structures at 50 to 80 are eligible for rehabilitation unless otherwise approved for replacement by the FHWA. The following criteria determine whether or not a structure is structurally deficient or functionally obsolete:

### STRUCTURALLY DEFICIENT

A condition of 4 or less for any of the following:

- Deck Rating
- Superstructure Rating
- Substructure Rating

Or, an appraisal of 2 or less for the following:

- Structure Rating
- Waterway Adequacy

### FUNCTIONALLY OBSOLETE

An appraisal of 3 or less for the following:

- Deck Geometry
- Under Clearance
- Approach Roadway Alignment

Or, an appraisal of 3 for the following:

- Structure Rating
- Waterway Adequacy

According to the National Bridge Inspection Standards (NBIS), <u>condition ratings</u> are used to describe an existing bridge compared with its condition if it were new. The ratings are based on the materials, physical condition of the deck (riding surface), the superstructure (supports immediately beneath the driving surface), and the substructures (foundation and supporting posts and piers). General condition ratings range from 0 (failed condition) to 9 (excellent condition). This differs from <u>appraisal ratings</u>, which are usually done in the office where access to all necessary information and specifications is available, and consider the field condition, waterway adequacy, geometric and safety configurations, structural evaluation, and safe load capacity of the bridge.

Based on the most recent Bridge Inspection Report, the Maclay Bridge was determined to be functionally obsolete, but not structurally deficient. Its sufficiency rating is calculated to be 27.3, which is less than 49.9, thereby making the bridge eligible for replacement.

A functionally obsolete bridge is one that was built to standards that are not used today. Functionally obsolete bridges are those that do not have adequate lane widths, shoulder widths, or vertical clearances to serve current traffic demand, or those that may be occasionally flooded. Functionally obsolete bridges are not automatically rated as structurally deficient, nor are they inherently unsafe. American Association of State Highway Transportation Officials (AASHTO) standards specify single-lane bridges are appropriate on routes with AADT volumes less than 50 vpd. For the Maclay Bridge, the appraisal values for the "Deck Geometry" and the "Approach Roadway Alignment" are such that the bridge is categorized as being functionally obsolete. This is based on the single-lane width of the bridge being sub-standard for the current traffic volumes, and the sub-standard curves on both approaches to the bridge.

**Table 14** shows the sufficiency rating for the Maclay Bridge. For the "Under Clearance" criteria, a notation of "N" means that the structure does not pass over a highway or railroad and is not relevant to the functionally obsolete sufficiency rating criteria. Off-system bridge data statewide suggests that 98.3 percent of all off-system bridges have a sufficiency rating higher than the Maclay Bridge health index.

Criteria		Maclay Bridge		
Structurally Deficiency Suffici	iency l			
Deck Rating	≤4	6		
Superstructure Rating	≤ 4	6		
Substructure Rating	≤ 4	5		
Structure Rating	≤ 2	4		
Waterway Adequacy		8		
Functionally Obsolete Sufficie	ency R	ating Criteria		
Structure Rating	3	4		
Deck Geometry	≤ 3	3		
Under Clearance	≤ 3	N		
Waterway Adequacy	3	8		
Approach Roadway Alignment		3		
Sufficiency Rating		27.3		
Structure Status		Functionally Obsolete / Not Structurally Deficient		

#### Table 14: Bridge Sufficiency Rating for Maclay Bridge

Source: MDT Bridge Management System, 2012. Calculations for Sufficiency Ratings utilize a formula that includes various factors determined during the bridge field inspection and evaluation.

# 4.8.2. Bridge Health Index

The "Health Index" is a variable based on "weighting" bridge components to establish a clear, dependable communication of bridge performance information to management, elected officials, and the public. The Bridge Health Index is a 0-100 ranking system for bridge maintenance with 100 being a "best" condition and 0 indicating a "worst" condition. The health index provides an indication of how individual bridge components rank on the 0-100 condition scale. To generate a health index rating for the entire bridge, weighted values are assigned to the individual bridge components according to the economic consequences of their failure. Thus, components whose failure has relatively little economic effect, such as railings, receive less weight than those whose failure could close the bridge, such as girders. The Health Index number provides a performance measure and management tool for bridge maintenance.

The health index is not an FHWA directive for assessing bridges, rather, it was developed by the California Department of Transportation (Caltrans) and its computations are now included in bridge management software. Guidance provided by Caltrans suggests that the health index concept for a single bridge be evaluated in context with a statewide network of bridges. Based on the recent October 31, 2011

bridge inspection, the Maclay Bridge was given a health index of 89.91. Montana's statewide off-system bridge data indicates that 72.9 percent of all off-system bridges have a health index higher than the Maclay Bridge health index. This health index value places the Maclay Bridge near the bottom quartile of all off-system bridges.

### 4.8.3. Fracture Critical Status

The Maclay Bridge is fracture critical. Truss bridges are typically fracture critical. If one part of the truss should fail, the entire bridge span may fail. As a bridge ages and traffic increases the steel in the truss may begin to weaken because of fatigue. The bridge requires special "fracture critical" inspections to reduce the chance of failure. With proper inspection and maintenance, the bridge is considered safe. An inspection that shows a problem could result in immediate closure.

# 4.9. PARKING CONSIDERATIONS

Over the past 30 years, Missoula County has passed numerous resolutions that restrict parking within the vicinity of the Maclay Bridge. Although comments made at the first informational meeting do not indicate parking is an issue, research of past resolutions indicates that parking concerns have existed since at least 1979. Copies of various parking resolutions are included in **Appendix C**. **Table 15** identifies the resolution number, title, passage date, and summarizes their content.

Table 15: Mis	ssoula County Parking Resolutions	
Resolution	·	Passag


Resolution Number	Resolution Title	Passage Date	Summary Description
	REGULATION OF PARKING, CONGREGATING,	24-Jul-79	<ul> <li>Prohibits parking on the Maclay Bridge and the road right-of-way leading to it for 500 yards</li> </ul>
79-128			<ul> <li>Prohibits loitering on, fishing from, diving or jumping from, and climbing or congregating on the Maclay Bridge</li> </ul>
	ETC. ON MACLAY BRIDGE		<ul> <li>Requires signing on the Maclay Bridge and approaches prohibiting parking</li> </ul>
			Allows Missoula County Sheriff to take action to ensure compliance
	A RESOLUTION CREATING A RESIDENTIAL ON-STREET PARKING PERMIT REGULATION PROGRAM IN THE MACLAY BRIDGE AREA		Established the Maclay Bridge On-Street     Parking Permit Regulation Program
90-064		18-Jul-90	Between June 1st and September 30th
90-064			Between 3:00 pm and 6:00 am
			<ul> <li>Created boundary of program – just east of Humble Road &amp; west to Blue Mountain Road</li> </ul>
91-067	A RESOLUTION SUPERCEDING RESOLUTION NO. 90-064, A RESOLUTION CREATING A RESIDENTIAL ON-STREET PARKING PERMIT REGULATION PROGRAM IN THE MACLAY BRIDGE AREA, SIGNED JULY 18, 1990 (AMENDING SECTION 1, PARAGRAPH A)	17-Jul-91	<ul> <li>Added clarification to "Section 1, Paragraph A" of resolution 90-064</li> </ul>
99-003	REGULATING PARKING, CONGREGATING, ETC. ON MACLAY BRIDGE AND AMENDING RESOLUTION 79-128	7-Jan-99	Amended resolution 79-128
			Amended resolution 91-067
2011-073	REGULATING PARKING, CONGREGATING, ETC. ON MACLAY BRIDGE AND AMENDING RESOLUTION NO. 91-067	7-Jun-11	• Extends the parking district boundary further to the east along North Avenue, past Humble Road, by 300 feet
			At the request of landowners

Source: Missoula County Public Works Department, 2012

In addition, a review of Missoula County "911 Calls" was completed. In a search of the call records for the Orchard Homes and Target Range areas for June, July and August of 2010 and 2011, numerous citations were issued (see **Figure 6**) in response to activities near the bridge. These citations included the following categories:

- Criminal Mischief, Curfew and Loitering, Disorderly Conduct, Disturbance, Suspicious Activity
- Extra Patrol
- Hazardous Vehicle
- Other Hazard

During this time period, there were 109 calls made for the area located at the east end of the existing bridge (4680 North Avenue West). Of these calls, 42 were for "hazardous vehicle", which is primarily related to parking concerns. The review of the provided 911 calls, coupled with the many parking resolutions passed over the four decades by Missoula County, indicate parking is a concern in the vicinity of the Maclay Bridge.



#### Figure 6: Crime Locations in General Vicinity

## 4.10. ROADWAY SURFACING

Existing roadway surfacing characteristics were determined through field measurements for River Pines Road, the Maclay Bridge, and North Avenue. Items measured included the surface width, lane width, shoulder width, and the presence of non-motorized features. **Table 16** shows the existing roadway and bridge widths.

	Location	Lanes	Surface Width (ft)	Lane Width (ft)	Shoulder Width (ft)
North Ave W	Clements Rd to Maclay Bridge	2	31	11	1 (north) / 8 (south)
Maclay Bridge	On Bridge	1	14	14	0
<b>River Pines Rd</b>	Maclay Bridge to Blue Mountain Road	2	22	11	0

#### Table 16: Existing Road and Bridge Surfacing

Source: Estimated based on field measurements

The MDT *Road Design Manual* indicates a top width of 40 feet is appropriate. This roadway width would accommodate two 12-foot travel lanes and two 8-foot shoulders. The MDT RDM is a guideline only, and due to the approach roadways being under County jurisdiction, close coordination with Missoula County would be necessary to define the appropriate roadway width that is context sensitive to the community and still meets Missoula County requirements for safe and efficient travel. Missoula County standards (**Table 10**) indicate the required surfacing width would be 44 feet for a collector roadway. Neither the Missoula County nor MDT standard widths are attained on the bridge or its approaches.

## 4.11. ACCESS POINTS

Access points were identified through a review of available GIS data, aerial photography and field observation. There are approximately 47 access points along River Pines Road and North Avenue. The vast majority of the access points are private approaches. There are 10 public approaches along these two segments within the study area. The prevalence of access points along a roadway can contribute to decreased safety as turning movements into and out of the access points may create conflict points. On high volume roadways it is generally desirable to attempt access management to reduce conflict points caused by turning traffic. Depending on the type of improvement options identified through this study, access management may be considered for some facilities within the vicinity of the Maclay Bridge.

**Table 17** provides a summary of access points along River Pines Road and North Avenue.

#### Table 17: Access Points

	Distance (mi)	Public	Private	Access / mi	
North Ave W	Clements Rd to Maclay Bridge	0.78	7	31	48.7
River Pines Rd Maclay Bridge to Blue Mountain Road		0.67	3	6	13.4
	Total	1.45	10	37	32.4

Source: Estimated based on aerial photography

## 4.12. RIGHT-OF-WAY

Existing right-of-way widths along River Pines Road and North Avenue are between 60 and 80 feet. New right-of-way, easements and/or construction permits from adjoining landowners will be required if improvement options extend beyond existing right-of-way limits based on legal land survey.

Also, a Montana Department of Natural Resources and Conservation (DNRC) land use license or easement would be required between the low water marks of the river for improvement options involving the construction of a bridge at a new location.

## 4.13. HYDRAULICS

The Bitterroot River is the primary surface water feature within the study area. Any improvement option(s) identified will require an assessment of impacts to the Bitterroot River. If a project is developed that impacts the Bitterroot River, mitigation will be required depending on the type of impacts and permitting

requirements. Although the Bitterroot River joins the Clark Fork River about 3,500 feet downstream from the bridge, it is unlikely any potential improvement options would affect the Clark Fork River. O'Brien Creek parallels River Pines Road and joins the Bitterroot River southwest of the existing bridge. A section of O'Brien Creek was recently restored by Montana Fish Wildlife & Parks (MFWP).

The Big Flat Irrigation Ditch crosses River Pines Road west of the Maclay Bridge and could be impacted depending of the type of improvement options identified through this study. A small Missoula Irrigation District ditch parallels South Avenue and the ditch crosses South Avenue west of Humble Road and west of Clements Road.

## 4.13.1. Floodplain Considerations

The Maclay Bridge is located within a detailed delineated floodplain (FIRM panel 30063C1455). Accordingly, any bridge rehabilitation, reconstruction, or relocation would require a formal floodplain permit. There may be concerns pertinent to increases to the Flood Insurance Study (FIS) 100-year flood elevation. Missoula County floodplain regulations require the low chord of any "new" bridge to be 2 feet above the 100-year flood elevation. At its present North Avenue location, this would likely necessitate the bridge and associated road grade, to be raised. The existing bridge in its present condition would not be subject to the "no increase" requirement. This discussion is relevant for a future reconstruction or relocation option, and not applicable to a rehabilitation option.

Any identified improvement options, would need to be developed and analyzed to ensure impacts to the floodplain and river would be minimized. However, Federal Emergency Management Agency (FEMA) regulations require that if a project results in an increase of the published base flood elevation, a conditional letter of map revision (CLOMR) must be approved.

A CLOMR requires that FEMA approve the hydraulic model and revisions to the base flood elevation. A detailed floodplain model would be required to determine the proposed bridge opening and the effect on the base floodplain elevation. The existing FIS model would be obtained and used, however some new river cross sections would be required. This process can take a year or more.

## 4.13.2. Preliminary Hydrology

The Bitterroot River at the Maclay Bridge drains 2,814 square miles of area and consists mostly of forested mountainous terrain within a wide populated valley. The design flood for a reconstruction or relocation improvement option would likely be the 100-year event due to the delineated floodplain and the risk to adjacent landowners. The 10, 50 and 500 year floods would also need to be modeled to meet CLOMR requirements. **Table 18** contains preliminary hydrology values as computed by MDT. This information is useful to identify general "order of magnitude" flows and compare the published FIS values against USGS calculated results.

Source	Area (sq mi)	Q2 (cfs)	Q5 (cfs)	Q10 (cfs)	Q25 (cfs)	Q50 (cfs)	Q100 (cfs)	Q500 (cfs)
USGS <sup>(a)</sup>	2,814	14,500	20,000	23,400	27,300	30,000	32,500	38,000
FIS <sup>(b)</sup>	2,842			20,900		29,700	31,800	42,000

#### **Table 18: Preliminary Hydrology for Bitterroot River**

<sup>(a)</sup> USGS gage number 12352500

<sup>(b)</sup> The Flood Insurance Study (FIS) flows would likely be used for future design // Q = Flood flow in cubic feet per second (cfs)

## 4.13.3. Channel Characteristics

The Bitterroot River is meandering near the existing bridge, even though aerial photographs show that the banks have moved very little since the 1976 flood event, which was considered a historic flood year across Montana. The existing bridge has washed out at least two times since 1935. River Pines Road, located on the west side of the Bitterroot River, has rock riprap on its fill slope for approximately 750 feet upstream of the bridge. The FIS shows a 5-foot deep scour hole at the bridge, and about a foot of backwater for the base flood. Based on review of four aerial photographs from the years 1935 and 1961 (USFS), and 2003 and 2011 (USDA), it appears the scour hole has grown westward towards the west bank of the river. Scour holes can develop for a variety of reasons (i.e. poor angle of attack of the stream on the bridge, inadequate waterway opening under the bridge, etc.) and are of concern in that scour holes can eventually reach the bottom of footings and undermine bridge supports (columns and/or abutments). Channel scour was not part of the original design in the 1940's, and the existing bridge piers are located in the river channel on unknown materials.

Gravel and sand bar development has been observed but not adequately studied both upstream and below the existing bridge. It appears the channel has been altered with the deposition of material upstream of the bridge (changing the shape of the channel changes stream flow). Increased water velocities also remove material from the stream bed. If too much material is washed away, the piers in the channel may become unstable.

Backwater is a concern as it can flood adjacent properties and change the flow regime just upstream of the bridge. There is a large island upstream from the existing bridge that has been there for a long time due to the size of the trees. Ice is considered to be light and debris is moderate at this location on the Bitterroot River. Although not properly studied, it appears that the existing bridge configuration has constricted the Bitterroot River when compared to its normal, free flow natural state. If a project is developed, this should be analyzed via detailed hydrologic and hydraulic modeling effort at some future time, if a project is developed.

## 4.14. TRANSIT SERVICE

Transit service is currently provided by Mountain Line Transit via Route 9, which travels within the study area along South Avenue, Clements Road and Seventh Street, but does not cross the Maclay Bridge.

## 4.15. UTILITIES

The existing Maclay Bridge carries an eight-inch natural gas line. There are overhead utility lines along the south side of South Avenue and along River Pines Road. There are also buried phone lines along both roads. Near the easterly bridge approach, there is a NorthWestern Energy natural gas substation that serves as a primary feeder hub for gas facilities on both sides of the Bitterroot River.

# **5.0 ENVIRONMENTAL SETTING**

This section provides a summary of the *Environmental Scan*. The primary objective of the Environmental Scan is to determine the potential constraints and opportunities within the Environmental Scan boundary. As a planning level scan, the information is obtained from various reports, websites and other documentation. This scan is not a detailed environmental investigation. Refer to the Environmental Scan for more detailed information.

## 5.1. GEOGRAPHIC SETTING

The Maclay Bridge is located at the western end of the Missoula Valley at the confluence of the Clark Fork and Bitterroot Rivers and encompasses lands in both the City of Missoula and Missoula County, Montana. The topography east of the Bitterroot River is generally level, while the area west of the Bitterroot River is comprised of foothills for the Bitterroot Mountains. Surface elevations over most of the area average about 3,120 feet above sea level with elevations exceeding 3,500 feet in the McCauley Butte area and in foothill areas.

## 5.1.1. Land Ownership and Land Management

Most of the lands in the vicinity of the Maclay Bridge are privately owned with the exception of the Kelly Island Fishing Access Site, located near the confluence of the Clark Fork and Bitterroot Rivers, which is state-owned and managed by the MFWP. Some county-owned parcels and Lolo National Forest lands also exist in the area. Both the Five Valleys Land Trust and Rocky Mountain Elk Foundation hold conservation easements on some private lands within the general vicinity.

## 5.1.2. Land Use

Land use in the area consists mostly of suburban residential properties on one-half acre or larger parcels, a few commercial uses, two schools and recreational/open spaces. The area also contains agricultural uses on irrigated lands ranging in size from one acre to 50 acres.

## **5.2. PHYSICAL RESOURCES**

## 5.2.1. Geologic Resources

According to Montana Bureau of Mines and Geology mapping, the area contains alluvial materials associated with modern channels and floodplains along with glacial lake deposits and volcanic bedrock in some portions. The foothills and mountains in the area are comprised mainly of Precambrian rocks of various formations.

## 5.2.2. Soils and Prime Farmland

Information regarding areas of prime farmland in the area was compiled from the US Department of Agriculture, Natural Resource Conservation Service (NRCS). Using the NRCS's Web Soil Survey website, several soil map units in the area have been classified as prime farmland if irrigated and farmland of local importance.

If a project is advanced using federal or state funds, coordination with the NRCS will be required to determine if the Farmland Protection Policy Act (FPPA) of 1981 (Title 7 United States Code, Chapter 73, Sections 4201-4209) applies and necessary NRCS processing requirements. Projects planned and completed without the assistance of a Federal agency are not subject to the FPPA.

## 5.2.3. Water Resources

#### SURFACE WATERS

Surface waters in the area include the Bitterroot River, the Clark Fork River, and O'Brien Creek. Information on these surface waters within the area was obtained from the Montana Department of Environmental Quality's (MDEQ) website. Section 303, subsection "d" of the Clean Water Act requires the State of Montana develop a list, subject to U.S. Environmental Protection Agency (USEPA) approval, of water bodies that do not meet water quality standards. When water quality fails to meet state water quality standards, MDEQ determines the causes and sources of the pollutants in a sub-basin assessment and sets maximum pollutant levels, called total maximum daily loads (TMDL).

A TMDL sets maximum pollutant levels in a watershed. The TMDLs become the basis for implementation plans to restore the water quality to a level that supports its designated beneficial uses. The implementation plans identify and describe pollutant controls and management measures to be undertaken (such as best management practices), the mechanisms by which the selected measures would be put into action, and the individuals and entities responsible for implementation projects.

The Bitterroot River and the Clark Fork River are both listed as a 303(d) water body within the area. Probable causes of impairment include nutrients, siltation/sediment, and thermal modification.

Placement of fill or excavation within these surface waters would be subject to regulation by the U.S. Army Corps of Engineers (USACOE) under Section 404 of the Clean Water Act and the Montana Stream Protection Act (SPA). Other water-related permits may also be necessary.

#### **IRRIGATION FEATURES**

The area contains irrigation features and infrastructure associated with the Big Flat Irrigation District and the Missoula Irrigation District. Any potential impacts to irrigation facilities will need to be examined to determine if the irrigation facilities are considered waters of the U.S. and subject to jurisdiction by the U.S. Army Corps of Engineers (USACOE) or need approvals from the U.S. Department of the Interior Bureau of Reclamation

### GROUNDWATER

The Missoula aquifer, which most of the urban area population relies on, is a shallow unconfined aquifer formed in coarse alluvial material (sands and gravels) extending from the Clark Fork River at Hellgate Canyon westward across the valley to the Bitterroot River. The Missoula aquifer was designated as a Sole Source Aquifer by the USEPA in 1988. Following the designation, the Missoula Valley Water Quality District was formed in 1993. An Aquifer Protection Ordinance, administered by the Water Quality District, was adopted in 1994.

## 5.2.4. Wetlands

The USACOE defines wetlands as those areas that are inundated or saturated by surface or ground water at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions. Wetlands generally include swamps, marches, bogs, and similar areas.

A wetlands survey was conducted for the Maclay Bridge EA in 1993 which identified riverine and areas of emergent and forested/shrub wetlands along the Bitterroot River. However, this survey is outdated and new wetland impact evaluation must be conducted if a project is forwarded. Wetland impacts should be avoided to the greatest extent practicable. All unavoidable wetland impacts would need to be mitigated as required by the USACOE.

## 5.2.5. Floodplains (EO 11988) and Floodways

Executive Order (EO) 11988, Floodplain Management, requires federal agencies to avoid direct or indirect support of floodplain development whenever a practicable alternative exists. EO 11988 and 23 CFR 650 Part A requires an evaluation of project alternatives to determine the extent of any encroachment into the base floodplain. The base flood (100-year flood) is the regulatory standard used by federal agencies and most states to administer floodplain management programs. A "floodplain" is defined as lowland and relatively flat areas adjoining inland and coastal waters, including flood-prone

areas of offshore islands, with a one percent or greater chance of flooding in a given year. As described in the Federal Highways Administration's (FHWA) floodplain regulation (23 CFR 650 Part A), floodplains provide natural and beneficial values serving as areas for fish, wildlife, plants, open space, natural flood moderation, water quality maintenance, and groundwater recharge.

A FEMA delineated floodplain exists along the Bitterroot and Clark Fork Rivers in the Maclay Bridge area.

## 5.2.6. Hazardous Material

The Montana Natural Resource Information System (NRIS) database was searched for underground storage tank (UST) sites, leaking underground storage tank (LUST) sites, abandoned mine sites, remediation response sites, landfills, National Priority List (NPL) sites, hazardous waste, crude oil pipelines, and toxic release inventory sites in the area.

The following sites where initially identified as locations with potential contamination impacts:

- Eight underground storage tank locations;
- One leaking underground storage tank locations; and
- One petroleum release compensation site.

Further evaluation may be needed at specific sites to determine the potential for encountering contamination if a project requiring soil excavation is forwarded. This evaluation may include reviewing MDEQ files for specific sites and/or conducting subsurface investigation activities to determine the extent of soil and groundwater contamination at locations of interest. If contaminated soils or groundwater is encountered during construction, handling and disposing of the contaminated material would need to be conducted in accordance with State, Federal, and local laws and rules.

## 5.2.7. Air Quality

EPA designates communities that do not meet National Ambient Air Quality Standards (NAAQS) as "nonattainment areas". "Nonattainment areas" are localities where air pollution levels persistently exceed the NAAQS or MAAQS (Montana Ambient Air Quality Standards), or that contribute to ambient air quality in a nearby area that fails to meet standards. States are then required to develop a plan to control source emissions and ensure future attainment of NAAQS. An area that has been designated as non-attainment in the past, but now complies with the NAAQS is classified as a "maintenance" area.

The Maclay Bridge area is located in a non-attainment area for PM-10 and a maintenance area for carbon monoxide.

Transportation conformity considerations will apply in this area if projects forwarded use federal or state funds to help ensure that any proposed activities will not cause or contribute to any new violations of the NAAQS; increase the frequency or severity of NAAQS violations; or delay timely attainment of the NAAQS or any required interim milestone.

If a project forwarded uses federal of state funds, an evaluation will also be required to determine if there is any potential for Mobile Source Air Toxics Rule (MSAT) effects.

## 5.2.8. Noise

Should a project be advanced with federal or state funds, it will be necessary to establish whether the project is a "Type I Project" as defined in 23 CFR 772.5(h). Type I projects involve:

• Construction of a highway on a new location;

- The physical alteration of an existing highway which significantly changes either the horizontal or vertical alignment or increases the number of through-traffic lanes; or
- The potential for creating a traffic noise impact (e.g., idling vehicles at rest areas, weigh stations).

A detailed noise analysis would be required for a Type I project. If it is determined that the project is not Type I, it is then considered a Type III project which does not require a noise analysis or consideration of noise abatement. Type II projects are retrofit noise abatement projects.

If a project is forwarded, future construction activities may cause localized, short-duration noise impacts. These impacts would need to be.

## **5.3. VISUAL RESOURCES**

Visual resources refer to the landscape character (what is seen), visual sensitivity (human preferences and values regarding what is seen), scenic integrity (degree of intactness and wholeness in landscape character), and landscape visibility (relative distance of seen areas) of a geographically defined view shed. The landscape throughout the area contains an array of biological, scientific, historic, wildlife, ecological, and cultural resources mixed with a remote location.

The Bitterroot River riparian corridor, the Kelly Island Fishing Access Site, Lolo National Forest land, and a large conservation easement in the McCauley Butte area provide areas of natural open space and add to the visual resources present in the area.

## 5.4. BIOLOGICAL RESOURCES

Existing information on wildlife, fisheries and special status species known to occur or that may potentially occur in the area was reviewed from a variety of sources including the U.S. Fish and Wildlife Service (USFWS), the MFWP, the Montana Natural Heritage Program (MNHP), and other resource documents. This limited survey is in not intended to be a complete and accurate biological survey of the study area. A complete biological survey of the area would be needed before potential selection of a specific project site, if a project is forwarded.

## 5.4.1. Wildlife and Fish

General fish and wildlife resources would need to be surveyed during any future project development process. MFWP should be contacted during the project development process for local expertise regarding the wildlife and fisheries resources of the area. If a project is forwarded from the improvement option(s), encroachment into the waterway and the associated riparian habitat should be minimized to the extent practicable.

## WILDLIFE RESOURCES

The most common forms of wildlife found on the developed lands in the area include species adapted to suburban life and some level of human disturbance as well as other species that make use of river and its riparian areas as permanent habitat and movement corridors. These include mule and white-tailed deer, small mammals (like coyote, red fox, squirrels, raccoons, skunks, beaver, mink), and a variety of rodents. Additionally, there are areas of winter range for elk, mule deer, and white-tailed deer located in the mountains and foothills in the area. Other species like moose, black bear, and mountain lion may occasionally pass through the riparian corridors and forested lands in the area.

Numerous species of birds occur in this portion of the Missoula area including ospreys, sandhill cranes, wild turkey, ringed-neck pheasant, a variety of raptors (osprey, bald eagles, falcons, and hawks), owls,

woodpeckers, migratory waterfowl, and many neo-tropical migratory birds (flycatchers, warblers, vireos, grosbeaks, and orioles).

Amphibians and reptiles occurring in the area include spotted frog, leopard frog, bull frog, western yellowbellied racer, western garter snake, and western painted turtle.

#### **AQUATIC RESOURCES**

The major surface waters found within the area include the Bitterroot River, Clark Fork River, O'Brien Creek, and the Big Flat Ditch. All of these waters, except for the Big Flat Ditch, are managed as fisheries by the MFWP. The Bitterroot and Clark Fork Rivers have been rated as Outstanding for their fisheries resource value by MFWP. Both streams receive recreational angler use year-round for sport fishing although restrictions exist relative to fishing for certain species. O'Brien Creek has a Moderate rating for its fisheries resource value and is open to use by anglers on a seasonal basis.

According to maps developed by the USFWS, the Bitterroot and Clark Fork Rivers and O'Brien Creek are designated as Bull Trout Critical Habitat (BTCH).

## 5.4.2. Threatened and Endangered Wildlife Species

The federal list of endangered and threatened species is maintained by the USFWS. Species on this list receive protection under the Endangered Species Act (ESA). An 'endangered' species is one that is in danger of extinction throughout all of a significant portion of its range. A 'threatened' species is one that is likely to become endangered within the foreseeable future throughout all or a significant portion of its range. The USFWS also maintains a list of species that are candidates or proposed for possible addition to the federal list.

The endangered, threatened, proposed, and candidate species list for Montana Counties (March 2012) was obtained from the USFWS website. This list generally identifies the counties where one would reasonably expect the species to occur, not necessarily every county where the species is listed. **Table 19** shows the listed species that could potentially occur within Missoula County and provides information about habitats where these species typically occur.

Common Name	Scientific Name	USFWS Status	Habitat Requirements
Bull Trout	Salvelinus confluentus	Threatened, Critical Habitat Designated	Bull trout are found in the Clark Fork and Flathead drainages of western Montana. Sub-adult and adult fluvial bull trout reside in larger streams and rivers and spawn in smaller tributary streams, whereas adfluvial bull trout reside in lakes and spawn in tributaries. Within the Maclay Bridge area, the Bitterroot River, Clark Fork River, and O'Brien Creek are designated as Critical Habitat for bull trout.
Grizzly Bear	Ursus arctos horribilus	Threatened	In Montana, Grizzly Bears primarily use meadows, seeps, riparian zones, mixed shrub fields, closed timber, open timber, sidehill parks, snow chutes, and alpine slabrock habitats. Grizzly bear habitat and recovery zones in Missoula County include the Seeley, Swan, and Jocko Valleys, lower Mission Valley, and portions of the upper Rattlesnake watershed.
Canada Lynx	Lynx Canadensis	Threatened, Critical Habitat Designated	West of the Divide, Canada Lynx generally occur in subalpine forests at elevations between 4,000 to 7,000 feet in stands composed of pure lodgepole pine but also mixed stands of fir, pine, larch, and hardwoods. Habitat for the species does not exist in the Maclay Bridge area.
Wolverine	Gulo gulo luscus	Candidate	Wolverines live in remote and inhospitable places away from human populations. In the northern Rocky Mountains, wolverines are restricted to high mountain environments near the treeline, where conditions are cold year-round and snow cover persists well into the month of May. Habitat for the species does not exist in the Maclay Bridge area.
Yellow Billed Cuckoo (Western Population)	Coccyzus americanus	Candidate	Western cuckoos breed in large blocks of riparian habitats, particularly woodlands with cottonwoods and willows. This candidate species requires patches of at least 25 acres of dense, riparian forest with a canopy cover. This habitat may be present in the Maclay Bridge area.

## Table 19: USFWS Endangered, Threatened, Proposed, and Candidate Wildlife Species

Source: USFWS, List of Endangered, Threatened, Proposed and Candidate Species Montana Counties.

An evaluation of potential impacts to all endangered, threatened, proposed, or candidate species will need to be completed during the project development process.

## 5.4.3. Montana Animal Species of Concern

Wildlife species of concern are native Montana animals that are considered to be "at risk" due to declining population trends, threats to their habitats, and/or restricted distribution. Designation of a species as a Montana Animal Species of Concern (or Potential Species of Concern) is not a statutory or regulatory classification. The designation as a Species of Concern provides a basis for resource managers and decision-makers to make proactive decisions regarding species conservation and data collection priorities. Each Species of Concern is assigned a state numeric rank ranging from S1 (highest risk, greatest concern) to S5 (demonstrably secure, least concern) reflecting the degree of risk to each species based on available information. Other state ranks applied to Species of Concern include: SU (unrankable due to insufficient information), SH (historically occurred), and SX (believed to be extinct). State ranks may be followed by modifiers, such as B (breeding), N (non-breeding), or M (migratory).

**Table 20** lists the animal species of special concern by the Montana Heritage Program in the study area. The results of the data search reflect the current status of their data collection efforts. These results are not intended as a final statement on sensitive species within a given area, or as a substitute for on-site surveys. If a project is forwarded from the improvement option(s), on-site surveys will need to be completed during the project development process.

Common Name	Scientific Name	State Rank	MNHP Occurrences in General Area by Township and Range	MNHP Known Occurrences in Maclay Bridge Area
Westslope Cutthroat Trout	Oncorhynchus clarkia lewisi	S2	T13N, R20W T12N, R20W	Yes
Hoary Bat	Laslurus cinereus	S3	T13N, R20W T12N, R20W	Yes
Fisher	Martes pennanti	S3	T13N, R20W	Possible on Lolo National Forest
Black-backed Woodpecker	Picoides arcticus	S3	T13N, R20W T12N, R20W	Yes
Western Skink	Eumeces skiltonianus	S3	T13N, R20W	Yes
Fringed Myotis	Myotis thysanodes	S3	T12N, R20W	Yes
Grasshopper Sparrow	Ammodramus savannarum	S3B	T12N, R20W	Yes
Cassin's Finch	Carpodacys cassinii	S3	T12N, R20W	Yes
Pileated Woodpecker	Dryocopus pileatus	S3	T12N, R20W	Yes
Lewis's Woodpecker	Melanerpes lewis	S2B	T12N, R20W	Yes
Flammulated Owl	Otus flammeolus	S3B	T12N, R20W	No
Bald Eagle	Halieetus leucocephalus		T13N, R20W T12N, R20W	Yes
Great Blue Heron	Ardea herodias	S3	T13N, R20W T12N, R20W	Yes

#### **Table 20: Montana Animal Species of Concern**

Source: Montana Natural Heritage Program, Animal and Plant Species of Concern Searchable Database.

## 5.4.4. Vegetation

This portion of the Missoula Valley contains isolated remnants of native vegetation. Areas of native dry grasslands, open ponderosa pine forest, and riparian deciduous forests and associated wetlands exist along the Bitterroot and Clark Fork Rivers. Vegetation in developed areas consists of ornamental trees and shrubs, lawns, and flowerbeds associated with residential landscapes. The area also contains areas of cultivated lands.

#### THREATENED AND ENDANGERED PLANT SPECIES

The online database of threatened, endangered, proposed, and candidate plant species maintained by the USFWS identifies two plants—Water Howellia and Whitebark Pine—as potentially occurring in Missoula County. Water Howellia is a threatened plant species and the Whitebark Pine is a candidate species for listing. **Table 21** presents habitat requirements for each of these species. Known occurrences and habitat requirements suggest these plants are unlikely to occur in the area.

Common Name	Scientific Name	USFWS Status	Habitat Requirements
Water Howellia	Howellia aquaticus	Threatened	Water howellia is a winter annual aquatic plant that grows in small, vernal, freshwater wetlands that have an annual cycle of filling up with water over the fall, winter and early spring, followed by drying during the summer. The wetlands typically consist of small shallow ponds within a matrix of forest vegetation and are usually bordered in part by deciduous trees. Known occurrences of the species in Montana are all within the Swan River drainage in the northeastern portion of Missoula County.
Whitebark Pine	Pinus albicaulis	Candidate	Whitebark pine typically occurs in isolated stands on cold and windy high-elevation or high-latitude sites in western North America. This habitat does not exist in the Maclay Bridge area.

#### Table 21: USFWS Endangered, Threatened, Proposed, and Candidate Plant Species

Source: USFWS, List of Endangered, Threatened, Proposed and Candidate Species Montana Counties.

As with listed wildlife species, consultation with the USFWS will be necessary and an evaluation of potential impacts to all listed, candidate, and proposed plant species must be completed if a project is forwarded.

### PLANT SPECIES OF CONCERN

The file search of the MNHP database lists one plant species of concern—Toothcup (*Rotala ramosior*) in the area. Toothcup is a rare plant identified from only a limited number of wetland sites in western Montana.

The results of the MNHP database search are not intended as a final statement on sensitive species within a given area, or as a substitute for on-site surveys. If a project is forwarded, a determination will need to be made if there is a need for any on-site surveys for plant species of concern during the project development process.

### NOXIOUS WEEDS

Noxious weeds degrade habitat, choke streams, crowd native plants, create fire hazards, poison and injure livestock and humans, and fouls recreation sites. Areas with a history of disturbance are at particular risk of weed encroachment. There are 32 noxious weeds in Montana, as designated by the Montana Statewide Noxious Weed List (effective April 15, 2008). According to the Montana Invaders Database, there are documented occurrences of 20 noxious weed species in Missoula County since 1875. The area will need to be surveyed for noxious weeds. County Weed Control Supervisors should be contacted regarding specific measures for weed control during project development.

## 5.5. CULTURAL AND ARCHAEOLOGICAL RESOURCES

Section 106 of the National Historic Preservation Act (36 CFR 800) establishes requirements for taking into account the effects of proposed Federal, Federally assisted or Federally licensed undertakings on any district, site, building, structure or object included in or eligible for inclusion in the National Register of Historic Places (NRHP).

A Cultural Resources Information System (CRIS) and Cultural Resources Annotated Bibliography (CRABS) file search was conducted for the area. The CRABS file search indicates 26 cultural resource surveys have been conducted on lands within or near the area between 1978 and 2010. The CRIS file search identified 28 recorded properties within the area including one National Register-listed site—the Fort Missoula Complex (24MO0266).

**Table 22** lists the site name (where known), assigned Smithsonian Site Number, resource type, and National Register of Historic Places (NRHP) eligibility status for previously recorded cultural resource sites within the study area. There may be additional unknown cultural sites located within the area have not been identified and recorded.

Resource Name	Smithsonian Site #	Type of Resource	National Register Eligibility Status
Stettler Property	24MO05l6	Historic Residence	Ineligible
Rice Property	24MO05I7	Historic Residence and Outbuildings	Consensus determination of eligibility
Maxwell Property	24MO05l8	Historic Residence and Outbuildings	Ineligible
Maclay Property	24MO0519	Historic Residence and Outbuildings	Recommended as eligible for National Register
Missoula Irrigation District Ditches	24MO0520	Historic Irrigation System	Consensus determination of eligibility
Maclay Bridge	24MO0521	Historic Vehicular/Foot Bridge	Determined eligible for National Register
Big Flat Ditch	24MO0587	Historic Irrigation System	Consensus determination of eligibility
Maclay Ditch	24MO0954	Historic Irrigation System	Undetermined
Target Range Elementary School	24MO0589	Historic School	Listed on the National Register
Site in T13N, R20W, Sec. 35	24MO0209	Lithic Material Concentration	Undetermined
Site in T13N, R20W, NW 1/4 Sec. 35	24MO1388	Historic Residence	Undetermined

#### **Table 22: Summary of Cultural Resources**

Source: Montana Historical Society, CRIS File Search Results, 3/21/2102.

If a project is forwarded from the Planning Study, a cultural resource survey of the Area of Potential Effect (APE) for the project as specified in Section 106 of the National Historic Preservation Act would need to be conducted. Section 106 outlines a process to identify historic properties that could be affected by the undertaking, assess the effects of the project and investigate methods to avoid, minimize or mitigate any adverse effects on previously recorded and newly discovered historic or archaeological resources.

## 5.5.1. 4(f) Resources

A review was conducted to determine the presence of Section 4(f) properties along the corridor. Section 4(f) refers to the original section within the Department of Transportation Act of 1966 (49 U.S.C. 303), which sets the requirements for consideration of park and recreational lands, wildlife and waterfowl refuges, and historic sites in transportation project development. **Table 23** lists resources within the Maclay Bridge area that may potentially be subject to Section 4(f). A graphic showing 4(f) resources is included in the Environmental Scan, a separate document prepared for the Maclay Bridge Planning Study.

Table 23: St	ummary of	Potential	Section	<b>4(f)</b>	Resources
--------------	-----------	-----------	---------	-------------	-----------

Name	Type of 4(f) Resource	Comments /Location
Kelly Island FAS	Public Recreation Site	666-acre site located at confluence of Bitterroot and Clark Fork Rivers, owned and managed by MFWP
Rosecrest Park <sup>(a)</sup>	Neighborhood Park	9.6 acres located south Spurgin Road between Clement Road and 37th Avenue. County ownership
Schmautz Park <sup>(a)</sup>	Neighborhood Park	4.2 acres, undeveloped parcel located north of North Avenue and west of 42nd Avenue. County ownership
Target Range School Playground Target Range School (24MO0589)	Neighborhood Park Historic School	10-acre area containing sports fields, basketball courts, and play equipment. Target Range School is listed on National Register.
Dinsmore River Four	Conservation Park	Bitterroot River island habitat located south of existing Maclay Bridge County ownership
Double R Acres	Conservation Park	Clark Fork River riparian habitat adjoining Kelly Island FAS. County ownership
O'Brien Cr. Meadows Common Area	Conservation Park	O'Brien Creek riparian area located near intersection of Big Flat Road and O'Brien Creek Road. County ownership. Identified in Missoula County Parks and Conservation Lands Plan (1997)
Capi Court Park <sup>(a)</sup>	Unimproved County Park	North of Spurgin Road and east of Sierra Drive
Five Valley Land Trust Conservation Easements	Wildlife Habitat/Public Use	Various locations along Bitterroot River
Lolo National Forest Lands	Public Multiple-use Property	South and west of Maclay Bridge area, part of Blue Mountain Recreation Area
Rice Property (24MO05I7)	Historic Residence and Outbuildings	Consensus determination of eligibility for National Register
Maclay Property (24MO05I9)	Historic Residence and Outbuildings	Recommended as eligible for National Register
Maclay Bridge (24MO052I)	Historic Vehicular/Foot Bridge	Determined eligible for National Register. Owned by Missoula County
Big Flat Ditch (24MO0587) Missoula Irrigation District Ditches (24MO0520)	Historic Irrigation Systems	Consensus determination of eligibility for National Register

Sources: 1) Montana Historical Society, CRIS File Search Results, 3/21/2102; 2) Missoula County Parks and Conservation Lands Plan, 1997.; 3) Missoula County, Final Draft Parks and Trails Master Plan, 2012.

<sup>(a)</sup> Capi Court, Rosecrest Park, and Schmautz Park are county parks that are the result of subdivision park and open spaces requirements from the Missoula County Subdivision Regulations, section 3-080.

Prior to approving a project that "uses" a Section 4(f) resource, FHWA must find that there is no prudent or feasible alternative that completely avoids 4(f) resources. "Use" can occur when land is permanently incorporated into a transportation facility or when there is a temporary occupancy of the land that is adverse to a 4(f) resource. Constructive "use" can also occur when a project's proximity impacts are so severe that the protected activities, features, or attributes that qualify a resource for protection under 4(f) are "substantially impacted".

Section 4(f) does not apply to projects that do not use federal transportation funding.

## 5.5.2. 6(f) Resources

Section 6(f) of the Land and Water Conservation Fund Act (LWCF) (16USC, Section 4601 et. seq.) provides funds for buying or developing public use recreational lands through grants to local and state governments. Section 6(f)(3) of the Act prevents conversion of lands purchased or developed with LWCF funds to non-recreation uses, unless the Secretary of the Department of Interior (DOI), through the National Park Service (NPS), approves the conversion.

A review of the LWCF grants in Missoula County maintained by MFWP shows that Kelly Island Fishing Access Site (FAS) is the only property in the area acquired/improved under Section 6(f) of the LWCF.

# 6.0 CONCLUSION

This section provides a list and description of areas of concern and other consideration within the vicinity of the Maclay Bridge. These areas were identified through review of available reports, field review, public databases, and other resources.

## 6.1. TRANSPORTATION SYSTEM

The following transportation system areas of concern were noted:

## Traffic Volumes

• Existing and projected traffic volumes (2,610 vpd and 5,650 vpd, respectively) exceed the AASHTO standard for a single-lane bridge (traffic volume < 100 vpd).

## <u>Safety</u>

- A number of crash trends and areas of concern were identified within the crash analysis area. Specific areas of concern identified are located on the following roadways:
  - Big Flat Road
  - Blue Mountain Road
  - > North Avenue
  - River Pines Drive
  - South Avenue

### Travel Time

- Without the existing Maclay Bridge in service, it would be expected to take approximately 18.58
  minutes longer using the Kona Bridge or 4.47 minutes longer using the Buckhouse Bridge when
  travelling between Community Medical Hospital to the intersection of Big Flat Road/Blue
  Mountain Road/O'Brien Creek Road/River Pines Road. In terms of emergency service, this
  means that travel times would likely be longer if the Maclay Bridge is out of service.
  - Any delay in emergency response travel time, typically measured in seconds, is an important consideration within the planning area. Comments provided by the Missoula Rural Fire Department state that 5 minutes or more are added to their response times when using the Buckhouse Bridge in lieu of the Maclay Bridge.

#### Horizontal Alignment

- Three horizontal curves do not meet current Missoula County or MDT standards.
  - Two of the sub-standard horizontal curves lead into and out of each side of the existing bridge.
  - A crash trend has been identified at the west end of the bridge (intersection of River Pines Road & Riverside Drive).

## **Clear Zones**

• Numerous locations have features within the horizontal clear zone and are unprotected. Primary concern is located along River Pines Road adjacent to the Bitterroot River, where the top of fill slope is within 2 to 4 feet of the edge of the travel lane.

#### **Bridge**

- The existing bridge is "functionally obsolete" due to the approach geometry on both ends of the bridge, and the narrow single lane bridge width.
- The existing bridge is "load restricted" due to its present condition, which prevents some vehicles from crossing.
- The Maclay Bridge has a Bridge Health Index that suggests its individual components are in good condition.
- The Maclay Bridge is fracture critical, indicating if one part of the truss should fail, the entire bridge span may fail. With proper inspection and maintenance, the bridge is considered safe.
- There are no bicycle or pedestrian features on the bridge.
- The current structure exhibits spalling and cracked concrete and exposed rebar.
- Rust and steel pitting is observed under the bridge on some load bearing members and the deck.
- The bridge is a composite of varying ages and types of load-bearing steel used throughout the structure.
- The strength of the steel is unknown in much of the bridge, as it has never been tested.
- Channel scour was not part of the original design in the 1940's, and the existing bridge piers are located in the river channel on unknown materials.

### Parking

• Parking concerns are evident based on numerous resolutions passed by the Missoula County Commission, and also based on numerous "911 calls" to the area.

#### <u>Widths</u>

- The single lane bridge width of 14 feet does not meet current AASHTO, Missoula County or MDT standards for width given existing and projected traffic volumes.
- Roadway widths on River Pines Road do not incorporate shoulders.
- Bicycle and pedestrian facilities are absent on River Pines Road.

## 6.2. Environmental Considerations Within Environmental Scan Boundary

The following environmental considerations were noted. They are referenced herein for completeness, and do not necessarily point to a defined area of concern. In some instances, the included language is intended to bring attention to unique permitting requirements if and when a project is developed. Environmental considerations are more fully described in the Environmental Scan document, a separate memorandum prepared as part of the Maclay Bridge Planning Study.

#### Prime Farmland

• Areas of prime farmland, farmland of statewide importance, and farmland of local importance are located within the area.

#### Water Resources

- The Bitterroot River, Clark Fork River, and O'Brien Creek are located within the area. The Bitterroot River and Clark Fork River are listed as 303(d) water bodies, which do not meet water quality standards.
- Irrigation facilities exist within the area.
- Numerous private groundwater wells are in the area, along with on-site wastewater systems.

#### **Wetlands**

• Wetlands are located within the area.

#### Floodplains and Floodway

- FEMA-delineated floodplains exist along the Bitterroot and Clark Fork Rivers, and at the confluence of O'Brien Creek and the Bitterroot River.
- Missoula County would have a "no increase" requirement for the 100-year base flood elevation measured against the existing FEMA base flood elevations.
- Based on field review, it appears that the existing bridge configuration has constricted the Bitterroot River when compared to its normal, free flow natural state. This should be analyzed via detailed hydrologic and hydraulic modeling effort at some future time, if a project is developed.
- Although not properly studied, it appears the Bitterroot River channel has been altered with the deposition of material upstream of the bridge.
- Although not properly studied, it appears that increased water velocities have removed material from the stream bed. If too much material is washed away, the piers in the channel may become unstable.
- Based on an initial review, but not properly studied, of four aerial photographs from the years 1935 and 1961 (USFS), and 2003 and 2011 (USDA), it appears the scour hole has grown westward towards the west bank of the river.

#### Hazardous Substances

- There are eight underground storage tank (UST) locations.
- There is one leaking underground storage tank (LUST) location.
- There is one petroleum release compensation site.

#### Air Quality

• Transportation conformity analysis would be required regardless of funding sources, via the MPO's regional emissions analysis, should an improvement option be forwarded.

#### Fish and Wildlife

- Five endangered, threatened, proposed, or candidate species are listed for Missoula County. Of the five, two may be likely to occur within the area. These are the Bull Trout (threatened, critical habitat designated) and the Yellow Billed Cuckoo (candidate species).
- 13 animal species of concern are listed for Missoula County.

#### Vegetation

- No endangered, threatened, proposed, or candidate plant species are expected to occur within the area.
- One plant species of concern may potentially be found within the area Toothcup (Rotala ramosior).

#### Cultural and Archaeological Resources

- Eleven separate cultural resources are known to exist within the area.
- Fourteen 4(f) resources are located within the area. One of the fourteen is also a 6(f) site.

## **6.3. OTHER CONSIDERATIONS**

The following other considerations were noted:

#### Neighborhood residents have expressed concern over:

- Speeds being an issue on North Avenue, River Pines Road and South Avenue.
- <u>Traffic Growth</u> through the neighborhood in recent years, and the potential for that to continue.
- <u>Safety</u> and the potential for increased vehicle crashes.
- Noise impacts due to increasing vehicular traffic through the area.
- <u>Livability</u> and the desire to maintain the rural character of the area and limit traffic growth.
  - The Target Range Neighborhood Plan emphasizes the importance of continued County maintenance of the structure to help preserve access for local and Missoula Valley residents seeking recreational opportunities on nearby lands.
  - > The Target Range Neighborhood Plan does not identify the need for a new bridge.
- <u>Unreported behavior related to individuals jumping off the bridge structure and/or recreating on the river islands, sand bars, and bridge scour hole.</u>

#### **Project Nomination**

• Missoula County has nominated the existing Maclay Bridge for replacement using funding from FHWA's Off-System Bridge Program (formerly known as the *Highway Bridge Replacement and Rehabilitation Program*), pending the outcome of this planning study.







PHOTO 1: LOOKING SOUTHWEST - RIVER PINES ROAD (NOTE POSTED SPEED LIMIT OF 35 MPH)



PHOTO 2: LOOKING NORTHEAST – UPSTREAM FACE OF EXISTING BRIDGE



PHOTO 3: LOOKING SOUTHEAST ON ALIGNMENT – 14 TON POSTED WEIGHT LIMIT WAS REDUCED TO 11 TONS AFTER THIS IMAGE WAS TAKEN



PHOTO 4: LOOKING NORTHEAST – UPSTREAM FACE OF EXISTING BRIDGE



PHOTO 5: LOOKING SOUTHEAST ON NORTH AVENUE – AFTER CROSSING THE EXISTING BRIDGE



PHOTO 6: LOOKING NORTHWEST ON ALIGNMENT – 14 TON POSTED WEIGHT LIMIT WAS REDUCED TO 11 TONS AFTER THIS IMAGE WAS TAKEN



PHOTO 7: LOOKING WEST - NOTE RIPRAP ARMORED FILL SLOPE ON RIVER PINES ROAD



PHOTO 8: LOOKING WEST FROM EAST BANK OF BITTERROOT RIVER



PHOTO 9: NORTHWESTERN ENERGY NATURAL GAS SUBSTATION – ON SOUTH SIDE OF NORTH AVENUE JUST BEFORE CROSSING EXISTING BRIDGE



PHOTO 10: PERMIT AREA PARKING SIGNS ARE PREVALENT ALONG MANY ROADWAYS PER VARIOUS MISSOULA COUNTY PARKING RESOLUTIONS



PHOTO 11: LOOKING NORTHWEST ON ALIGNMENT AS TRUCK TRAVERSES EXISTING BRIDGE – 14 TON POSTED WEIGHT LIMIT WAS REDUCED TO 11 TONS AFTER THIS IMAGE WAS TAKEN



PHOTO 12: LOOKING EAST ON RIVER PINES ROAD AT HORIZONTAL CURVE



PHOTO 13: LOOKING SOUTHWEST ALONG RIVER PINES ROAD – NOTE RIPRAP ARMORING ALONG FILL SLOPE AND POWER POLE NEXT TO ROADWAY



PHOTO 14: LOOKING WEST FROM NORTH AVENUE - NOTE 11 TON POSTED WEIGHT LIMIT




PHOTO 15: LOOKING EAST ALONG NORTH AVENUE – NOTE WIDE SHOULDER ON SOUTH SIDE (RIGHT) FOR PEDESTRIANS/BICYCLES



PHOTO 16: AFTER THE POSTED WEIGHT LIMIT WAS REDUCED FROM 14 TO 11 TONS, NEW SIGNS WERE PLACED AT VARIOUS LOCATIONS



PHOTO 17: BICYCLIST ON RIVER PINES ROAD TRAVELLING SOUTHWEST IN DRIVING LANE



PHOTO 18: LOOKING WEST THROUGH THE INTERSECTION OF NORTH AVENUE AND HUMBLE ROAD




PHOTO 19: LOOKING WEST THROUGH THE INTERSECTION OF NORTH AVENUE AND HUMBLE ROAD



PHOTO 20: DEGRADED JOINT BETWEEN TWO CONCRETE SPANS (NOTE HIGH PRESSURE NATURAL GAS LINE)



PHOTO 21: EXPOSED RUSTED REBAR AND CONCRETE SPALLING (ON EAST BRIDGE ABUTMENT)



PHOTO 22: MISSING GROUT AND SKEWED JOINT (EAST BRIDGE SPAN)



PHOTO 23: BROKEN CONCRETE, EXPOSED RUSTING REBAR, AND WOODEN SHIM (UNDER EAST SPAN)



PHOTO 24: WOODEN SHIM UNDER CONCRETE SPAN



**PHOTO 25: CRACKS IN CONCRETE PIER** 



PHOTO 26: CLOSE UP OF CRACKS IN CONCRETE PIER



PHOTO 27: RUST ON STEEL MEMBERS (UNDER THE BRIDGE)



PHOTO 28: STEEL MEMBERS OF VARYING AGES AND CONDITION



# APPENDIX B MACLAY BRIDGE INSPECTION REPORT



## INITIAL ASSESSMENT FORM FOR STRUCTURE :

#### L32101000+01001

Location : W MISSOULA Structure Name: LB-01 MACLAY BRIDGE

General Location Data	
District Code, Number, Location : 01 Dist 1 MISSOULA	Division Code, Location :11 MISSOULA
County Code, Location : 063 MISSOULA	City Code, Location :00000 RURAL AREA
Kind fo Hwy Code, Description : 4 4 County Hwy	Signed Route Number : 32101
Str Owner Code, Description : 2 County Highway Agency	Maintained by Code, Description :2 County Highway Agency
Intersecting Feature : BITTERROOT RIVER 010	Kilometer Post, Mile Post : 0.16 km 0.10
Structure on the State Highway System : Latitude : 46°51'11"	Construction Data
Structure on the National Highway System : Longitude : 114°05'52 Str Meet or Exceed NBIS Bridge Length : X	Construction Project Number : -1 Construction Station Number : 0+00.00
Traffic Data	Construction Drawing Number : RECORDSE
	Construction Year : 1935
Current ADT : 2,774 ADT Count Year : 2006 Percent T	rucks : 3 % Reconstruction Year : 1964

## Structure Loading, Rating and Posting Data

_ L	Dauling Data .						
	Design Loading :		0 Unknown	Rating Data :	Operating	Inventory	Posting
	Inventory Load, Design :	12.7 mton	1 LF Load Factor	Truck 1 Type 3 :	19	11	11
	Operating Load, Design :	20.9 mton	1 LF Load Factor	Truck 2 Type 3-S3 :	29	17	
	Posting :		5 At/Above Legal Loads	Truck 3 Type 3-3 :	37	22	

### Structure, Roadway and Clearance Data

#### Structure Deck, Roadway and Span Data :

Structure Length :105.46 mDeck Area :515.00 m sqDeck Roadway Width :4.27 mApproach Roadway Width :6.10 mMedian Code, Description :0 No median

#### Span Data

Loading Data :

Main Span				
Numb	er Spans : <b>2</b>			
Material Type Code, Description : 3 Steel				
Span Design Code, Description : 10 Truss - Thru				
Deck				
Deck Structure Type :	6 Corrugated Steel			
Deck Surfacing Type :	6 Bituminous			
Deck Protection Type :	0 None			
Deck Membrain Type :	0 None			

#### Structure Vertical and Horizontal Clearance Data :

Vertical Clearance Over the Structure : Reference Feature for Vertical Clearance : Vertical Clearance Under the Structure : Reference Feature for Lateral Underclearance : Minimum Lateral Under Clearance Right : Minimum Lateral Under Clearance Left :

4.32 m N Feature not hwy or RR 0.00 m N Feature not hwy or RR 0.00 m 0.00 m

#### Approach Span

	Number of Spans : 2					
Material Type	Code, Description : 5 Pre	stressed concrete				
Span Design	Code, Description: 4 Tee	e Beam				


## (52) Out-to-Out Width : **4.88 m**



#### Structure Vertical and Horizontal Clearance Data Inventory Route :

•									
Over / Under Direction Name	Inventory Route	South, West or Bi-directional Travel			North or East Travel				
		Direction	Vertical	Horizontal	Direction	Vertical	Horizontal		
Route On Structure	L32101	Both	4.32 m	4.27 m	N/A				
NORTH AVE WEST									

Montana De of Transport	partment ation	NITIAL ASSI	L32101	000+0100	<u>R STRUCTURE :</u> 1	Printing Dat	Page 2 of 15 Form: bms001d e : Monday, June 18 2012
Inspection D Sufficiency Rating : 2 Health Index : 89.91 Structure Status :Fun	27.3	(91) Inspe Next Fract	n Due Date : 3 ction Fequency ure Critical Due critical Detail : \$	/ (months) : <b>24</b> e Date : <b>31 Oc</b>			
NBI Inspection Da							
(90) Date of Last Ins (90) Inspectio	pection : 31 October	2011		La	ast Inspected By :Darrel Reic Inspected By :	ch - 2051	
(58) Deck (59) Superstructure (60) Substructure (72) App Rdwy	Rating : 6	(68) Deck Ge (67) Structure (69) Under Clea (41) Posting	Rating : 4 arance : N	(36A) (36B	proach Rail Rating : N Bridge Rail Rating : 0 ) Transition Rating : 0 D) End Rail Rating : 0	(61) Channe (71) Waterway A	
Inspection Hours Crew Hours for inspec Helper He	ction : 2			oper Required for inspection		g Depth : 2.	00 in
Special Crew He Special Equipment He	- 1			Flagger Hours	-1		
Inspection Worl Candidate ID		Status	Priority	Effected Structure Unit	Scope of Work	Action	Covered Condition States
D11-FY2003-000007			Low	All Spans	311 Moveable Bearing	Rehab Elem	X X X X X
Clean wet soil and moss Still needs maintenance 09' still Same for 2011 inspectio	work performed 2		irea on West e	nd of main spa	n 1 truss, see pic		




# L32101000+01001

Continue


#### **Element Inspection Data**

\*\*\*\*\*\*\*\*\*\*\*\* Span : Main-0 - -1 \*\*\*\*\*\*\*\*\*\*

Element De	scription									
Smart Flag	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 30	- Corrug/Orthotp	c Deck				·				
	1	3	268	sq.m.	Х	0	0	(	100	
						%	%	%	6 %	
Previous Ins	spection Notes :									
incidental 10 and clatters 10/13/2009 forming. Ap	00 percent sectio under traffic. Th - Asphalt overlay pproach transitior	n loss. Ma e left corn shows so ns fairly sm	ost of the soffit of er of the steel pome transverse of nooth. Soffit of o	coating late on cracking corruga	is in good sh the right side g at floorbear ted decking s	hape. The steel the is bent up and m locations and shows some coa	transition plate so could be a hazar approach span jo ating loss and rus	ections at bent d. bint location with ting about string	loss with small spo 5 has some loose b n minor potholes ger connection loca	bolts NZDZ ations.
11/17/2005	- Deck surface is				-		ome minor rustin from Steel Grid to	-	lo problems noted.	ZZDW SPGZ
(54.86 * 4.8	/									
Inspection	notes:									
=lement 112	2 - Unpnt Stl Stri									
	1	3	110	m.		90	10	(		
						%	%	%	%	
Previous Ins	spection Notes :								1	
	- Unpainted stee	I stringers	show some sur	face ru	st with some	minor surface p	itting.			EUMZ
	- Unpainted stee	I stringers	show some sur	face rus	st with some	minor surface p	itting.			EUMZ
10/31/2011	- Unpainted stee	I stringers	show some sur	face ru:	st with some	minor surface p	itting.			EUMZ
10/31/2011	- Unpainted stee	I stringers	show some sur	face rus	st with some	minor surface p	itting.			EUMZ
10/31/2011 Inspection	- Unpainted stee Notes:		show some sur	face ru	st with some	minor surface p	itting.			EUMZ
10/31/2011 Inspection	- Unpainted stee Notes: 3 - Paint Stl Strin	ger			st with some				5	EUMZ
10/31/2011 Inspection	- Unpainted stee Notes:		show some sur	face rus	st with some	80	10	Ę		
10/31/2011 Inspection Element 113	- Unpainted stee Notes: 3 - Paint Stl Strin 1	ger			st with some			ş %		EUMZ
10/31/2011 Inspection Element 113 Previous Ins	- Unpainted stee Notes: 3 - Paint Stl Strin 1 spection Notes :	ger 3	329	m.		80	10	%	6 %	
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace length when not replaced	- Unpainted stee Notes: 3 - Paint Stl Strin 1 spection Notes : - Changed the co d and minor to m h the timber deck	ger 3 ondition str noderate so was remo	329 ate back to 80-1 ection loss was ved. Minor are 139 meters to 32	m. 0-5-5 b observe as of se	pecause of th ed. In 2003 2	80 % e 2002 and 2003 21 stringers were th minor to mode	10 % 3 inspection note e replaced. All th erate paint loss w	s. In 2002 the j e stringers wervas observed in		l up EUMZ s were
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace ength when not replaced 10/13/2009	- Unpainted stee Notes:  3 - Paint Stl Strin  1  spection Notes :  - Changed the ca d and minor to m the timber deck J. Changed quar - No significant c	ger 3 ondition str noderate so was remo ntity from 4 changes no	329 ate back to 80-1 ection loss was ved. Minor area 139 meters to 32 oted.	m. 0-5-5 b observe as of see 29 mete	because of th ed. In 2003 2 ection loss wi ers because t	80 % e 2002 and 2003 21 stringers were th minor to mode	10 % 3 inspection note e replaced. All th erate paint loss w	s. In 2002 the j e stringers wervas observed in	blanks were pulled e inspected at arm the stringers that t	l up EUMZ s were
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace length when not replaceo 10/13/2009 09/25/2007	- Unpainted stee Notes:  3 - Paint Stl Strin  1  spection Notes :  - Changed the co d and minor to m the timber deck d. Changed quar - No significant c - Rusting appear	ger 3 ondition stand noderate stand was remo notity from 4 shanges no rs mostly u	329 ate back to 80-1 ection loss was ved. Minor area 439 meters to 32 oted. inchanged. No	m. 0-5-5 b observe as of se 29 mete problen	pecause of th ed. In 2003 2 ection loss wi ers because t ns noted.	80 % e 2002 and 200 21 stringers were th minor to mode the replaced strir	10 % 3 inspection note e replaced. All th erate paint loss w	s. In 2002 the particular stringers were stringers were vas observed in ced with unpain	blanks were pulled e inspected at arm the stringers that v ted steel stringers.	l up EUMZ s were NZDZ
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace ength when not replaced 10/13/2009 09/25/2007 11/17/2005	- Unpainted stee Notes: 3 - Paint Stl Strin 1 spection Notes : - Changed the co d and minor to m the timber deck d. Changed quar - No significant c - Rusting appear - Stringers show	ger 3 ondition str noderate so was remo htity from 4 changes no rs mostly u some pair	329 ate back to 80-1 ection loss was ved. Minor are 139 meters to 32 oted. inchanged. No nt loss with mino	m. 0-5-5 b observa as of se 29 mete problem pr rustin	pecause of th ed. In 2003 2 ection loss wi ers because t ns noted. ng basically th	80 % e 2002 and 2003 21 stringers were th minor to mode the replaced strin hroughout. No p	10 % 3 inspection note e replaced. All the erate paint loss w ngers were replace problems noted.	s. In 2002 the p the stringers were vas observed in ced with unpain (8 * 54.86 = 438	blanks were pulled e inspected at arm the stringers that we ted steel stringers.	l up EUMZ is were NZDZ ZZDW SPGZ
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replaced 10/13/2009 09/25/2007 11/17/2005 08/25/2003 section loss 11/19/2002	- Unpainted stee Notes: 3 - Paint Stl Strin 3 - Paint Stl Strin 1 spection Notes : - Changed the ca d and minor to m the timber deck d. Changed quar - No significant c - Rusting appear - Stringers show - 21 stringers we in areas where t - Top flanges of	ger 3 ondition st noderate st was remo ntity from 4 shanges no rs mostly u some pair ere replace there is mi stringers h	329 ate back to 80-1 ection loss was ved. Minor area 339 meters to 32 oted. inchanged. No nt loss with minor d in August 200 nor to moderate ave minor to moderate	m. 0-5-5 b observe as of se 29 mete problen pr rustin 03. The paint k oderate	pecause of th ed. In 2003 2 ection loss with ers because t ins noted. ing basically the ere is no chan poss. All string e section loss	80 % e 2002 and 2002 21 stringers were th minor to mode the replaced strin hroughout. No p nge in the conditi gers were inspec . This was obse	10 % 3 inspection note e replaced. All the erate paint loss with ngers were replace problems noted. ion of the remain cited at arms lenge	s. In 2002 the particular sector of the partic	blanks were pulled e inspected at arm the stringers that v ted steel stringers.	l up EUMZ Is were NZDZ ZZDW SPGZ ninor KHDZ oved.
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace ength when not replaced 10/13/2009 09/25/2007 11/17/2005 08/25/2003 section loss 11/19/2002 pulled up an	- Unpainted stee Notes:  3 - Paint Stl Strin  3 - Paint Stl Strin  5 - Changed the co d and minor to m the timber deck d. Changed quar - No significant c - Rusting appear - Stringers show - 21 stringers we in areas where t	ger 3 ondition st noderate su was remo thity from 4 shanges no rs mostly u some pair ere replace here is mi stringers h e paint syst	329 ate back to 80-1 ection loss was ved. Minor area 39 meters to 32 oted. inchanged. No not loss with minor d in August 200 nor to moderate ave minor to moderate ave minor to moderate	m. 0-5-5 b observe as of se 29 mete problen or rustin 3. The paint k oderate of the s	pecause of th ed. In 2003 2 ection loss wi ers because t ins noted. ing basically th ere is no chan oss. All string e section loss stringers is no	80 % 21 stringers were th minor to mode the replaced strin hroughout. No p nge in the conditi gers were inspec . This was obse o longer effective	10 % 3 inspection note e replaced. All the erate paint loss with ngers were replace problems noted. ion of the remain cited at arms lenge	s. In 2002 the particular sector of the partic	blanks were pulled e inspected at arm the stringers that w ted steel stringers. 8.88) ngers, they have m ber deck was remo	l up EUMZ Is were NZDZ ZZDW SPGZ ninor KHDZ oved.
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace ength when not replaced 10/13/2009 09/25/2007 11/17/2005 08/25/2003 section loss 11/19/2002 pulled up an 08/15/2000	<ul> <li>Unpainted stee</li> <li>Notes:</li> <li>3 - Paint Stl Strin</li> <li>3 - Paint Stl Strin</li> <li>1</li> <li>spection Notes :</li> <li>Changed the code and minor to menthe timber deck</li> <li>Changed quare</li> <li>No significant code and minor to menthe timber deck</li> <li>Changed quare</li> <li>Stringers show</li> <li>21 stringers where too and replaced. The stringers of an areas where too and replaced. The stringers of an areas of a stringers of a strin</li></ul>	ger 3 ondition st noderate su was remo thity from 4 shanges no rs mostly u some pair ere replace here is mi stringers h e paint syst	329 ate back to 80-1 ection loss was ved. Minor area 39 meters to 32 oted. inchanged. No not loss with minor d in August 200 nor to moderate ave minor to moderate ave minor to moderate	m. 0-5-5 b observe as of se 29 mete problen or rustin 3. The paint k oderate of the s	pecause of th ed. In 2003 2 ection loss wi ers because t ins noted. ing basically th ere is no chan oss. All string e section loss stringers is no	80 % 21 stringers were th minor to mode the replaced strin hroughout. No p nge in the conditi gers were inspec . This was obse o longer effective	10 % 3 inspection note e replaced. All the erate paint loss with ngers were replace problems noted. ion of the remain cited at arms lenge	s. In 2002 the particular sector of the partic	blanks were pulled e inspected at arm the stringers that w ted steel stringers. 8.88) ngers, they have m ber deck was remo	l up EUMZ s were ZZDW SPGZ ninor KHDZ yved. Q UZLZ
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replaced ength when not replaced 10/13/2009 09/25/2007 11/17/2005 08/25/2003 section loss 11/19/2002 pulled up an 08/15/2000 12/09/1998	- Unpainted stee Notes:	ger 3 ondition st noderate su was remo thity from 4 shanges no rs mostly u some pair ere replace here is mi stringers h e paint syst	329 ate back to 80-1 ection loss was ved. Minor area 39 meters to 32 oted. inchanged. No not loss with minor d in August 200 nor to moderate ave minor to moderate ave minor to moderate	m. 0-5-5 b observe as of se 29 mete problen or rustin 3. The paint k oderate of the s	pecause of th ed. In 2003 2 ection loss wi ers because t ins noted. ing basically th ere is no chan oss. All string e section loss stringers is no	80 % 21 stringers were th minor to mode the replaced strin hroughout. No p nge in the conditi gers were inspec . This was obse o longer effective	10 % 3 inspection note e replaced. All the erate paint loss with ngers were replace problems noted. ion of the remain cted at arms lenge	s. In 2002 the particular sector of the partic	blanks were pulled e inspected at arm the stringers that w ted steel stringers. 8.88) ngers, they have m ber deck was remo	l up EUMZ s were NZDZ ZZDW SPGZ hinor KHDZ oved. UZLZ HADW
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace length when not replaced 10/13/2009 09/25/2007 11/17/2005 08/25/2003 section loss 11/19/2002 pulled up an	Unpainted stee Notes:     I     I     Paint Stl Strin     1     spection Notes :     Changed the ca d and minor to m the timber deck d. Changed quar - No significant c - Rusting appear - Stringers show - 21 stringers where t - Top flanges of d replaced. The - Top flanges of - None -	ger 3 ondition st noderate su was remo thity from 4 shanges no rs mostly u some pair ere replace here is mi stringers h e paint syst	329 ate back to 80-1 ection loss was ved. Minor area 39 meters to 32 oted. inchanged. No not loss with minor d in August 200 nor to moderate ave minor to moderate ave minor to moderate	m. 0-5-5 b observe as of se 29 mete problen or rustin 3. The paint k oderate of the s	pecause of th ed. In 2003 2 ection loss wi ers because t ins noted. ing basically th ere is no chan oss. All string e section loss stringers is no	80 % 21 stringers were th minor to mode the replaced strin hroughout. No p nge in the conditi gers were inspec . This was obse o longer effective	10 % 3 inspection note e replaced. All the erate paint loss with ngers were replace problems noted. ion of the remain cted at arms lenge	s. In 2002 the particular sector of the partic	blanks were pulled e inspected at arm the stringers that w ted steel stringers. 8.88) ngers, they have m ber deck was remo	l up EUMZ is were NZDZ ZZDW SPGZ hinor KHDZ oved. UZLZ HADW TYYB
10/31/2011 Inspection Element 113 Previous Ins 10/31/2011 and replace length when not replaced 10/13/2009 09/25/2007 11/17/2005 08/25/2003 section loss 11/19/2002 pulled up an 08/15/2000 12/09/1998 08/01/1995	- Unpainted stee Notes: 3 - Paint Stl Strin 1 spection Notes : - Changed the co d and minor to m in the timber deck d. Changed quar - No significant co - Rusting appear - Stringers show - 21 stringers we in areas where to - Top flanges of ad replaced. The - Top flanges of - None - None - None	ger 3 ondition st noderate su was remo thity from 4 shanges no rs mostly u some pair ere replace here is mi stringers h e paint syst	329 ate back to 80-1 ection loss was ved. Minor area 39 meters to 32 oted. inchanged. No not loss with minor d in August 200 nor to moderate ave minor to moderate ave minor to moderate	m. 0-5-5 b observe as of se 29 mete problen or rustin 3. The paint k oderate of the s	pecause of th ed. In 2003 2 ection loss wi ers because t ins noted. ing basically th ere is no chan oss. All string e section loss stringers is no	80 % 21 stringers were th minor to mode the replaced strin hroughout. No p nge in the conditi gers were inspec . This was obse o longer effective	10 % 3 inspection note e replaced. All the erate paint loss with ngers were replace problems noted. ion of the remain cted at arms lenge	s. In 2002 the particular sector of the partic	blanks were pulled e inspected at arm the stringers that w ted steel stringers. 8.88) ngers, they have m ber deck was remo	l up EUMZ s were NZDZ ZZDW SPGZ hinor KHDZ yved. UZLZ HADW TYYB UOTS



Element Description					•	.) * * * * * * * *			
Smart Flag Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 121 - P/Stl Thru Tru	uss/Bot								
1	3	110	m.		80	10	10	0	(
					%	%	%	%	%
Previous Inspection Notes :									
10/31/2011 - Bottom chord h	nas some t	op coat loss wit	n some	areas of stat	te 3 rust. Materi	al accumulations	needs to be clea	aned off the bottom	EUMZ
chord. No changes noted. 10/13/2009 - No significant o	changes no	oted.							NZDZ
09/25/2007 - Material accum	-		d need	l cleaned peri	iodically. No oth	er significant cha	nges noted.		ZZDW
11/17/2005 - Lower chord sh		-			•	-	-	ons. Some minor	SPGZ
cracking of some tension me periodically (54.86 * 2 = 10	embers alo								ned
08/25/2003 - No change									KHDZ
11/19/2002 - None									UZLZ
08/15/2000 - None									HADW
12/09/1998 - None									ТҮҮВ
08/01/1995 - None									UOTS
01/01/1995 - None									UDLM
Inspection Notes:									
Element 126 - P/Stl Thru Tru	uss/Top								
1	3	110	m.		90	10	0	0	(
					%	%	%	%	9
Previous Inspection Notes :									
10/31/2011 - No changes no	ted in the	top truss.							EUMZ
10/13/2009 - No significant of									NZDZ
09/25/2007 - Some diagonal	•		w some	e minor defor	mation. No char	iges noted. Som	e additional rust	ing noted.	ZZDW
11/17/2005 - No detected ch nuts appear to be "backed o							t losses and min	or rusting. A coupl	le SPGZ
08/25/2003 - No change		bar dont appea				_,			KHDZ
11/19/2002 - Truss member upward. Spacer around pin a	at U1 upsti	ream side has o	pened	up but is still	in place.	`	, <b>.</b>		
08/15/2000 - Truss member upward.	U5 L6 dov	wnstream side is	bent a	ind non-funct	ional. Truss me	nber U1 L2 (inte	erior member) up	stream side is bow	
12/09/1998 - None									TYYB
08/01/1995 - None 01/01/1995 - None									UOTS UDLM
Inspection Notes:									



* * * * * * * * * * * Span : Main-01 (cont.)	* * * * * * * * * *
--	---------------------


Element Des	scription									
Smart Flag	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 152	2 - Paint Stl Floo	r Beam								
	1	3	49	m.		80	10	5	5	0
						%	%	%	%	%
Previous Ins	pection Notes :									
10/31/2011 ·	The painted ste	eel floor be	ams have area	s of pair	nt loss and ru	usting. The 200	3 inspection repo	ort shows that the	e floor beams were	EUMZ
	arms length when No significant of			moved	and minor se	ection loss was o	observed on top of	of the top flanges	6.	NZDZ
	No significant o	Ũ		litional	rusting about	t nanel noints				ZZDW
	Ŭ	Ũ			Ŭ	•	noted. (10 * 4.88	3 - 48 80)		SPGZ
		•		0	•	•	`	,	no paint, and minor	
section loss	on the top of the					ms is in faily goo			io paint, and minor	
11/19/2002 -										UZLZ
08/15/2000 ·										HADW
12/09/1998 -										ТҮҮВ
08/01/1995										UOTS
01/01/1995 ·	None									UDLM
Inspection I	Notes:									
Element 181	- Pnt Vrt X-Frai	me								
	1	3	83	m.		85	10	5	0	0
						%	%	%	%	%
Previous Ins	pection Notes :					I	I		I I	
10/31/2011 ·	No changes no	ted with th	e X-Frame.							EUMZ
10/13/2009 -	No significant o	changes no	oted.							NZDZ
09/25/2007 -	Some minor da	amage to s	way bracing. N	o chang	ges noted.					ZZDW
11/17/2005 -	Some frames s	show some	minor paint los	s and n	ninor rusting	with some collis	ion damage - pas	st. No significan	t changes noted.	SPGZ
08/25/2003 ·	No change									KHDZ
11/19/2002 -	None									UZLZ
08/15/2000 ·	None									HADW
12/09/1998 -	None									TYYB
08/01/1995 ·	None									UOTS
01/01/1995 ·	None									UDLM
Inspection I	Notes:									



L32101000+01001

Continue

****** Span : Main-01 (cont.) * * * * * * * * * *	
Element Description	
	Stat 3 Pct Stat 4 Pct Stat 5
Element 210 - R/Conc Pier Wall	
1 3 7 m. 90 10	0 0
% %	% %
Previous Inspection Notes :	
10/31/2011 - Some minor cracking with some minor edge spalling. No changes noted.	EUMZ
10/13/2009 - No significant changes noted.	NZDZ
09/25/2007 - No significant changes to wall at P3 and P4.	ZZDW
11/17/2005 - Wall shows some cracking. Some minor edge spalling. No changes noted. No problems noted.	SPGZ
08/25/2003 - No change	KHDZ
11/19/2002 - None	UZLZ
08/15/2000 - None	HADW
12/09/1998 - None	TYYB
08/01/1995 - None	UOTS
01/01/1995 - None	UDLM
Inspection Notes:	
Element 215 - R/Conc Abutment B5	
1 3 7 m. 95 5	0 0
	% %
Previous Inspection Notes :	
10/31/2011 - No changes noted with the abutment at bent 5.	EUMZ
10/13/2009 - No additional deterioration noted.	NZDZ
09/25/2007 - Cracking and spalling appear unchanged. Material accumulations anout both sides of West abutmen	
bearing devices.	
11/17/2005 - Abutment components show some minor cracking and edge spalling. Material accumulations along obearings needs cleaned periodically. See pics	cap top and about roller nest SPGZ
08/25/2003 - No change	KHDZ
11/19/2002 - None	UZLZ
08/15/2000 - None	HADW
12/09/1998 - None	TYYB
08/01/1995 - None	UOTS
01/01/1995 - None	UDLM
Inspection Notes:	




Element Desc	ription					-				
	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 311 -	Moveable Be	aring B5	I	1					I	
	1	3	2	2 ea.		0	100	0		
						%	%	%	%	(
Previous Insp	ection Notes :									
devices are no	on functional.	No change	r bolts and the es from the last ion about devi	QA rep	ort.	oller nest is twis	ted and the roller	s are out of alig	nment. The roller	EUMZ NZDZ
09/25/2007 - F	Roller nest dev	rices at We	est abutment to	tally nor	n functional.	Others ok.				ZZDW
11/17/2005 - F structure. 08/25/2003 - N			end is twisted i	in it's ke	eper and full	of material, see	pic Has not roll	ed in years but	there is still movme	ntin SPGZ KHDZ
		•	v/ wet soil and	moss						UZLZ
08/15/2000 - N			wet son and	11033.						HADW
12/09/1998 - N			on-functional							ТҮҮВ
08/01/1995 - N		inge are m								UOTS
01/01/1995 - 1										UDLM
Element 313 -	Fixed Bearing									
	1	3	2	2 ea.		65	30	5		
Previous Insp	ection Notes :					%	%	%	%	(
· ·		om the 200	9 QA inspectio	n renor						EUMZ
	lo significant o			nicpon						NZDZ
	lo significant o	-								ZZDW
	-	-	oted. No proble	ems not	ed.					SPGZ
08/25/2003 - 1	-	Ũ	·							KHDZ
11/19/2002 - F	Paint is peeling	g, fleck rust	t and pitting ev	ident.						UZLZ
08/15/2000 - N	lone									HADW
12/09/1998 - 1	lone									ТҮҮВ
08/01/1995 - N	lone									UOTS
01/01/1995 - N	lone									UDLM
Inspection No	otes:									




* * * * * * * * * * * Span : Main-01 (cont.) * * *	* * * * * * * *
--	-----------------

Element Des	scription									
-	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 334	- Metal Rail Co	ated					·		· · · ·	
	1	3	110	m.		90	5	5	0	0
						%	%	%	%	%
Previous Ins	pection Notes :									
10/31/2011 -	Minor damage	with protec	ctive coating los	ss and n	ninor rusting	<b>]</b> .				EUMZ
10/13/2009 -	No significant o	hanges no	oted.							NZDZ
09/25/2007 -	No significant o	hanges no	oted. Damage	still rema	ains.					ZZDW
11/17/2005 -	Some minor co	llision ding	s and dents. N	lo probl	ems noted.	Some minor pai	nt spot losses an	d rusting. (54.86	6 * 2 = 109.72)	SPGZ
08/25/2003 -	Timber curbs w	vere replac	ed with tubular	steel, a	nd all handr	ail was straighte	ned and painted	with galv paint in	August 2003.	KHDZ
11/19/2002 -	None									UZLZ
08/15/2000 -	Collision dama	ge								HADW
12/09/1998 -	Paint loss and	vehicular d	lamage.							TYYB
08/01/1995 -	None									UOTS
01/01/1995 -	None									UDLM
Inspection I	Notes:									
Element 361	- Scour Smart I	Flag								
Х	1	1	1	ea.	Х	100	0	0		
						%	%	%	%	%
Previous Ins	pection Notes :									
10/31/2011 -	Countermeasu	res are in p	olace.							EUMZ
10/13/2009 -	None									NZDZ
09/25/2007 -	None									ZZDW
Inspection I	Notes:									
Element 372	2 - CntrMesur Sn	nFlag								
X	1	1	1	ea.	X	0	100	0	0	
						%	%	%	%	%
Previous Ins	pection Notes :									
	· No changes no	ited.								EUMZ
	· Countermeasu		e and holding	Minor re	epair neces	sarv.				NZDZ
09/25/2007 -		pictor			,					ZZDW
Inspection I										
			* * *	* * * *	* * * 900	n : Appr-11 *	* * * * * * * * *	*		
					Spai					


Element Des	scription								
Smart Flag	Scale Factor	Env	Quantity	Units Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5



Element Des	•									
	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 63 -	- Unp Top Flang	/AC Ovl								
	1	3	182	sq.m.	X	100	0	0	0	
						%	%	%	%	(
Previous Ins	pection Notes :		1							
10/31/2011 -	- Minor cracking	of the asp	halt. No other p	oroblem	s noted.					EUMZ
10/13/2009 -	- Minor cracking	of overlay	. No significant	change	es noted.					NZDZ
09/25/2007 -	- Some transver	se cracking	g of asphalt. No	o proble	ms noted.					ZZDW
Inspection I	Notes:									
Element 110	) - R/Conc Oper	Girder Te	e Beams - Spa	ins 1 an	d 2					
	1	3	149	m.		100	0	0	0	
						%	%	%	%	
Previous Ins	spection Notes :									
	- No changes, n	o problems	noted							EUMZ
	- No changes, n									NZDZ
10/13/2000 -	- No significant (	handes no	hote							
	- No significant o	-		acks in f	asphalt So	ffit appears unch	anged Some mi	nor cracking and	d scaling	770\//
09/25/2007 -	- Surface smoot	h with som	e transverse cr				anged. Some mi	-	-	
09/25/2007 - 11/17/2005 -	- Surface smoot - Surface shows	h with som fairly smo	e transverse cra oth. Minor Crac	cking at	bridge end.	Soffit appears u	inchanged. No p	-	d scaling. (37.34 * 4 = 149.3	,
09/25/2007 - 11/17/2005 - 08/25/2003 -	- Surface smoot - Surface shows - Keyways repai	h with som fairly smo	e transverse cra oth. Minor Crac	cking at	bridge end.		inchanged. No p	-	-	
09/25/2007 - 11/17/2005 -	- Surface smoot - Surface shows - Keyways repai	h with som fairly smo	e transverse cra oth. Minor Crac	cking at	bridge end.	Soffit appears u	inchanged. No p	-	-	6) SPGZ
09/25/2007 - 11/17/2005 - 08/25/2003 -	- Surface smoot - Surface shows - Keyways repai	h with som fairly smo	e transverse cra oth. Minor Crac	cking at	bridge end.	Soffit appears u	inchanged. No p	-	-	6) SPGZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection N	- Surface smoot - Surface shows - Keyways repai Notes:	h with som fairly smo red, petror	e transverse cra oth. Minor Crac	cking at	bridge end.	Soffit appears u	inchanged. No p	-	-	6) SPGZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection N	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur	h with som fairly smo red, petror	e transverse cra oth. Minor Crao nat laid over the	cking at	bridge end.	Soffit appears u overlay placed ir	nchanged. No p n August 2003.	roblems noted.	(37.34 * 4 = 149.3	6) SPGZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection N	- Surface smoot - Surface shows - Keyways repai Notes:	h with som fairly smo red, petror	e transverse cra oth. Minor Crac	cking at	bridge end.	Soffit appears u	inchanged. No p	-	-	6) SPGZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection N	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur	h with som fairly smo red, petror	e transverse cra oth. Minor Crao nat laid over the	cking at	bridge end.	Soffit appears u overlay placed ir	nchanged. No p n August 2003.	roblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur	h with som fairly smo red, petror	e transverse cra oth. Minor Crao nat laid over the	cking at	bridge end.	Soffit appears u overlay placed ir 90	nchanged. No p n August 2003. 10	roblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur 1 spection Notes :	h with som fairly smo red, petror mn 3	e transverse cra oth. Minor Crao nat laid over the 3	cking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 %	nchanged. No p n August 2003. 10	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 -	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur 1 spection Notes :	h with som fairly smo red, petror nn 3 with a spa	e transverse cra oth. Minor Crac nat laid over the 3 11 near the top o	cking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 %	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 - 10/13/2009 -	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur 1 spection Notes : - Minor cracking	h with som fairly smo red, petror mn 3 with a spa changes no	e transverse cra oth. Minor Crao nat laid over the 3 Jul near the top o oted.	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 -	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur 1 spection Notes : - Minor cracking - No significant of	h with som fairly smo red, petror mn 3 with a spa changes no spalling app	e transverse cra oth. Minor Crao nat laid over the 3 Il near the top o oted. Dear unchanged	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 -	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur 1 spection Notes : - Minor cracking - No significant of - Cracking and s - No significant of	h with som fairly smo red, petror mn 3 with a spa changes no spalling app	e transverse cra oth. Minor Crao nat laid over the 3 Il near the top o oted. Dear unchanged	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection R Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 -	- Surface smoot - Surface shows - Keyways repai Notes: 5 - R/Conc Colur 1 spection Notes : - Minor cracking - No significant of - Cracking and s - No significant of	h with som fairly smo red, petror mn 3 with a spa changes no changes no	e transverse cra oth. Minor Crao nat laid over the anat laid over the anat laid over the sear unchanged oted.	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ KHDZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 - 11/19/2002 -	<ul> <li>Surface smoot</li> <li>Surface shows</li> <li>Keyways repain</li> <li>Notes:</li> <li>Anterstand State</li> <li>R/Conc Column</li> <li>R/Conc Column</li> <li>R/Conc Column</li> <li>Notes:</li> <li>Minor cracking</li> <li>No significant of</li> <li>No significant of</li> <li>No significant of</li> <li>No significant of</li> <li>None</li> </ul>	h with som fairly smo red, petror mn 3 with a spa changes no spalling app changes no s and mino	e transverse cra oth. Minor Crao nat laid over the anat laid over the	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ KHDZ UZLZ
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 - 11/19/2002 - 08/15/2000 -	<ul> <li>Surface smoot</li> <li>Surface shows</li> <li>Keyways repain</li> <li>Notes:</li> <li>Notes:</li> <li>A R/Conc Colurt</li> <li>P R/Conc Colurt</li> <li>T</li> <li>Spection Notes :</li> <li>Minor cracking</li> <li>No significant of</li> <li>Cracking and se</li> <li>No significant of</li> <li>No significant of</li> <li>None</li> <li>Random crack</li> <li>Random crack</li> </ul>	h with som fairly smo red, petror mn 3 with a spa changes no spalling app changes no s and mino	e transverse cra oth. Minor Crao nat laid over the anat laid over the	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ KHDZ UZLZ HADW
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection R Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 - 11/19/2002 -	<ul> <li>Surface smoot</li> <li>Surface shows</li> <li>Keyways repained</li> <li>Notes:</li> <li>Anticipation</li> <li>Anticipation</li> <li>Anticipation</li> <li>Anticipation</li> <li>No significant of</li> <li>No significant of</li> <li>None</li> <li>Random crack</li> <li>Random crack</li> <li>None</li> </ul>	h with som fairly smo red, petror mn 3 with a spa changes no spalling app changes no s and mino	e transverse cra oth. Minor Crao nat laid over the anat laid over the	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ KHDZ UZLZ HADW TYYB
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection R Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 - 11/19/2002 - 08/15/2000 - 12/09/1998 -	<ul> <li>Surface smoot</li> <li>Surface shows</li> <li>Keyways repained the shows</li> <li>Keyways repained the shows</li> <li>Notes:</li> <li>Anticestantian structure the shows</li> <li>Repection Notes :</li> <li>Minor cracking</li> <li>No significant of the shows</li> <li>No significant of the shows</li> <li>No significant of the shows</li> <li>None</li> <li>Random crack</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> </ul>	h with som fairly smo red, petror mn 3 with a spa changes no spalling app changes no s and mino	e transverse cra oth. Minor Crao nat laid over the anat laid over the	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ KHDZ UZLZ HADW TYYB UOTS
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection I Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 - 11/19/2002 - 08/15/2000 - 12/09/1998 - 08/01/1995 - 01/01/1995 -	<ul> <li>Surface smoot</li> <li>Surface shows</li> <li>Keyways repained the shows</li> <li>Keyways repained the shows</li> <li>Notes:</li> <li>Anticestation of the shows</li> <li>Repection Notes :</li> <li>Minor cracking</li> <li>No significant of the shows</li> <li>No significant of the shows</li> <li>No significant of the shows</li> <li>None</li> <li>Random crack</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> </ul>	h with som fairly smo red, petror mn 3 with a spa changes no spalling app changes no s and mino	e transverse cra oth. Minor Crao nat laid over the anat laid over the	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW SPGZ KHDZ UZLZ HADW TYYB UOTS
09/25/2007 - 11/17/2005 - 08/25/2003 - Inspection R Element 205 Previous Ins 10/31/2011 - 10/13/2009 - 09/25/2007 - 11/17/2005 - 08/25/2003 - 11/19/2002 - 08/25/2003 - 11/19/2002 - 08/15/2000 - 12/09/1998 - 08/01/1995 -	<ul> <li>Surface smoot</li> <li>Surface shows</li> <li>Keyways repained the shows</li> <li>Keyways repained the shows</li> <li>Notes:</li> <li>Anticestation of the shows</li> <li>Repection Notes :</li> <li>Minor cracking</li> <li>No significant of the shows</li> <li>No significant of the shows</li> <li>No significant of the shows</li> <li>None</li> <li>Random crack</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> <li>None</li> </ul>	h with som fairly smo red, petror mn 3 with a spa changes no spalling app changes no s and mino	e transverse cra oth. Minor Crao nat laid over the anat laid over the	eking at em and a ea.	bridge end. a 2" asphalt	Soffit appears u overlay placed ir 90 % lo exposed rebar	nchanged. No p n August 2003. 10 %	oblems noted.	(37.34 * 4 = 149.3	6) SPGZ KHDZ EUMZ NZDZ ZZDW




Element Des			-							_
Smart Flag	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 215	- R/Conc Abutr	ment B1								
	1	3	-	7 m.		95	5	0	0	
						%	%	%	%	
Previous Ins	pection Notes :									
10/31/2011 -	3 exposed con	crete colun	nns at abutmer	nt 1. Mir	nor cracking	and minor edge	spalling on the al	butment.		EUMZ
10/13/2009 -	No significant of	changes no	oted.							NZDZ
09/25/2007 -	B1 shows som	e sloughing	g from under a	butment	. Some mind	or cracking and n	ninor delaminatio	on at corners.		ZZDW
11/17/2005 -	No changes no	oted. No pi	oblems noted.							SPGZ
08/25/2003 -	None									KHDZ
11/19/2002 -	None									UZLZ
08/15/2000 -	None									HADW
12/09/1998 -	None									TYYB
08/01/1995 -	None									UOTS
01/01/1995 -	None									UDLM
Inspection N	Notes:									
Element 234	- R/Conc Cap									
	1	3		1 m.		90	5	5	0	
						%	%	%	%	
Drovieus Inc	nantion Noton .					70	70	70	70	
	pection Notes :	d	to consisted							
	No changes to									EUMZ
	No significant of									NZDZ
	No significant of									ZZDW
	No significant of	changes no	oted.							SPGZ
08/25/2003 -										KHDZ
				spall ar	ea is .21 sq i	m x 3.8 cm deep	•			UZLZ
	Random crack									HADW
	Top of concrete	e parapet r	has areas of mi	nor spal	ling but no e	xposed rebar.				TYYB
08/01/1995 -										UOTS
01/01/1995 -	None									UDLM
Inspection N	Notes:									



L32101000+01001

Continue


			* * * * * *	* * * * *	՝ Span : Al	ppr-11 <b>(con</b>	t.) * * * * * * * *	* * *		
Element Des	•									
	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 334	- Metal Rail Co	ated								
	1	3	75	m.		90	5	5	0	0
						%	%	%	%	%
Previous Ins	pection Notes :					I	I		I	
10/31/2011 -	Minor damage	with protec	tive coating los	s and n	ninor rusting.	. The 8 inch con	crete curb has s	palling with some	e exposed rebar.	EUMZ
10/13/2009 -	None									NZDZ
09/25/2007 -	See main span	notes.								ZZDW
11/17/2005 -	see main span	element no	otes. (37.34 * 2	2 = 74.6	8)					SPGZ
08/25/2003 -	Painted 2003									KHDZ
11/19/2002 -	None									UZLZ
08/15/2000 -	Collision dama	ge								HADW
12/09/1998 -	Minor paint los	- 3.								TYYB
08/01/1995 -										UOTS
01/01/1995 -	None									UDLM
Inspection N	lotes:									
	Voles.									
			***	****	* * * 0		* * * * * * * * * *			
					Spar	1. Main-21	* * * * * * * * *			
Element Des	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
-	· Corrug/Orthotp		Quantity	Onits						
	1	3	58	sq.m.	X	0	0	100	0	0
	•	0		9 <b>9</b> .111.	~	%	%	%	%	%
						/0	/0	70	70	/0
	pection Notes :									
10/31/2011 - soffit is in go		se cracking	g of asphalt. Th	e corru	pated steel s	offit shows coati	ng loss with some	e rusting. Most o	of the corrugated	steel EUMZ
10/13/2009 -										NZDZ
09/25/2007 -	Some transvers	se cracing	of asphalt surfa	ace.						ZZDW
11/17/2005 -	See main span	element n	otes. Main spa	an 2 sim	ilar. (11.96 <sup>;</sup>	* 4.88 = 58.36)				SPGZ
Inspection N	Notes:									
1		aor								
Element 112	- Unpnt Stl Strii	igei								
Element 112	•		16	m.		90	10	0	0	
Element 112	- Unpnt Stl Stri	3	16	m.		90 %	10	0	0	0/
	1		16	m.		90 %	10 %	0 %	0 %	%
Previous Ins	1 pection Notes :	3				%	%	%	%	
Previous Ins 10/31/2011 -	1 pection Notes : Unpainted Stee	3 el stringers	shows minor s		usting and s	%		%	%	% EUMZ
Previous Ins 10/31/2011 -	1 pection Notes : Unpainted Stee t were replaced	3 el stringers	shows minor s		usting and s	%	%	%	%	
Previous Ins 10/31/2011 - stringers that	1 pection Notes : Unpainted Stee t were replaced	3 el stringers	shows minor s		usting and s	%	%	%	%	
Previous Ins 10/31/2011 - stringers that	1 pection Notes : Unpainted Stee t were replaced	3 el stringers	shows minor s		usting and s	%	%	%	%	



L32101000+01001 Continue

\*\*\*\*\*\*\*\*\*\* Span : Main-2 - -1 (cont.) \*\*\*\*\*\*\*\*\*

Smart Flag         State Factor         Env         Quantity         Units         Inspection         Pet Stat 1         Pet Stat 2         Pet Stat 3         Pet Stat 4	Element De	scription									
1         3         80         m         80         15         S         0         0           Provious Inspection Notes :         103/300/11         30         <	Smart Flag	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Provious Inspection Notes :         Signal         Signal <td>Element 11:</td> <td>3 - Paint Stl String</td> <td>ger</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Element 11:	3 - Paint Stl String	ger								
PreVious Inspection Notes :       EUM2         100312011 - No changes noted from the 2003 inspecton report. The deck was removed in 2003 and the stringers were inspected at arms length in the 2003 report the stringers with moderate section loss were replaced and the stringers left in 1013 compare in 2002 were unpainted.       NZD2         10132009 - None       Nonor rusting and coating loss appears unchanged. No problems noted.       NZD2         10132009 - None       Noner rusting and coating loss appears unchanged. No problems noted.       NZD2         10132009 - Vinner continons appear unchanged. No problems noted.       NZD2         10132009 - Vinner continons appear unchanged. No problems noted.       NZD2         10132009 - Vinner rusting and coating loss appears and not of the tube, see picks.       NZD2         10132009 - Vinner rusting and coating loss appears and not of the tube, see picks.       NZD2         10132009 - Vinner rusting and coating acts of minor section loss and paint system is non-functional on top of langes.       NZD2         10209 - Sea, timber nallers (60 m) set along aide of painted steel stringers and deck is spiked to them.       NYP3         10132009 - None       UOIX         10132009 - None       NZD2         10132009 - None       NZ		1	3	80	m.		80	15	5	0	0
10312011       No changes subol from the 2003 inspection resort. The dock was removed in 2003 and the stringers were inspaced at arms length and a was and in the stringers were inspaced at arms length and a was and in the stringers were inspaced at arms length and a was and in a stringer inspection. Some were uparted.       N2D2         10/13/2009 - None       None runting and costing loss appears unchanged. No problems noted.       N2D2         10/13/2009 - None       No problems noted.       N2D2         10/13/2009 - None were uparted.       No problems noted.       N2D2         10/13/2009 - None were uparted.       No problems noted.       N2D2         10/13/2009 - None were uparted.       No problems noted.       N2D2         10/13/2009 - None were uparted.       No problems noted.       N2D2         10/13/2009 - None were uparted.       No problems noted.       N2D2         10/13/2009 - Tog flanges of stringers and of the loss apprix.       Stringers.       HID2         10/13/2009 - Tog flanges of stringers have isolated areas of minor to moderate section loss and paint system is non-functional on top of flanges.       HAD2         10/13/2009 - None       UD1M       Norther stringers were indicated areas of minor section loss and paint system is non-functional on top of flanges.       HAD2         10/13/2009 - None       10/13/2009 - None       Norther stringers were indicated areas of more section loss and paint system is non-functional on top of flanges.       HAD2							%	%	%	%	%
as stated in element 113 for the main span). In the 2003 report the stringers with moderate section loss were replaced and the stringers left in Jace have isolated areas of minor section loss on the planges. The quantity was changed from 96 meters to 80 meters because the stringers left in Jace have isolated areas of minor section loss on the planges. The quantity was changed from 96 meters to 80 meters because the stringers left in Jace have some meters to 80 meters because the stringers left in Jace have some meters to 80 meters because the stringers left in Jace have some meters to 80 meters because the stringers left in Jace have some meters to 80 meters because the stringers left in Jace have some meters to 80 meters because the stringers left in Jace have some analytic stringers with moderate section loss are replaced in August KHDZ 10/12/005 - None for the tube, see pics. Jace have some analytic stringers with moderate section loss and paint system is non-functional on top of flanges. Jace Jace Jace Jace Jace Jace Jace Jace	Previous Ins	spection Notes :						L			
99/25/2007 - Minor rusting and coating loss appears unchanged. No problems noted.       220W         11/17/2005 - Stringer conditions appear unchanged. No problems noted.       West end members sit on neoprene type pads eight total. Four each on of the tube, see pics       KH02         10/25/2007 - Winron section loss in isolated areas of top finage of stringers. Stringers with moderate section loss were replaced in August (KH02       KH02         10/25/2007 - Moderate loss of paint and isolated areas of minor to moderate section loss and paint system is non-fluctional on top of flanges.       UZL2         12/09/1989 - 6 at. timber nailers (60 m) set along side of painted steel stringers and deck is spiked to them.       TYPE         1       3       24       m       86       10       6       0       0         1       3       24       m       86       10       6       0       0       9         1       3       24       m       86       10       6       0       0       9         10/31/2011 - Minor paint loss with some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted.       EUMZ       1       1       2       2       2       2       2       2       1       0       0       0       1       1       1       1       1       1       1       1       1	(as stated ir place have i that were re	n element 113 for isolated areas of placed in 2002 w	the main sminor sect	span). In the 20 tion loss on the	03 repc	ort the string	gers with moderat	te section loss we	ere replaced and	the stringers left	in gers
11/17/2005 - Stringer conditions appoint unchanged. No problems noted. West and members sit on neoprane type pads eight total. Four each on SPG2 isster and is not to the piece with a pad under each and of the tube, see pics Stringers with moderate section loss were replaced in August KHD2 10/02/001 - Vor minon section loss of paint and isolated areas of minor to moderate section loss and paint system is non-functional on top of flanges.       KHD2 10/02 - Top flanges of stringers have isolated areas of minor to moderate section loss and paint system is non-functional on top of flanges.       KHD2 10/02 - Top flanges of stringers have isolated areas of minor to moderate section loss and paint system is non-functional on top of flanges.       KHD2 10/02 - Top flanges of stringers have isolated areas of minor section loss on top flanges.       KHD2 10/02 - Top flanges of stringers have isolated areas of minor section loss on top flanges.       KHD2 10/02 - Top flanges of stringers have isolated areas of minor section loss on top flanges.       LU2 2         10/02/1995 - None       UDLM       UDLM       UDLM       LU2 - P/Sit Thru Truss/Bot       UDLM         1       3       24       m.       86       10       6       0       0         10/03/2009 - None        9       9       9       9       No       No         10/03/2009 - None         9       9       9       No       No         10/03/2009 - None          9       9       9       No       No			nd coating	loss appears u	nchang	ed. No pro	blems noted.				
11/19/2002 - Top flanges of stringers have isolated areas of minor to moderate section loss and paint system is non-functional on top of flanges.       U2.2         02/15/2000 - Moderate loss of paint and isolated areas of minor section loss on top flanges       HADW         02/15/2000 - Moderate loss of paint and isolated areas of minor section loss on top flanges       HADW         02/01/1995 - None       UDELM         03/01/1995 - None       UDELM         1       3       24 m.       85       10       5       0       0         1       3       24 m.       85       10       5       0       0         2       1       3       24 m.       85       10       5       0       0         3/10/12011 - Minor paint loss with some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted.       EUMZ         10/31/2011 - Minor paint loss with some material accumulations. Some minor spot paint loss and minior rusting. No changes noted.       EUMZ         10/31/2010 - All horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No       SPG2         10/31/2010 - All horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No       SPG2         10/31/2010 - None       UDIM       UDIM       UDIM         10/31/30	East end sit 08/25/2003	on two tube pied	es with a p	pad under each	end of	the tube, se	ee pics	·		0	
12/09/1998 - 5 ea. timber nailers (60 m) set along side of painted steel stringers and deck is spiked to them.       TYYB         38/01/1995 - None       UOTS         UIN1995 - None       UDLM         Inspection Notes:       Image: Ima		- Top flanges of	stringers h	ave isolated are	eas of m	ninor to mod	derate section los	s and paint syste	m is non-functio	nal on top of flan	ges. UZLZ
Darl 1/1995 - None       UOTS         UI/11/1995 - None       UDLM         Inspection Notes:       Imspection Notes:         Imspection Notes:       Imspection Notes:	08/15/2000	- Moderate loss of	of paint and	d isolated areas	s of min	or section lo	oss on top flange	s			HADW
D1/01/1995 - None       UDLM         Inspection Notes:	12/09/1998	- 5 ea. timber nai	ilers (60 m	) set along side	of pain	ted steel st	ringers and deck	is spiked to them	ı.		TYYB
Inspection Notes:   Element 121 - P/Stl Thru Truss/Bot   I 3 24 m. 85 10 5 0 0  Previous Inspection Notes:  I0/31/2011 - Minor paint loss with some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted. EUMZ NZD22 D013/2007 - Material accumulations increasing. Rusting appears unchanged. I1/17/2005 - Alt horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No SPGZ NOT - Material accumulations increasing. Rusting appears unchanged. I1/17/2005 - Alt horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No SPGZ Norbitry Some UZLZ D8/15/2000 - None UZLZ D8/15/2000 - None UDLM Inspection Notes:  Element 126 - P/Stl Thru Truss/Top  Element 126 - P/Stl	08/01/1995	- None									UOTS
Element 121 - P/Stl Thru Truss/Bot           1         3         24         m.         85         10         5         0         0           Previous Inspection Notes :         0	01/01/1995	- None									UDLM
1         3         24         m.         85         10         5         0         00           Previous Inspection Notes :         Image: Constraint Constent Constent Constraint Constent Constraint Constent Constraint Co	Inspection	Notes:									
1         3         24         m.         85         10         5         0         00           Previous Inspection Notes :         Interview of the section Notes section Notes in Some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted.         EUMZ           10/13/2009 - None         Note of the section Notes increasing. Rusting appears unchanged.         ZZDW         NZDZ           10/13/2009 - None         Naterial acumulations increasing. Rusting appears unchanged.         ZZDW         SPGZ           11/17/2005 - All horizontal pieces have some material accumualtions. Some minor spot paint loss and minor rusting. No changes noted. No create the section Notes increasing. Rusting appears unchanged.         ZZDW           10/13/2003 - No change         KHDZ         KHDZ           10/19/2003 - No ne         UZLZ           11/19/2002 - None         UZLZ           12/09/1998 - None         UOTS           12/09/1995 - None         UOTS           11/19/2005 - None         UDLM           Inspection Notes:         UDLM           Inspection Notes:         VIDLM           1         3         131         m.         90         0         0         0           10/13/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.         EUMZ         NZDZ <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>											
1         3         24         m.         85         10         5         0         00           Previous Inspection Notes :         Interview of the section Notes section Notes in Some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted.         EUMZ           10/13/2009 - None         Note of the section Notes increasing. Rusting appears unchanged.         ZZDW         NZDZ           10/13/2009 - None         Naterial acumulations increasing. Rusting appears unchanged.         ZZDW         SPGZ           11/17/2005 - All horizontal pieces have some material accumualtions. Some minor spot paint loss and minor rusting. No changes noted. No create the section Notes increasing. Rusting appears unchanged.         ZZDW           10/13/2003 - No change         KHDZ         KHDZ           10/19/2003 - No ne         UZLZ           11/19/2002 - None         UZLZ           12/09/1998 - None         UOTS           12/09/1995 - None         UOTS           11/19/2005 - None         UDLM           Inspection Notes:         UDLM           Inspection Notes:         VIDLM           1         3         131         m.         90         0         0         0           10/13/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.         EUMZ         NZDZ <t< td=""><td>Element 12</td><td>1 <sub>-</sub> P/Stl Thru Tru</td><td>es/Bot</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>	Element 12	1 <sub>-</sub> P/Stl Thru Tru	es/Bot								
Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing. Rusting appears unchanged.       Image: Control of the section Notes is increasing.       Image: Control of the section Notes is increasing. <td></td> <td></td> <td></td> <td>24</td> <td>~</td> <td></td> <td>05</td> <td>10</td> <td>F</td> <td>0</td> <td>0</td>				24	~		05	10	F	0	0
Previous Inspection Notes :       Image: Constraint loss with some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted. NZDZ       VZDZ         10/13/2009 - None       XZDW         09/25/2007 - Material acumulations increasing. Rusting appears unchanged.       ZZDW         11/17/2005 - All horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No       SPGZ         08/25/2003 - No change       UZLZ         11/19/2002 - None       UZLZ         11/19/2002 - None       UZLZ         11/19/2003 - No ne       UZLZ         12/09/1998 - None       UZLZ         12/09/1998 - None       UZLZ         12/09/1996 - None       UOTS         11/19/2002 - None       UOTS         11/19/2003 - No ne       UZLZ         12/09/1995 - None       UOTS         11/19/2014 - Pryst       UDLM         Inspection Notes:       UDLM         Inspection Notes:       UDLM         1       3       131       m.       90       10       0		1	3	24	m.						
10/31/2011 - Minor paint loss with some minor state 3 rust in some areas. Some exposed metal but no section loss seen. No changes noted.       EUMZ         10/13/2009 - None       NZDZ         10/13/2007 - Material accumulations increasing. Rusting appears unchanged.       ZZDW         11/17/2005 - All horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No       SPGZ         11/17/2005 - None       VZLZ         11/19/2002 - None       VZLZ         12/09/1998 - None       UZLZ         12/09/1998 - None       UDLM         12/09/1995 - None       UDLM         Inspection Notes:       VZLZ         1       3       131       m.       90       10       0       0       0         2/revious Inspection Notes :       ************************************							%	%	%	%	%
10/13/2009 - None       NZDZ         09/25/2007 - Material acumulations increasing. Rusting appears unchanged.       ZZDW         11/17/2005 - All horizontal pieces have some material accumualitons. Some minor spot paint loss and minior rusting. No changes noted. No       SPGZ         09/25/2007 - Material acumulations increasing. Rusting appears unchanged.       ZZDW         11/17/2005 - All horizontal pieces have some material accumualitons. Some minor spot paint loss and minior rusting. No changes noted. No       SPGZ         07/02/2003 - No change       WHDZ         11/19/2002 - None       UZLZ         08/25/2000 - None       UZLZ         08/15/2000 - None       UOTS         12/09/1998 - None       UOTS         01/01/1995 - None       UOTS         11/01/1995 - None       UOTS         11/01/1995 - None       UOTS         11/01/1995 - None       UDLM         Inspection Notes:       UDLM         1       3       131 m.       90       0       0       0         1       3       131 m.       90       0       0       0       0       0         2       1       3       131 m.       90       10       0       0       0       0       0       0       0       0       0	Previous Ins	spection Notes :									
2/2/2/2007 - Material accumulations increasing. Rusting appears unchanged.       2/2/2/2004         11/17/2005 - All horizontal pieces have some material accumulations. Some minor spot paint loss and minior rusting. No changes noted. No       SPGZ         10/17/2002 - None       KHDZ         10/17/2004 - None       UZLZ         11/19/2002 - None       UZLZ         12/09/1998 - None       UZLZ         12/09/1996 - None       UJDLM         Inspection Notes:       UJDLM         Inspection Notes:       UJDLM         11/19/2001 - Paint system mostly in good shape. Minor paint loss with some minor rusting.       YZDV         10/3/2001 - Paint system mostly in good shape. Minor paint loss with some minor rusting.       ZZDW	10/31/2011	- Minor paint loss	s with som	e minor state 3	rust in s	some areas	. Some exposed	metal but no sec	tion loss seen.	No changes note	d. EUMZ
11/17/2005 - All horizontal pieces have some material accumualtions. Some minor spot paint loss and minior rusting. No changes noted. No       SPGZ         02/25/2003 - No change       KHDZ         11/19/2002 - None       UZLZ         08/15/2000 - None       HADW         12/09/1998 - None       UOTS         08/01/1995 - None       UDLM         Inspection Notes:       UDLM         1       3       131       m.       90       10       0       0         2       Previous Inspection Notes :       %	10/13/2009	- None									NZDZ
broblems noted. (11.96 * 2 = 23.92)       KHDZ         D8/25/2003 - No change       KHDZ         D8/15/2000 - None       UZLZ         D8/15/2000 - None       HADW         12/09/1998 - None       TYYB         D8/01/1995 - None       UOTS         D1/01/1995 - None       UDLM         Inspection Notes:       UDLM         Element 126 - P/Stl Thru Truss/Top       0       0         1       3       131 m.       90       10       0       0         Previous Inspection Notes :       ************************************				-	• • •		-				
08/15/2000 - None       HADW         12/09/1998 - None       TYYB         08/01/1995 - None       UOTS         01/01/1995 - None       UDLM         Inspection Notes:       UDLM         Element 126 - P/Stl Thru Truss/Top       0         1       3       131       m.       90       10       0       0         Previous Inspection Notes :       %       %       %       %       %       %       %         10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.       EUMZ       NZDZ	problems no	oted. (11.96 * 2 =		some material	accumi	ualtions. So	ome minor spot p	aint loss and min	ior rusting. No c	hanges noted. N	
12/09/1998 - None       TYYB         08/01/1995 - None       UOTS         01/01/1995 - None       UDLM         Inspection Notes:       Inspection Notes:         Element 126 - P/Stl Thru Truss/Top       0         1       3       131       m.       90       10       0       0         Previous Inspection Notes :       %       <	11/19/2002	- None									UZLZ
08/01/1995 - None       UOTS UDLM         Inspection Notes:       UDLM         Element 126 - P/Stl Thru Truss/Top       0       0       0         1       3       131       m.       90       10       0       0       0         Previous Inspection Notes :       %	08/15/2000	- None									HADW
D1/01/1995 - None     UDLM       Inspection Notes:	12/09/1998	- None									TYYB
Inspection Notes: Element 126 - P/Stl Thru Truss/Top 1 3 131 m. 90 10 0 0 0 % % % % % Previous Inspection Notes : 10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting. 10/13/2009 - None EUMZ NZDZ	08/01/1995	- None									UOTS
Element 126 - P/Stl Thru Truss/Top          1       3       131       m.       90       10       0       0       0         1       3       131       m.       90       10       0       0       0         1       3       131       m.       90       10       0       0       0         Previous Inspection Notes :       ************************************	01/01/1995	- None									UDLM
1     3     131     m.     90     10     0     0     0       Previous Inspection Notes :       10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.       EUMZ NZDZ	Inspection	Notes:									
1     3     131     m.     90     10     0     0     0       Previous Inspection Notes :       10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.       EUMZ NZDZ											
Previous Inspection Notes : 10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting. 10/13/2009 - None EUMZ	Element 120	6 - P/Stl Thru Tru	ss/Top								
Previous Inspection Notes : 10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting. 10/13/2009 - None NZDZ		1	3	131	m.		90	10	0	0	0
10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.EUMZ10/13/2009 - NoneNZDZ							%	%	%	%	%
10/31/2011 - Paint system mostly in good shape. Minor paint loss with some minor rusting.EUMZ10/13/2009 - NoneNZDZ	Previous Ins	spection Notes :									
10/13/2009 - None NZDZ	10/31/2011	- Paint system m	ostly in go	od shape. Mino	or paint	loss with so	ome minor rusting	J.			EUMZ
Inspection Notes:			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
	Inspection	Notes:									



### INITIAL ASSESSMENT FORM FOR STRUCTURE :

Pct Stat 5

0 %

%

%

L32101000+01001 Continue

\*\*\*\*\*\*\*\*\* Span : Main-2 - -1 (cont.) \*\*\*\*\*\*\*\*\*

Element Des	scription									
Smart Flag	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	P
Element 152	2 - Paint Stl Floo	r Beam								
	1	3	10	m.		80	10	5	5	5
						%	%	%	%	>
Previous Ins	spection Notes :								·	
10/31/2011	- The painted ste	eel floor be	am have areas	of paint	loss and r	usting. The 2003	3 inspection repor	t shows that the	floor beams were	е
inspected at 10/13/2009		en the timb	per deck was re	moved	and minor s	section loss was	observed on top	of the top flanges	s.	
09/25/2007	- Panel points co	ontinue to s	show advancing	rusting	. No signifi	icant changes.				
11/17/2005	- Some minor pa	aint loss an	d rusting. No p	roblems	s noted. (4	.88 * 2 = 9.76)				
08/25/2003	- Isolated areas	of paint los	s, fleck rust and	d minor	section los	s in top of top fla	nge.			
11/19/2002	- None									
08/15/2000	- None									
12/09/1998	- None									
08/01/1995	- None									
01/01/1995	- None									
Inspection	Notes:									
Element 302	2 - Compressn J	oint Seal (	Compression Jo	oint Sea						
	1	3	5	m.		100	0	0		
						%	%	%	%	þ
Previous Ins	spection Notes :								L	
	- No problems, r	no changes	noted.							
10/13/2009		ie enangee								
	- No problems n	oted.								
	- See main span		otes. (4.88 * 1	= 4.88)						
	- New in August			,						
Inspection	-									
пореспол	Notes.									
Elomont 211	1 - Moveable Be	oring								
			0			05	- -	0		
	1	3	2	ea.		95		0		
						%	%	%	%	
Previous Ins	spection Notes :									
10/31/2011	<ul> <li>No changes no</li> </ul>	oted from th	ne 2009 QA ins	pection	report.					
10/13/2009	- None									
09/25/2007	- Some material	accumulat	ions about devi	ces. Mi	nor rusting	and paint loss.				
pics And the	<ul> <li>Pony truss strin hen the original - Non-functioning</li> </ul>	pony truss	pads under ea slotted plate m	ch end o ovable a	on West en and fixed pl	d and one under ate at each corne	each end of a pa er.	ir of tube floorbe	ams on East end	d, see
11/19/2002	- Non-functional									
08/15/2000	- Non functional									

12/09/1998 - Non-functional.


08/01/1995 - None

01/01/1995 - None


Inspection Notes:



			* * * * * *	* * * * *	* Span : <b>M</b>	ain-21 <b>(con</b> f	.) * * * * * * * *	* * *		
Element Des										
Smart Flag	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 313	- Fixed Bearing									
	1	3	2	ea.		0	100	0		
						%	%	%	%	%
Previous Ins	pection Notes :					I			I	
10/31/2011 -	No changes no	ted from th	ne 2009 QA ins	pection	report.					EUMZ
10/13/2009 -	None									NZDZ
09/25/2007 -	Some material	accumulat	ions about devi	ces with	n minor paint	loss and rusting	. No significant	changes noted.		ZZDW
11/17/2005 -	Fixed plate at n	nain pier w	vith minor spot p	paint los	s and minor	rusting. No prot	lems noted. Ma	in span 2 pony t	russ only.	SPGZ
08/25/2003 -	No change									KHDZ
11/19/2002 -	None									UZLZ
08/15/2000 -	None									HADW
12/09/1998 -	None									ТҮҮВ
08/01/1995 -	None									UOTS
01/01/1995 -	None									UDLM
Inspection N	Notes:									
Element 334	- Metal Rail Co	ated								
	1	3	24	m.		90	5	5	0	0
						%	%	%	%	%
Previous Ins	pection Notes :									
	Some coating l	oss with so	ome minor rusti	ng of ra	il					EUMZ
10/13/2009 -	-			ng or ru						NZDZ
	See main span	notes								ZZDW
	See main span		otes (11.96.*.)	2 = 23 9	12)					SPGZ
	New tubular ste					03				KHDZ
11/19/2002 -										UZLZ
	Collision dama	ae								HADW
12/09/1998 -		5-								ТҮҮВ
08/01/1995 -										UOTS
01/01/1995 -										UDLM
Inspection N	Notes:									
L										



General Inspection Notes	
10/31/2011 - None	EUMZ
10/13/2009 - None	NZDZ
09/25/2007 - None	ZZDW
11/17/2005 - Changed NBI item 41 to (B) because bridge is posted for more weight than what it is rated for. Nate.	SPGZ
08/25/2003 - None	KHDZ
11/19/2002 - Drift was removed and bearings were cleaned by Missoula County in Nov. 2002. The bearings are still non-functional. Deck plank repairs necessitated by mechanical wear were made on 3 different occasions during 2002 by the Missoula County. Missoula County is in the process of contracting design for repairs and redecking for this bridge for 2003. The ADTs continue to rise on this bridge yearly. This structure is Missoula County's current	UZLZ
08/15/2000 - Steve German, PE for MDOT Missoula and Barb Shubert, Missoula County performed a fracture critical inspection on 8/15/2000 on all of the tension members of the trusses. No evidence of cracking or section loss was detected. 12/09/1998 - MISCNTY1 inspection comments - Structure L32101000+01001 -	HADW TYYB
Date 12/9/98 - Previous comments > Sufficiency Rating Calculation Accepted by ops\$u5963 at 3/11/97 08:40:00 Sufficiency Rating Calculation Accepted by OPS\$U9004 at 2/19/97 12:31:36	
08/01/1995 - Sufficiency Rating Calculation Accepted by ops\$u5963 at 3/11/97 08:40:00 Sufficiency Rating Calculation Accepted by OPS\$U9004 at 2/19/97 12:31:36	UOTS
01/01/1995 - Sufficiency Rating Calculation Accepted by pontis at 3/24/98 09:42:23 Sufficiency Rating Calculation Accepted by pontis at 3/23/98 14:45:24 MISCNTY1 inspection comments - Structure L32101000+01001 - Date 10/7/97 12/01/1994 - Updated with tape 1995	UDLM NB95
08/01/1992 - Updated with tape 1994	NB94
06/01/1989 - Updated with tape 1992	NB92



# Resolution 79-128

EVOL 143 PAGE 982

# REGULATION OF PARKING, CONGREGATING, ETC. ON MACLAY BRIDGE.

Whereas, vehicles parked on the approaches to the Maclay Bridge over the Bitterroot River West of Missoula are creating a hazard and rendering dangerous passage over the bridge; and

Whereas, persons loitering on, diving or jumping from, and climbing or congregating on the bridge structure are creating a hazard and rendering dangerous passage over the bridge; and

Whereas, the Board of County Commissioners is authorized by Section 61-12-101 M.C.A. to adopt regulations governing parking on county roads; and

Whereas, Section 61-8-705 M.C.A. authorizes the removal of illegally parked vehicles; and

Whereas, Section 45-8-107 M.C.A. specifies that rendering dangerous for passage a public right-of-way constitutes a public nuisance.

NOW THEREFORE BE IT RESOLVED that parking on Maclay Bridge and on the road right-of-way leading to it for distance of 500 yards be and same is hereby prohibited.

BE IT FURTHER RESOLVED, that loitering on, fishing from, diving or jumping from and climbing or congregating on Maclay Bridge be and the same is hereby prohibited.

BE IT FURTHER RESOLVED that the County Surveyor place appropriate signs on Maclay Bridge and its approaches with said signs, in addition to prohibiting parking, stating that illegally parked vehicles will be towed.

BE IT FURTHER RESOLVED that Missoula County Sheriff is hereby requested to take such action as is required to assure compliance with the parking and pedestrian regulations on Maclay Bridge and its approaches.

DATED this 24th day of July, 1979.

Clerk & Recorder

in Valtenne Chair

OUT OF OFFICE Commissioner

received and filed

Commissioner

451019

#### RESOLUTION NO. 90-064

3 RIDDES

A RESOLUTION CREATING A RESIDENTIAL ON-STREET PARKING PERMIT REGULATION PROGRAM IN THE MACLAY BRIDGE AREA

WHEREAS, the Board of County Commissioners of Missoula County is authorized, pursuant to Section 7-14-2106 M.C.A., to establish parking regulations by resolution for the purpose of regulating the parking of motor vehicles in unincorporated towns and villages; and

WHEREAS, Section 61-12-101 M.C.A. provides that local authorities may regulate, within the reasonable exercise of police power, the standing or parking of vehicles on streets or highways under their jurisdiction; and

WHEREAS, the Board of County Commissioners has received a petition from residents living in the Maclay Bridge area requesting the establishment of a residential on-street parking permit regulation program; and

WHEREAS, the Board of County Commissioners of Missoula County, Montana, has determined after a Public Hearing on July 18, 1990, and public input that:

- The area proposed for the parking permit regulation program, as outlined in the attached Exhibit "A", is predominantly residential in character;
- The streets in the area near Maclay Bridge are regularly congested with vehicles parked by persons not residing in the area;
- 3. In order to better provide adequate motor vehicle parking for residents of the area, it is necessary to establish an area limiting the parking of vehicles along the public streets in the residential area to vehicles registered or controlled and exclusively used by persons residing in the residential area; and

WHEREAS, the Board of County Commissioners has deemed it a necessity to immediately address the problems of littering, noise and disruptive behavior through the adoption of a resolution creating a residential on-street parking permit regulation program in the Maclay Bridge area;

NOW, THEREFORE, BE IT RESOLVED that effective August 1, 1990, this Resolution shall be in full force and effect in Missoula County (7-25-123, M.C.A.).

### SECTION 1: LIMITATIONS ON PARKING.

- A. It shall be unlawful for any person to stop, stand or park a vehicle on any street included in the Maclay Bridge On-Street Parking Permit Regulation Program, as identified in Exhibit "A" of this resolution adopted by the Board of County Commissioners, during the months and hours set forth in this resolution; except in the following circumstances:
  - Those vehicles displaying a valid residential parking permit for the area.
  - An emergency vehicle, including but not limit to an ambulance, fire engine or other law enforcement vehicle.
  - 3. A clearly marked business vehicle which is under the control of a person providing a service to persons or

property located in the designated residential permit only parking area, including but not limited to a delivery vehicle.

- B. The months and hours during which the area is designated a residential permit only parking area shall be June 1st through September 30th during the hours of 3:00 p.m. to 6:00 a.m.
- C. Anyone violating this section shall be subject to a fine of not less than twenty dollars (\$20.00) and not more than forty dollars (\$40.00) per ticket. Each day an offense exists constitutes a separate offense. Imprisonment may not be a part of any penalty imposed for a violation of this part.

#### SECTION 2: RESIDENTIAL PARKING PERMIT APPLICATION PROCEDURE.

Applications for residential parking permits shall be submitted to the Missoula Parking Commission on a form prescribed by the Missoula Parking Commission and shall be accompanied by proof in a form satisfactory to the Missoula Parking Commission of the applicant's place of residence within the residential parking permit only area, as well as proof of registration or use and control of each vehicle for which a residential parking permit is sought. Each application shall be accompanied by the appropriate fee of seven dollars (\$7.00). No part of the parking permit fee shall be refundable. This fee is established at a level that covers the cost of administration and enforcement of the residential parking permit only regulations in the residential area.

### SECTION 3: RESIDENTIAL PARKING PERMIT FORM AND ISSUANCE.

- A. Upon approval by the Missoula Parking Commission of the application of any person residing in a residential parking permit only area, a residential parking permit shall be issued for each vehicle receiving approval. Approved residences may also purchase packets of fifteen (15) guest parking permits for a fee of five dollars (\$5.00).
- B. Each residential parking permit issued by the Missoula Parking Commission for a vehicle shall set forth the date of issuance and license number of the vehicles for which it is issued. Annual permits shall be required. A permit shall be valid for no longer than the permit year of issuance. The issuance of a residential parking permit does not serve as a guarantee that there will always be a parking space available for the permit holder on the public streets within the designated residential parking permit area.

# SECTION 4: DISPLAY OF RESIDENTIAL PARKING PERMITS REQUIRED.

Residential parking permits shall be displayed on a vehicle in the place and in the manner prescribed by the Missoula Parking Commission. It is unlawful to either fail to display or improperly display a residential parking permit, or to attempt to use a residential parking permit from another area in a designated residential area. Anyone violating this section shall be subject to a minimum fine of twenty dollars (\$20.00) and a maximum fine of forty dollars (\$40.00). Each day an offense exists constitutes a separate offense. Imprisonment may not be a part of any penalty imposed for a violation of this section.

#### SECTION 5: SEVERABILITY.

If any section, subsection, sentence, clause, phrase or work of this resolution is for any reason held to be invalid or

unconstitutional, such decision shall not affect the validity of the remaining portions of this resolution.

ann

DATED this 18th day of July , 1990.

BOARD OF COUNTY COMMISSIONERS

anettover Janet vens, Chairman 4 Man ara-Ù Barbara Evans, Commissioner

Thangk &

Ann Mary Dussault, Commissioner

APPROVED AS TO FORM AND CONTENT:


Umalle

ì

ATTEST:

Jern ? Clerk & Recorder

hai Deputy County Attorney



### RESOLUTION NO. 91-067

#### A RESOLUTION SUPERSEDING RESOLUTION NO. 90-064, A RESOLUTION CREATING A RESIDENTIAL ON-STREET PARKING PERMIT REGULATION PROGRAM IN THE MACLAY BRIDGE AREA, SIGNED JULY 18, 1990 (AMENDING SECTION 1, PARAGRAPH A)

WHEREAS, the Board of County Commissioners of Missoula County is authorized, pursuant to Section 7-14-2106 M.C.A., to establish parking regulations by resolution for the purpose of regulating the parking of motor vehicles in unincorporated towns and villages; and

WHEREAS, Section 61-12-101 M.C.A. provides that local authorities may regulate, within the reasonable exercise of police power, the standing or parking of vehicles on streets or highways under their jurisdiction; and

WHEREAS, the Board of County Commissioners has received a petition from residents living in the Maclay Bridge area requesting the establishment of a residential on-street parking permit regulation program; and

WHEREAS, the Board of County Commissioners of Missoula County, Montana, has determined after a Public Hearing on July 18, 1990, and public input that:

- 1. The area proposed for the parking permit regulation program, as outlined in the attached Exhibit "A", is predominantly residential in character;
- The streets in the area near Maclay Bridge are regularly congested with vehicles parked by persons not residing in the area;
- 3. In order to better provide adequate motor vehicle parking for residents of the area, it is necessary to establish an area limiting the parking of vehicles along the public streets in the residential area to vehicles registered or controlled and exclusively used by persons residing in the residential area; and

WHEREAS, the Board of County Commissioners has deemed it a necessity to immediately address the problems of littering, noise and disruptive behavior through the adoption of a resolution creating a residential on-street parking permit regulation program in the Maclay Bridge area;

NOW, THEREFORE, BE IT RESOLVED that effective immediately, this Resolution shall be in full force and effect in Missoula County (7-5-123, M.C.A.).

#### SECTION 1: LIMITATIONS ON PARKING.

- A. It shall be unlawful for any person, or for the registered owner of a vehicle to permit any person, to stop, stand or park a vehicle on any street included in the Maclay Bridge On-Street Parking Permit Regulation Program, as identified in Exhibit "A" of this resolution adopted by the Board of County Commissioners, during the months and hours set forth in this resolution except in the following circumstances:
  - 1. Those vehicles displaying a valid residential parking permit for the area.
  - 2. An emergency vehicle, including but not limited to an ambulance, fire engine or other law enforcement vehicle.

- 3. A clearly marked business vehicle which is under the control of a person providing a service to persons or property located in the designated residential permit only parking area, including but not limited to a delivery vehicle.
- B. The months and hours during which the area is designated a residential permit only parking area shall be June 1st through September 30th during the hours of 3:00 p.m. to 6:00 a.m.
- C. Anyone violating this section shall be subject to a fine of not less than twenty dollars (\$20.00) and not more than forty dollars (\$40.00) per ticket. Each day an offense exists constitutes a separate offense. Imprisonment may not be a part of any penalty imposed for a violation of this part.

### SECTION 2: RESIDENTIAL PARKING PERMIT APPLICATION PROCEDURE.

Applications for residential parking permits shall be submitted to the Missoula Parking Commission on a form prescribed by the Missoula Parking Commission and shall be accompanied by proof in a form satisfactory to the Missoula Parking Commission of the applicant's place of residence within the residential parking permit only area, as well as proof of registration or use and control of each vehicle for which a residential parking permit is sought. Each application shall be accompanied by the appropriate fee of seven dollars (\$7.00). No part of the parking permit fee shall be refundable. This fee is established at a level that covers the cost of administration and enforcement of the residential parking permit only regulations in the residential area.

#### SECTION 3: RESIDENTIAL PARKING PERMIT FORM AND ISSUANCE.

- A. Upon approval by the Missoula Parking Commission of the application of any person residing in a residential parking permit only area, a residential parking permit shall be issued for each vehicle receiving approval. Approved residences may also purchase packets of fifteen (15) guest parking permits for a fee of five dollars (\$5.00).
- B. Each residential parking permit issued by the Missoula Parking Commission for a vehicle shall set forth the date of issuance and license number of the vehicles for which it is issued. Annual permits shall be required. A permit shall be valid for no longer than the permit year of issuance. The issuance of a residential parking permit does not serve as a guarantee that there will always be a parking space available for the permit holder on the public streets within the designated residential parking permit area.

### SECTION 4: DISPLAY OF RESIDENTIAL PARKING PERMITS REQUIRED.

Residential parking permits shall be displayed on a vehicle in the place and in the manner prescribed by the Missoula Parking Commission. It is unlawful to either fail to display or improperly display a residential parking permit, or to attempt to use a residential parking permit from another area in a designated residential area. Anyone violating this section shall be subject to a minimum fine of twenty dollars (\$20.00) and a maximum fine of forty dollars (\$40.00). Each day an offense exists constitutes a separate offense. Imprisonment may not be a part of any penalty imposed for a violation of this section.

# SECTION 5: SEVERABILITY.

If any section, subsection, sentence, clause, phrase or work of this resolution is for any reason held to be invalid or unconstitutional, such decision shall not affect the validity of the remaining portions of this resolution.

DATED THIS 17th day of July, 1991.

BOARD OF COUNTY COMMISSIONERS

naul Ann Mary Dussfult, Chair A. Asia

Barbara Evans, Commissioner

net Commissioner Janet vens,

ATTEST:

APPROVED AS TO FORM AND CONTENT:

County Clerk & Recorder

Deputy County Attorney

Surveyor - Maclay Buildge File Copy

### **RESOLUTION NO.** 99-003

# REGULATING PARKING, CONGREGATING, ETC. ON MACLAY BRIDGE. AND AMENDING RESOLUTION 79-128.

WHEREAS, vehicles parked on the approaches to the Maclay Bridge over the Bitterroot River west of Missoula area are creating a hazard and rendering dangerous passage over the bridge; and

WHEREAS, persons standing on, diving or jumping from, and climbing or congregating on the bridge structure are creating a hazard and rendering dangerous passage over the bridge; and

WHEREAS, the Board of County Commissioners is authorized by Section 61-12-101, M.C.A., to adopt regulations governing parking on County roads; and

WHEREAS, Section 61-8-705, M.C.A., authorizes the removal of illegally parked vehicles; and

WHEREAS, Section 45-8-111, M.C.A., specifies that rendering dangerous for passage a public right-of-way constitutes a public nuisance.

NOW, THEREFORE, BE IT RESOLVED that parking on Maclay Bridge and on the road right-of-way leading to it for distance of 500 yards be and the same is hereby prohibited.

BE IT FURTHER RESOLVED, that standing on, fishing from, diving or jumping from and climbing or congregating on Maclay Bridge be and the same is hereby prohibited.

BE IT FURTHER RESOLVED that the County Surveyor place appropriate signs on Maclay Bridge and its approaches with said signs, in addition to prohibiting parking, stating that illegally parked vehicles will be towed.

BE IT FURTHER RESOLVED that Missoula County Sheriff is hereby requested to take such action as is required to assure compliance with the parking and pedestrian regulations on Maclay Bridge and its approaches.

DATED this <sup>1</sup>/<sub>2</sub> day of January, 1999.

BOARD OF COUNTY COMMISSIONERS MISSOULA COUNTY

ATTEST:

Clerk and Recorde


Michael Kennedy, Chair

Missoula County Commissioner

**Bill** Carey Missouria County Commissioner

Barbara Evans Missoula County Commissioners

APPROVED AS TO FORM



# MEMORANDUM

DATE: August 31, 1998

TO: Acting Co. Attorney Mike Sehestadt

FROM: Capt. Don Morman

RE: MaClay Bridge

cc: Sheriff Chase, Undersheriff Weatherman

Attached you will find Resolution 79-128 that regulates Parking, Congregating, etc., on MaClay Bridge. Attached also is a Aug. 8, 1991 Memorandum from Karen Townsend. This year during discussions Karen requested that we write citations for Public Nuisance. I put out this memorandum. The only problem is that all Public Nuisance's should be written into Justice Court for Adults and Juvenile Courts for Juveniles. The obvious problem is that Youth Court can not levy fines(most violators are juveniles) so we are back to the old problem. Karen also requested that other remedies for Jumping, divng, climbing etc. Most of these again would be youth court citations.

I propose **the** you revising this resolution. Change the section for public nuisance to 45-8-111. Omit Loitering.

With these changes I would for 1999 again write all violators(adult and Juv.) into Justice Court. The bond presently is \$50.

Please be advised this request should have no effect on 91-067 which is the residential on-street parking permit regulations.

MIKE COULD WE VISIT THIS BEFORE SPRING WE ARE PUHING TO GETHER A NEW BOND Schedule

Mono

### RESOLUTION NO. 2011- 073

### REGULATING PARKING, CONGREGATING, ETC. ON MACLAY BRIDGE AND AMENDING RESOLUTION NO. 91-067

WHEREAS, Resolution No. 91-067 and were established to prohibit certain activities on Maclay Bridge and regulate parking in the general vicinity; and

WHEREAS, the Board of County Commissioners is authorized by MCA 61-12-101 to adopt regulations governing parking on County Roads; and

WHEREAS, MCA 61-8-705 authorizes the removal of illegally parked vehicles; and

WHEREAS, MCA 45-8-111(c) defines public nuisance as a condition that renders dangerous for passage any public highway or right of way or waters used by the public; and

WHEREAS, at the request of property owners to modify the parking district boundary;

NOW THEREFORE BE IT RESOLVED, that the parking district boundary be amended as represented in attached exhibit "A"; and

BE IT FURTHER RESOLVED, that all provisions of Resolution No. 91-067 remain in full force and effect.

th day of June, 2011 Dated this

BOARD OF COUNTY COMMISSIONERS


Jean Curtiss, Chair


Michele Landquist, Member

Bill Cárey, Member

ATTEST:

Clerk & Recorder





# Missoula County Public Works

Road:	River Pines Road
Location:	South of Maclay Bridge
Description 3:	

oad: ocation: escription 3:	River Pin South of	Maclay Bridge										D	ate:		10/3/20 Wednesd
	Begin	South		North		Combine		ur Volume	Begin	South		North		Combined	
	12:00 AM	South 0	1	0	1	0	2		12:00 PM	23	66	15	55	38	121
	12:15 AM	1		1		2	2		12:15 PM	18	00	9	55	27	121
	12:30 AM	0		0		0			12:30 PM	7		16		23	
	12:45 AM	Ő		Ő		Ő			12:45 PM	18		15		33	
	1:00 AM	0	1	0	0	0	1		1:00 PM	14	57	10	32	24	89
	1:15 AM	1	·	Ő	0	1	·		1:15 PM	10	07	5	02	15	0,
	1:30 AM	0		0		0			1:30 PM	15		11		26	
	1:45 AM	Ő		Ő		Ő			1:45 PM	18		6		24	
	2:00 AM	0	2	2	2	2	4		2:00 PM	9	58	13	64	22	122
	2:15 AM	2	-	0	-	2	•		2:15 PM	13	00	8	0.	21	
	2:30 AM	0		Ő		0			2:30 PM	18		22		40	
	2:45 AM	Ő		Ő		Ő			2:45 PM	18		21		39	
	3:00 AM	1	3	0	1	1	4		3:00 PM	22	115	12	52	34	89         122         167         191         238         181         120         72         40         24
	3:15 AM	1	0	1	•	2	•		3:15 PM	24		12	02	36	
	3:30 AM	1		0 0		1			3:30 PM	34		11		45	
	3:45 AM	0		0		0			3:45 PM	35		17		52	
	4:00 AM	0	1	0	2	0	3		4:00 PM	27	127	15	64	42	191
	4:15 AM	1		2	_	3	-		4:15 PM	35		16	-	51	
	4:30 AM	0		0		0			4:30 PM	36		16		52	
	4:45 AM	0		0		0			4:45 PM	29		17		46	
	5:00 AM	0	5	2	11	2	16		5:00 PM	33	143	27	95	60	238
	5:15 AM	0		2		2			5:15 PM	33		23		56	
	5:30 AM	2		3		5			5:30 PM	36		19		55	
	5:45 AM	3		4		7			5:45 PM	41		26		67	
	6:00 AM	0	9	2	31	2	40		6:00 PM	24	127	12	54	36	181
	6:15 AM	4		6		10			6:15 PM	34		14		48	
	6:30 AM	3		13		16			6:30 PM	37		9		46	
	6:45 AM	2		10		12			6:45 PM	32		19		51	
	7:00 AM	3	19	15	151	18	170		7:00 PM	24	73	12	47	36	120
	7:15 AM	4		41		45			7:15 PM	20		10		30	
	7:30 AM	2		45		47			7:30 PM	14		17		31	
	7:45 AM	10		50		60			7:45 PM	15		8		23	
	8:00 AM	11	50	36	91	47	141		8:00 PM	15	51	3	21	18	72
	8:15 AM	18		14		32			8:15 PM	20		7		27	
	8:30 AM	9		22		31			8:30 PM	6		6		12	
	8:45 AM	12		19		31			8:45 PM	10		5		15	
	9:00 AM	5	31	12	66	17	97		9:00 PM	8	27	4	13	12	40
	9:15 AM	8		26		34			9:15 PM	5		1		6	
	9:30 AM	9		15		24			9:30 PM	8		2		10	
	9:45 AM	9		13		22			9:45 PM	6		6		12	
	10:00 AM	11	47	16	58	27	105		10:00 PM	3	15	3	9	6	24
	10:15 AM	14		11		25			10:15 PM	6		2		8	
	10:30 AM	15		19		34			10:30 PM	4		1		5	
	10:45 AM	7		12		19			10:45 PM	2		3		5	
	11:00 AM	12	48	16	64	28	112		11:00 PM	0	8	1	3	1	11
	11:15 AM	9		16		25			11:15 PM	0		2		2	
	11:30 AM	9		20		29			11:30 PM	7		0		7	
	11:45 AM	18		12		30			11:45 PM	1		0		1	
		24 Hour Vo	lume	<u>South</u> 1084 (5	52.3%)	<u>Nortl</u> 987	<u>h</u> (47.7%)	<u>Combined</u> 2071							
					<u> 12:00 AM - 12:00 PM</u>						<u>12:</u>	00 PM - 12:0	<u>MA 00</u>		
		South		North		Combine	<u>a</u>			South		North		Combined	
	Count	217		478		695				867		509		1376	
-		31.2 %		68.8 %						63.0 %		37.0 %		F 66 5	
F	Peak Hour	8:00 AM		7:15 AM		7:15 AN	1			5:00 PM		5:00 PM		5:00 PM	
	Volume Factor	50		172 0.86		199				143 0.87		95 0.88		238 0.89	
		0.69		0 04		0.83									