
Project Crack Map NH-STPU-CM-MT-STPE 15-4(108)191

South Helena Interchange: High-Performance Concrete Deck

UNDERSIDE- EAST HALF: Deck condition as of August 2007 - November 2009



Crack August 2007 - Crack November 2009 - Cr

Note: All cracks hairline

SOUTH

**Note:** Not to scale. All values approximate. Map details a visual representation of the current underside deck condition.